



# URBAN DESIGN ADVANCEMENT BASIS OF DESIGN REPORT

November 2012

SOUTH BAY BUS RAPID TRANSIT  
EAST PALOMAR STREET GUIDEWAY (OLEANDER AVENUE  
TO OLYMPIC PARKWAY)

Prepared For:

San Diego Association of Governments  
401 B Street, Suite 800  
San Diego, CA 92101


Prepared By:

Kimley-Horn and Associates, Inc.  
401 B Street, Suite 600  
San Diego, California 92101

095721401  
November 2012  
Copyright © 2012 Kimley-Horn and Associates, Inc.



Kimley-Horn  
and Associates, Inc.



## TABLE OF CONTENTS

1	Executive Summary .....	3
1.1	Project Overview and Objective .....	3
1.2	Urban Design Advancement.....	4
2	Urban Design.....	7
2.1	Guideway Stations .....	7
2.2	Platform Components.....	7
2.3	Corridor Local Bus Stops .....	10
3	Tree Inventory .....	11
3.1	Arborist Report .....	11
4	Landscaping and Irrigation.....	12
4.1	Existing Conditions.....	12
4.2	Proposed Corridor Landscape and Irrigation.....	13
4.3	Proposed Station Landscape and Irrigation .....	13
4.4	Future Maintenance Agreements .....	14
5	Station Communications and Electrical Design .....	15
5.1	Electrical Power .....	15
5.2	Communications .....	15
6	Station Lighting Study .....	16
6.1	Station Lighting .....	16
6.2	Luminaires .....	16
6.3	Lighting Photometric Calculation Study .....	16
7	Appendix .....	18
7.1	Urban Design Exhibits .....	18
7.2	South Bay BRT Arborist Report.....	19
7.3	Landscape and Irrigation Exhibits .....	20
7.4	Station Communications and Electrical Exhibits.....	21
7.5	Station Lighting Exhibits.....	22

# 1 EXECUTIVE SUMMARY

## 1.1 Project Overview and Objective

The San Diego Association of Governments (SANDAG), in coordination with the Metropolitan Transit System (MTS), City of Chula Vista, and City of San Diego, will implement the South Bay Bus Rapid Transit (BRT) project providing transit service between the proposed Intermodal Transportation Center (ITC) at the Otay Mesa Port of Entry, Otay Ranch Communities, the City of Chula Vista, and downtown San Diego. From the ITC, the BRT will travel north via SR-905 and SR-125 to Otay Ranch Communities, proceed east through Chula Vista along East Palomar Street, then travel north on I-805 and SR-94 until the route terminates in downtown San Diego [Figure 1].



**Figure 1. South Bay Bus Rapid Transit Route**

BRT is a transit service intended to emulate rail service by providing faster travel times, higher passenger capacity, enhanced stations, and modern vehicles without the need for fixed rail and specialized structures and systems. The SBBRT will operate in a combination of mixed-flow lanes (BRT buses operating in lanes with general auto traffic) and exclusive transit-only guideways.

The purpose of this project is to complete the planning and design for the East Palomar Street guideway between Oleander Avenue and Olympic Parkway [Figure 1 – “Study Area”]. Within this four mile segment of East Palomar Street there are two distinct roadway cross sections. The eastern segment, between Heritage Road and Olympic Parkway, currently has a 29- to 51-foot landscaped median which was constructed with future transit in mind. The proposed BRT guideway can be achieved in this segment with limited roadway reconstruction. The western segment between

Oleander Avenue and Heritage Road will require roadway widening in order to accommodate the proposed BRT guideway median. The existing median in the western section varies between 4 feet and 16 feet.

## 1.2 Urban Design Advancement

The objective of this report is to document the Urban Design Advancement decision making process for the stations along the East Palomar Street corridor as well as those elements relating to the corridor itself. This decision making process included the following interagency coordination meetings:

- Five SANDAG and MTS staff meetings which focused on station design and operations,
- Two SANDAG and MTS staff meetings which focused on station security, communications and electrical design,
- Two SANDAG, MTS, and CALTRANS staff meetings which focused on data communication infrastructure,
- One SANDAG and South Bay Expressway (SBX) staff meeting which focused on data communication infrastructure,
- One City of Chula Vista staff meeting which focused on data communication infrastructure,
- Two MTS staff meetings which focused on station landscaping, irrigation and maintenance,
- Five City of Chula Vista Staff meetings which focused on corridor landscaping and irrigation,
- One formal SANDAG Senior Management presentation, and
- One formal MTS Senior Management presentation.

KHA reviewed and analyzed the urban design components within the design framework of the proposed roadway, traffic signals, stormwater management, and utility infrastructure improvements. These components respond to both the functional aspects of the corridor (i.e. Guideway Bus Station operations, fare collection, safety) and the aesthetic character of the corridor (i.e. the architectural and natural community character). With the guideway stations serving as the focal point, these components fell into three distinct design element categories:

1. Streetscape elements (station design, signage, pedestrian paving, site furnishings, lighting)
  - Conceptual design for the four Chula Vista BRT stations within the corridor study area [Figure 2 and 3]
2. Landscape elements (plant material – both existing and proposed),
  - Landscape within the guideway stations intended to enhance the parkways, medians, and miscellaneous slope areas from Oleander Avenue to Olympic Parkway.
3. Irrigations elements (irrigation systems – both existing and proposed).
  - New irrigation systems and existing irrigation systems incorporated into the design to provide adequate water supply to the proposed and existing landscape.

During the process it was determined by MTS that the stations would not operate initially as a paid fare zone, which places the responsibility of fare collection on the bus operators. However, MTS directed that all stations be designed to function as a paid fare zone at a future time to be determined. As a part of this, a number of platform elements were space planned but will not be included in the construction the stations. They are as follows:

Elements Included:

- Platform Shelter
- Station Signage
- Landscaping/irrigation
- Bicycle storage
- VMS signage
- Benches
- Trash Receptacles
- Lighting
- Fencing
- Special Paving
- Pay Phones (by Others)
- Security Cameras (by MTS)
- Public Address System (by MTS)

Elements planned for the future:

- Fare validation
- Ticket Vending Machines (TVM)n Devices (PCID)
- Vending Machines



**Figure 2. Typical Platform Bicycle Storage and Utility/Maintenance Area**



**Figure 3. Typical Platform Passenger Loading Area**

## 2 URBAN DESIGN

---

### 2.1 Guideway Stations

As part of the design advancement process, typical BRT station designs were developed to meet the aesthetic, functional, and operational requirements of a basic station [Appendix 7.1, Exhibit UD.02]. Each station within the Study Area is comprised of two platforms – a northbound platform and a southbound platform. Each platform was then divided into four separate functional zones, each with its own design elements:

**1. Passenger entrance and orientation zone:**

This zone is composed of entry landscaping, station identification signage, pedestrian entry/crosswalk landings, lighting, ramp access to platform and bicycle storage facilities, and station variable message signs and fare validation devices (PCID).

**2. Passenger waiting and comfort facilities zone:**

This zone is composed of shelters, palm trees, ticket vending machines, fare validation devices (PCID), security cameras, vending machines, trash receptacles, seating, informational signage, pay phones, and lighting.

**3. Passenger mobility and orientation zone:**

This zone is composed of interior station crosswalk access between platforms, lighting, ramp access to platforms, and station variable message signs and PCID devices.

**4. Station utility and maintenance zone:**

This zone is composed of station utility cabinets for electrical and data communications point of connections, lighting, and MTS maintenance personnel/vehicle access. This zone was located at the exit end of one of the platforms to limit passenger access and to provide improved visibility of the utility cabinets and of the maintenance crews by bus drivers exiting the station.

This basic layout was applied to each of the four station locations within the study area as a set of design parameters to inform the final layout design [Appendix 7.1, exhibits UD.05-UD.08]. In three of the four stations the “basic” configuration layout was followed with minor modifications to pedestrian access, bicycle storage, utility cabinet locations and maintenance access to meet site specific design requirements. The fourth station, Heritage Station, was modified as a “far side” configuration where the platforms were offset with the guideway crosswalk separating the platforms. This offset layout is typical of a standard bus stop that passes through an intersection to stop on the “far” side of the intersection. This allowed passengers to cross behind parked buses, much like an intersection crosswalk creating a safer environment for the pedestrian while not impeding bus traffic.

The platform height was set at 10” above the guideway paving for “near level” boarding by passengers. A rubberized wheel bumper will be applied to the curb face to aid drivers in the approach to the platform. No special door loading areas will be designated in order to provide flexibility for future bus operations.

### 2.2 Platform Components

▪ **Platform Shelter:**

- The preferred alternative Platform Shelter shall be Option C – a hybrid concept using roofing material similar to the Downtown/I-15 BRT shelter design in a cantilevered roof/column

configuration similar to the Blue Line LRT Shelter [Appendix 7.1, Exhibits UD.18-UD.20]. Column bases will be a stone veneer with precast concrete caps to accent the stone veneer and match the local architectural character. An integrated lean rail will be included where applicable. Option C was selected because the cantilevered style provided for a more open platform for pedestrians. In addition, Option C utilized the same roof components as the Downtown, I-15, and Super Loop BRT shelters. This allows MTS to maintain a smaller stock of customized roof panels, thereby, reducing long term maintenance costs.

- BRT pylons like those to be used in the Downtown San Diego corridor will not be utilized at the Palomar Street stations.

- **Paving:**

The preferred alternative platform pavers consist of the following conditions [Appendix 7.1, Exhibit UD.15]:

- Platform access ramps and landings are currently proposed to be a “buff” colored broom-finished concrete with tactile dome paver edging (color to be determined) as required by ADA regulations.
- Platform areas will be concrete unit pavers on a concrete base with tactile dome paver edging (color to be determined) as required by ADA regulations. Basis of design pavers shall be 8”x8” “cream/brown” colored pavers by Angelus Paving or approved equal.
- Shelter areas will consist of concrete unit pavers on a concrete base with tactile dome paver edging as required by ADA regulations. Basis of design pavers shall be 8”x8” “charcoal” colored pavers for borders and fields, 4”x8” “Red/Brown/Charcoal” colored paver bands, and 4”x8” “cream/brown” colored pavers for fields. Basis of design pavers will be colored pavers by Angelus Paving or approved equal.

Due to current MTS maintenance operations and cleaning procedures, pavers are not to be sealed.

- **Platform Fencing:**

Platform fencing will match to the typical 48” high ornamental fence utilized by MTS throughout their system. Fence will be painted black. The proposed fencing will provide an enclosed station area for passenger safety. An additional fence will connect to the platform fencing and run along the guideway travel lane side of the utility cabinets to not allow a person to hide between the cabinets and dart out into bus traffic as the bus exits the station.

- **Station Signage:**

- Platform signage will adhere to the current MTS *San Diego Trolley Station Sign Program Design Guidelines Manual*.
  - A Type 1 Station ID sign will be located in the parkway areas along the sidewalks at the crosswalks to the station.
  - A Type 2 Station ID sign will be located on each crosswalk entry into the station/guideway.
  - One Type 45 Kiosk sign will be located on each platform.



- One Type 30 ADA Platform sign at each shelter/bus loading zone (two per platform).
- **Site Furnishings - Amenities:**
  - Bench will be Steelsites RB-28 (4 seat, Silver) by Victor Stanley to match other benches in the MTS system. One bench per shelter.
  - Trash Receptacles will be Ironsites SD-42 (Black) by Victor Stanley to match other trash receptacles in the MTS system. Two trash receptacles will be provided per platform.
  - Bike Lockers will be eLOCKER by Bike Link to match other bike lockers in the MTS system. Three lockers will be provided per station. Electrical power and data communications service will be provided to each locker.
  - Vending machines: a plumbed pad site will be provided for refreshment vending machines to be located by MTS at a later date. One vending machine location will be provided per platform.
  - Telephone: a plumbed pad site will be provided for a pay phone to be located by MTS at a later date. One pay phone location will be provided per platform.
  - Newspaper vending racks: no newspaper vending racks will be provided at the proposed stations.
  - Advertising Space: no advertising space will be provided at the proposed stations.
- **Site Furnishings - Operations:**
  - Variable message signs (VMS) shall be DS 128 x 40 x 05 (7.62 MM Pitch) by DATA Display to match other variable message signs in the MTS Bus system. Two per platform.
  - Utility cabinets shall be one 3 Bay MTS Standard Communications Cabinet and one CALTRANS Type III-C (Modified) Service Equipment Enclosure per station. Station irrigation controllers shall be located in association with these two primary utility cabinets.

Fare collection services will be provided on the buses during boarding by bus drivers initially. MTS, however, wants to preserve the option of “paid fare zones” in the future. The proposed stations will have the required utility infrastructure installed with this project to allow for future “paid fare zone” operations. Conduit will be run to utility pull boxes positioned at designated locations on the platform to allow MTS to install the following:

  - Ticket vending machine: a plumbed pad site will be provided for ticket vending machines to be located by MTS at a later date. One per platform located under a platform shelter.
  - Fare Validators (PCID): a plumbed pad site will be provided for PCID readers to be located by MTS at a later date. Three per platform.
- **Security Camera – Locations:**
  - Each platform will have four Avigilon Security cameras (to be provided/installed by MTS) to provide the required 100% camera coverage. One or two of the cameras on each platform will have pan-tilt-zoom (PTZ) capabilities (to be determined by MTS at a later date). One camera will be mounted on top of each VMS sign and cover the end of the platforms while

- one camera will be mounted on each of the two center platform light poles and cover the center of the platform.
- In addition, all shelter columns and light poles will have the conduit provided to allow future flexibility for mounting additional cameras or adjusting camera coverage.
  - Camera coverage at the park and ride facility at the Otay Ranch Town Center will be coordinated by the City of Chula Vista with MTS during final design.
  - All camera heights to be 13' above the platform finish grade.

### **2.3 Corridor Local Bus Stops**

All existing local bus stops to remain in service and that are affected by new construction shall be replaced per MTS standards for local bus stops. All bus turnouts will be removed in the Oleander Avenue to Heritage Road segment of the corridor due to R.O.W. constraints.

## 3 TREE INVENTORY

---

### 3.1 Arborist Report

Kimley-Horn and Associates worked with the project's certified arborist, Rappoport Development Consulting Services LLC (RDCS), to complete an inventory and assessment of the street trees within the project limits. This inventory/assessment will supplement the tree survey which located all trees within the existing rights-of-way (ROW) and those within the first eight feet outside of the existing ROW. The inventory was performed in conjunction with the project supplemental field survey. All trees within the project limits were field labeled with a metal tree tag assigning an inventory number to the physical location. Each tree was then assessed for the following:

- Trunk diameter at breast height (DBH)
- Palm tree brown trunk height (BTH)
- Tree condition
- Planting location
- Specific health issues
- Maintenance needs
- Feasibility of preservation of existing palms
- Feasibility of relocating existing palms within the corridor

In addition to this assessment the arborist provided recommendations on improving the health of the existing trees as well as recommendations for the use of other tree species appropriate to the corridor aesthetic character and planting environment. This information will be utilized to guide the final landscape design parameters.

Within the project limits along the Palomar Street corridor there exists 1,553 deciduous/evergreen trees and palms. The most dominant tree species are the *Pyrus calleryana* – Bradford Pear (918 trees) and the *Washingtonia robusta* – Mexican Fan Palm (453 palms). These two tree species represent approximately 88% of the trees within the project corridor. Approximately 88% of the overall 1,553 trees within the corridor are in good condition. The remaining 12% vary from fair to poor condition or are dead. See Appendix 7.2 for the detailed information contained in the arborist report.

In addition to this inventory and assessment the project arborist will work with the design team during the final design phase to provide design support for tree preservation measures and palm tree relocation procedures where they may be necessary due to new guideway construction.

## 4 LANDSCAPING AND IRRIGATION

---

### 4.1 Existing Conditions

As part of the preliminary design advancement and in coordination with City of Chula Vista staff, the existing as-built conditions and maintenance district maps were reviewed for the corridor. It was determined that within the project area four City landscape and irrigation maintenance districts currently exist [Appendix 7.3]:

- D98: From Oleander to Hedencamp Elementary School
- D99: From Hedencamp Elementary School to Heritage Road
- D97: From Heritage Road to Santa Flora Road
- D97(2): From Santa Flora Road to Olympic Parkway

Within these maintenance districts the City assesses the residents a fee for the maintenance of the existing landscaping and irrigation systems. As part of the Final Design, the City staff will evaluate the proposed design against the current levels of plant material and maintenance costs. The goal being to have a “net neutral” final design to ensure that the residents do not have an increase in maintenance fees.

The existing landscaping and irrigation along the Study Area from Oleander Avenue to Olympic Parkway will be impacted in a variety of ways by the proposed South Bay BRT bus guideway, station construction, and roadway improvements:

- From Oleander Avenue to Heritage Road:
  - This segment will be the most impacted and will require the removal of landscape material within the existing rights-of-way (ROW). Final impacts to be determined during Final Design.
  - In addition, several steep slope conditions exist along the back of sidewalks outside of the ROW and will be impacted due to grading operations. Each grading conflict will be evaluated on a case-by-case basis with input from the project arborist and landscape architect to minimize impacts to the existing trees. In conjunction with the possible use of short retaining walls to minimize grading impacts, the arborist will make recommendations for tree preservation measures to be included in the final design package.
- From Heritage Road to Olympic Parkway:
  - Within this segment of the project, existing landscape impacts to the existing ROW will be limited to the existing median conversion to a bus guideway. These impacts will result in the removal of all existing pear trees due to grading and paving impacts to the critical root zones as well as tree canopy conflicts with vehicles within the guideway. However, due to the natural habitat and height of the Mexican Fan palm canopy, the existing palm trees will be preserved either in place or relocated within the guideway.

In addition to the impacts on the existing plants within the corridor, the irrigation system along the corridor will be impacted. The following are possible conditions and resolutions for the irrigation systems within the corridor:

- Condition 1: Complete removal of irrigation system components (sprinkler heads, piping, valves, controllers, backflow preventers, wiring, etc.). This condition primarily occurs in the existing median and parkway areas within the corridor.
- Condition 2: Partial removal of irrigation zone components (sprinkler heads, piping, valves, wiring, etc.). This condition may exist in places where control valves and zone connections exist in the existing parkway and the existing irrigation zones extend beyond the back of sidewalk into landscaped areas to remain. In this case, impacts due to the reconstruction of the parkway will require temporary irrigation measures to be implemented to maintain irrigation coverage to the remaining plant material until the final system can be brought back online.
- Condition 3: Improvements to existing irrigation components to remain for improved water conservation and/or efficiency of the system. These improvements will be considered on a case by case basis as part of the Final Design process.

## 4.2 Proposed Corridor Landscape and Irrigation

The proposed plant material for this project will be coordinated with the City of Chula Vista landscape architectural staff to meet the City water conservation ordinances and requirements of the existing maintenance districts. The final street tree selection will be evaluated to maintain the current character of the street corridor. The replacement of the existing parkway turf grass from Oleander Avenue to Heritage Road with drought tolerant groundcovers will also be evaluated with input from the City staff in conjunction with stormwater management plant material to be utilized in the parkway areas.

The existing irrigation system within the corridor is a reclaimed water line. As part of the approval process, the proposed system will be approved by the Otay Water District and by the Department of Environmental Health. In addition to the approval of the plans, these same agencies will be required to inspect and approve the installation of the systems prior to their use for irrigation. Until that approval has been received the contractor will be required to maintain the plant material within the zones affected or new zones.

## 4.3 Proposed Station Landscape and Irrigation

The four proposed stations will serve as urbanized transit nodes along the landscaped corridor. Comprised mostly of hardscape materials associated with the operations of the platform and guideway, the stations will have minimal landscaping in order to maximize safety and operations while maintaining the character of the corridor. The platform landscaping will consist of the relocation into a tree grate planter of existing Mexican Fan palms displaced by other project related construction. At the crosswalks, the platform landings will be recessed five feet off the travel ways in order to improve visibility of the pedestrians to the approaching automobiles. In these areas, beds of low growing daylilies will accent these crossings while at the same time maintaining the current character of the landscape in this section of the corridor. These palms and daylilies represent the only landscape plant material within the fenced platform area and will be on a separate metered irrigations system from the guideway medians and corridor parkways.

#### **4.4 Future Maintenance Agreements**

In addition to the approval of the “net neutral” construction impact calculations to the maintenance districts, the City, SANDAG, and MTS will be required to define a maintenance agreement for the corridor to include areas of responsibility and levels of service. These agreements will be developed during the Final Design process.

## 5 STATION COMMUNICATIONS AND ELECTRICAL DESIGN

---

### 5.1 Electrical Power

Electrical power at each station will consist of a single 200 Amp, 240 V, single phase electrical service from the Utility Company. SDG&E power will enter a meter pedestal located at one end of the station platform. Each pedestal will have internal breakers and photo cell to serve the platform devices and lighting. The electrical power will consist of tin-plated copper panel boards in NEMA 3R construction and copper conductors. At each end of the station platform an in grade SDG&E 3314 electrical box will be provided to allow conduit connection and pull locations for conductors. Each device will be provided with a minimum of one 2" conduit for power. All equipment proposed and future will be provided with conduit stub ups. Proposed and future equipment on the platform includes the following:

- Platform and Shelter Lighting
- Bike Lockers
- Variable Message Signs (VMS)
- Fare Validation (PCID)
- Ticket Vending Machines
- Vending Machines for food/drinks
- Pay Phone
- CCTV Cameras
- Public Address System

### 5.2 Communications

Communication systems at each station will consist of 3-bay communication cabinet tied into the communication backbone through the South Bay BRT project. The backbone consists of three 4" communication conduits along the guideway. The conduits will enter the communication cabinet and tie the fiber optic lines into existing SANDAG facilities (to be determined). The communication cabinet located at the end of the platform will distribute conduit and cable to all the required equipment. At each end of the station platform an in-grade SDG&E 3314 communication box will be provided to allow conduit connection and pull locations for cable. Each proposed and future device will be provided with a minimum of one 2" conduit for communications. All equipment proposed and future will be provided with conduit stub ups. Proposed and future equipment on the platform includes the following:

- Platform and Shelter Lighting
- Bike Lockers
- Variable Message Signs
- Fare Validation (PCID)
- Ticket Vending Machines
- Vending Machines for food/drinks
- Pay Phone
- CCTV Cameras
- Public Address System

## 6 STATION LIGHTING STUDY

---

### 6.1 Station Lighting

The station lighting consists of two different types of light fixtures: pole mounted light fixtures and canopy mounted light fixtures. The pole mounted fixtures are 150 watt metal halide fixtures mounted on 15' poles located throughout the platform for even light distribution to follow MTS and SANDAG standards for pole mounted fixtures. The shelter canopy mounted light fixtures are Light Emitting Diode (LED) fixtures, and shall be mounted to the shelter canopy for additional lighting under the station shelters to supplement the pole mounted fixtures. The fixtures shall be vandal resistant and not be spaced further than 60' per SANDAG requirements.

### 6.2 Luminaires

- **Pole Fixture:**

Metal halide shall be Gardco luminaires manufactured by Phillips Lighting or an approved equal pending final I-15 BRT fixture installation. Each luminaire shall consist of 150 watt metal halide with a 19" box square head, 240V, 4000K on a 15' square pole. Luminaires shall be mounted as shown in the plans and in accordance with the manufacturer's recommendations. Each pole shall be provided with 2" conduit for communications and 2" conduit for power to allow for security cameras, general use receptacles, and future equipment.

- **Shelter Canopy:**

LED strips shall be Lumencove luminaires manufactured by Lumenpulse, or approved equal. Each luminaire shall consist of white LEDs, Regular Output (RO), 24" long, 120V, and 4000K with a frosted lens. Luminaire shall be mounted as shown in the plans in accordance with the manufacturer's recommendations.

Lighting levels and photometric analysis are referenced in section 6.3.

### 6.3 Lighting Photometric Calculation Study

A photometric analysis was performed on the station's typical layout based on the fixtures identified in Section 6.2. The following analysis was done to determine the minimal and average lighting levels as required per Illuminating Engineer's Society (IES) and SANDAG standards.

- **Platform lighting levels:**

Per IES and SANDAG standards, an average of 5 foot-candles shall be provided on the platform. The photometric analysis conducted for the platform indicates an average of 6 foot-candles.

- **Guideway lighting levels:**

Per IES and SANDAG standards, an average of 2 foot-candles shall be provided on the guideway within the station. The photometric analysis conducted for the guideway indicates an average of 6 foot-candles.

- **Crosswalk lighting levels:**

Per IES and SANDAG standards, an average of 5 foot-candles shall be provided on the crosswalks. The photometric analysis conducted for the crosswalk indicates an average of 6 foot-candles.




The photometric analysis also included lighting levels at the utility cabinets which per IES and SANDAG standards, 5 foot candle average shall be provided on the yard equipment enclosures. The photometric analysis conducted for the utility cabinets indicates an average of 6 foot-candles.



## **7 APPENDIX**

---


### **7.1 Urban Design Exhibits**




Chula Vista Improvements





Otay Mesa ITC Improvements





KEY MAP  
NOT TO SCALE























NOTE:  
STATION SIGNAGE TO BE DETERMINED  
AND COORDINATED WITH OTAY RANCH  
TOWN CENTER AND MTS






















**PREFERRED ALTERNATIVE**





SITE PHOTO INSPIRATION:



E. Palomar St & Heritage Park Median Turnout



Heritage Park Community Center




E. Palomar St & Monarche Drive

PROPOSED FENCE STYLES:




STYLE A: METAL POST RAILING (Metal Color: Black)


**PREFERRED ALTERNATIVE**



STYLE B: STONE VENEER COLUMN AND RAILING (Metal Color: Black)



STYLE C: CMU BLOCK COLUMN, LOW WALL AND RAILING (Metal Color: Black)





STYLE B: STONE VENEER



Cognac Country Rubble



Honey Wheat Natural



Sequoia Rustic Ledge

STYLE C: CMU BLOCK




Red Brick Split-Face



Dusty Brown Split-Face



Merlot Split-Face



Red Brick Precision



Dusty Brown Precision



Merlot Precision



ELEVATION



OPTION A: Downtown/I-15 Shelter



SECTION



ELEVATION



OPTION B: Blue Line Trolley Shelter



SECTION



**PREFERRED ALTERNATIVE**



ELEVATION



OPTION C: Chula Vista Hybrid Shelter



SECTION



BENCH OPT1- LANDSCAPE FORMS - PRESIDIO



BENCH OPT2-VICTOR STANLEY - STEELSITES RB-28

**PREFERRED ALTERNATIVE**




TRASH CAN - VICTOR-STANLEY - IRONSITES SD-42



BIKE LOCKERS - BIKE LINK - eLOCKER



LIGHT POLE AND FIXTURE - GARDCO - SQUARE 10



PAVER GRATE - IRONSMITH



PLATFORM EDGE AND  
YELLOW TACTILE DOME



TICKET VENDING MACHINE



P.C.I.D.



VARIABLE MESSAGE SIGN



PAYPHONE



VENDING MACHINE





TYPE 1: Primary Site ID-16' Ht.  
(Outside of Guideway)



TYPE 1:  
ADA Plaque



TYPE 2:  
ADA Plaque



TYPE 2: Secondary Site ID-8' Ht.  
(At Platform Entry)  
in Guideway



TYPE 18: Pedestrian  
Information Sign




TYPE 8: Directional Kiosk



TYPE 51: Small Vehicular Restrictive Sign



TYPE 51: Large Vehicular Restrictive Sign




TYPE 19: Bus Bay Cube  
(Free Standing)



TYPE 10: Station Identification  
(On Shelter Canopy)



TYPE 12: Station Identification  
(On Light Pole)



TYPE 15: Destination  
(On Light Pole)




TYPE 30: ADA Platform  
(Free Standing)



TYPE 51: Restrictive Sign  
(On Light Pole)



TYPE 17: Small Information Accessible Route  
(On Light Pole)



TYPE 45: Information Kiosk, Four Panel  
(Free Standing)





*WASHINGTONIA ROBUSTA* - MEXICAN FAN PALM



*H. MULTIFLORA*

*HEMEROCALLIS* - DAY LILY



*H. FULVA ROSEA*



*H. HAKUNENSIS*




*H. FULVA*




Community Transit – Snohomish County, Washington  
(Near-Level Boarding with 10-inch Curb)




RTC Rapid – Reno, Nevada (Level Boarding)







**UD.29**  
Security Zones:  
Eastbound Platform Elevation





NORTH END



C1: on VMS pole at 13' height looking north.



C2: on VMS pole at 13' height looking south.



C3: on light pole at 14' height looking south.



C4: on light pole at 14' height looking north.



C5: on VMS pole at 13' height looking north.



C6: on VMS pole at 13' height looking south.

SOUTH END





NORTH END



C1: on VMS pole at 13' height looking north.



C2: on VMS pole at 13' height looking south.



C3: on light pole at 14' height looking north.



C4: on light pole at 14' height looking south.



C5: on VMS pole at 13' height looking north.



C6: on VMS pole at 13' height looking south.

SOUTH END

## **7.2 South Bay BRT Arborist Report**



## South Bay BRT Arborist Report

Client: Kimley-Horn and Associates  
401 B Street, Suite 600  
San Diego, CA. 92101

Prepared by: Mr. Jeremy Rappoport  
Rappoport Development Consulting Services LLC  
1286 University Ave. #807  
San Diego, CA. 92103

## **Table of Contents**

Executive Summary	3
Introduction	4
Observations	6
Testing and Analysis	11
Discussion	16
Tree Selection Considerations:	17
Conclusions	22
Recommendations	23
Glossary	24
Appendices A – M	
A – Assumptions and Limiting Conditions	26
B – Certificate of Performance	28
C – City of Chula Vista Recommended Plant List	29
D – Option 4, Typical Section, Oleander Avenue to Heritage Road	32
E – Option 4A, Typical Section, Oleander Avenue to Heritage Road	33
F – Typical Section, Heritage Road to Olympic Parkway	34
G – Palomar Tree Inventory Data	35
H – Data Results	70
I – Data Graphs	71
J – Species List	72
K – RDCS Recommended Tree Palette	73
L – Study Area Site Exhibit	74
M - Median & Parkway Tree Location Exhibit	75

## Executive Summary

Rappoport Development Consulting Services LLC (RDCS) was contracted to develop a tree inventory for the existing street trees within the medians and right of ways of East Palomar Street from Oleander Avenue east to Heritage Road and existing trees located in the median of East Palomar Street from Heritage Road east to Olympic Parkway for the development of the South Bay BRT guideway within the existing medians of East Palomar Road. The assignment also required RDCS to provide recommendations for a new street tree options that would be appropriate for the corridor based upon the environmental conditions and the observed maintenance practices.

The street tree inventory required extensive field inspection and utilized visual observation as the basis for the tree assessment. Tree data was documented on an excel spreadsheet that identified 1,553 woody trees and palm trees within the project limits. The two dominant trees are *Pyrus calleryana* (Bradford Pear) and *Washingtonia robusta*, (Mexican Fan Palm). The subject trees were identified and field labeled using ¾" aluminum tree tag stapled to the tree trunk. The inventory also assigned a location number to each tree, assessed the tree trunk diameter at breast height (DBH), palm tree brown trunk height (BTH), tree condition, planting location, specific health issues and maintenance needs.

During this process, the City of Chula Vista determined the following additional criteria:

1. All woody trees impacted by new construction that cannot be preserved in place will be removed.
2. All existing Mexican Fan Palms between Heritage Road and Olympic Parkway will be preserved in place or relocated/reused within the project corridor if feasible.

Based on the local climate and environment, RDCS concluded that an informal, drought tolerant Mediterranean street tree theme re-using existing Mexican Fan Palms supplemented with new and additional palm trees and flowering evergreen trees would be an appropriate street tree theme. Tree selection was based on tree size at maturity fitting into a restricted planter width, the tree form, growth characteristics and cultural requirements, drought tolerance, aesthetics and maintenance needs. Recommendations include reducing or eliminating turf grass as a ground cover, planting trees in shrub planters, using inorganic ground covers and drip irrigation.

## **Introduction**

RDCS was contacted by Kimley-Horn and Associates (KHA) in March of 2012. KHA requested a proposal resulting in a sub-consultant contract established between KHA and Rappoport Development Consulting Services LLC (RDCS) for arborist consulting services for a SANDAG project called the South Bay Bus Rapid Transit (SBBRT) located in San Diego and Chula Vista, California.

The SBBRT project includes the design and construction of BRT bus guideway in the median of East Palomar Street from Oleander Avenue east to Olympic Parkway (The Study Area). Due to expected construction impacts to the existing street trees along the 3.8 mile stretch of East Palomar Street, KHA contracted with RDCS for an arborist consulting services including a tree inventory, analysis, and an arborist report including new street theme and tree palette recommendations.

The purpose of this arborist report is to identify, inventory and analyze the existing median and parkway street tree health and location relative to the future bus lane improvements. Within the Study Area, RDCS will determine which trees can be relocated, re-used or abandoned and develop recommendations for a new street tree program based on City of Chula Vista approved street trees and street tree theme options.

### ***Assignment:***

1. Conduct a street tree field inspection and create a tree inventory for East Palomar Street – From Oleander Avenue east to Heritage Road.
  - a. Include all trees located in the existing median.
  - b. Include all trees in the city Right of Way (from back of walk to back of walk).
  - c. Include all trees in the zone from the back of each walk to a dimension of 8'-0" offset outside of each Right of Way line.
2. Conduct a street tree field inspection and create a tree inventory for East Palomar Street – From Heritage Road east to Olympic Parkway.
  - a. Include all trees located in the medians only.
3. Perform tree tagging, identification, data collection, and photographic documentation, and develop an inventory spreadsheet.
4. Create an arborist report containing the tree inventory, analysis and recommendations for a new street tree theme and a tree planting palette.

### *Limit of the Assignment*

This assignment was limited to:

1. Visual observation of the plant material.
2. Trees and palm trees observed from ground level.
3. Inventory performed by walking the Study Area.
4. Trunk DBH and palm BTH are approximate estimates.
5. The tree inspection and analysis did not include tree risk assessment.
6. Soil and tissue sampling and testing were not included in the assignment.
7. Work will be limited to the Study Area only.

### *Purpose and Use of the Report*

The purpose of this report is to make recommendations for the existing parkway and median trees on East Palomar Street affected by the proposed BRT bus guideway design and construction. This report should be used by KHA, SANDAG and project stakeholders to make tree related decisions to retain, move, relocate or abandon trees within Study Area. The tree inventory will identify, quantify and assess the health condition of the subject trees. This report recommends trees to retain, reuse, relocate or abandon based on current BRT bus guideway design options by KHA and recommends a new street tree theme with a recommended plant palette.

## Observations

The SBBRT project involves a 3.8-mile stretch of East Palomar Street in Chula Vista, California. East Palomar Street is an arterial road with an east – west orientation. This report and inspections considered tree located in the median, north and south parkways of East Palomar Street from Oleander Avenue east to Heritage Road and trees located in the median from Heritage Road east to Olympic Parkway (the Study Area).

### *Investigation Methods:*

Visual observation was used for inspecting all of the trees. The tree trunk measurement to determine the *diameter at breast height, (DBH)* and the palm tree *brown trunk height, (BTH)* are based on visual observation. Independent tape measurements were employed throughout daily inspections to cross verify estimated trunk diameters.

Visual observation and estimation was employed to determine palm tree brown trunk height (BTH). Using an Apple IPAD with a height and distance measuring application called *Too Big Too Far*, digital measurements cross-verified estimated brown trunk height measurements on random palm trees.

Trees were photo-documented using a Canon S95 digital camera.

The inventory process began with labeling each tree within the project scope of work. Each ¾" x 3 1/2" aluminum cardboard backed tree tag was engraved with the tree ID number and date. The label was stapled onto tree trunks greater than 3" in diameter or tied onto a tree branch if the trunk was less than 3" in diameter.

Trees were labeled as M (median), NP (north parkway) or SP (south parkway) starting at the intersection of Oleander Avenue and continued consecutively easterly to the terminus at Olympic Parkway.

Following tree labeling, site inspections utilized visual observation to assess the tree condition:

- The *tree crown* was observed from fifteen (15') feet, evaluating foliage color, density, limb, branch and twigs, and
- A 360-degree inspection of the tree trunk, *root crown* and visible surface roots was completed.

Field collected data was entered into an Excel spreadsheet on an Apple IPAD.



### *Site Conditions:*

The stretch of East Palomar Street examined from Oleander Avenue east to Olympic Parkway consists of three traffic lanes in each direction. From Oleander Avenue east to Heritage Road, there are several discontinuous median strips from block to block. The medians contain trees, turf and shrubs. From Heritage Road east to Olympic Parkway, the median strip is wide and planted primarily with turf, Mexican Fan Palms and Pear trees.

The road topography is level with minor vertical grades. The north and south parkways each contain wide sidewalks, discontinuous from the curb, thereby creating a planter strip between the curb and sidewalk and a planter behind sidewalk extending to a masonry residential sub-division screening wall or to a bottom of slope that represented a subdivision property line.

Both parkway planter areas between the curb and sidewalk were planted with trees and palms surrounded by turf grass, certain areas were planted with shrubs and shredded bark ground cover. Parkway planter areas extending eight feet behind the sidewalk were planted with trees and palms, shrubs and shredded bark ground cover, turf was not planted behind the sidewalk.

The median planter from Oleander Avenue to Heritage Blvd consists of trees with shrubs and shredded bark ground cover. The median planter from Heritage Road east to Olympic Parkway is dominated by trees and palms planted in turf strips behind the median curb or in wider turf areas that exist in portions of the median from Heritage Road to Olympic Parkway.

Both the median and parkways receive automatic overhead spray irrigation. Tree located in turf areas are irrigated by turf pop-up spray heads. Old flood bubbler heads in four-inch drainage pipe sleeves were observed in several tree wells. Trees located in shrub planters received irrigation from the overhead pop-up heads or spray heads on risers.

Throughout the course of the inventory inspection, landscape maintenance operations were observed in the median and parkways including turf mowing, edging and string trimming, minor shrub pruning and weeding. Trees located in turf areas displayed root crown and lower trunk damage consistent with string trimming injuries. In many areas, turf over-irrigation was reflected in the tree condition.

## Subject Trees:

The Callery or Bradford Pear (*Pyrus calleryana*) and the Mexican Fan Palm (*Washingtonia robusta*) dominate the median and parkway planters. Additional street tree species include the Chinese Flame Tree (*Koelreutaria bipinnata*), the Red Flowering Gum (*Corymbia ficifolia*), a few Fern Pine (*Podocarpus gracilior*), Aleppo Pine, (*Pinus halepensis*), Evergreen Pear (*Pyrus kawakamii*), African sumac (*Rhus lancea*), and Lemonade Berry (*Rhus integrifolia*).

The Callery or Bradford Pear is a medium sized deciduous tree native to Japan and Korea. At maturity, the tree may reach 40 feet in height with a third of the spread. The tree has a rapid growth rate, requires full sun, is tolerant of hot, dry conditions and is fairly adaptable to many conditions. The Bradford Pear is susceptible to fireblight, a bacterial infection that enters through the swelling buds of the pear and causes foliage blackening, leaf, twig and stem dieback. In severe cases, the entire crown may become infected. Certain Bradford Pear cultivars are fireblight resistant.

The Bradford Pear has deep green foliage summer foliage that gives way to orange, red and purple foliage during the colder fall and winter months. In late April through May, the tree produces a massive profusion of white flowers that cluster in 3" diameter corymbs. The appearance is extremely attractive although the flowers may be malodorous.

A showy flower display, fall color, fast grower and moderately sized tree, the Bradford Pear is popular, used as a street tree, mass and hedge effect, small residential tree, and accent flowering specimen tree. Drawbacks include a genetic predisposition to grow very dense, tight *crotch angles* that over time result in tree limb breakage caused by weight, mechanical damage, storm, wind, rain or other environmental conditions. Regular crown *cleaning* and *reduction* pruning is required to minimize poorly formed crotch angles and resultant tree damage.

In general, the Bradford Pear has been heavily overused in the landscape, resulting in less diverse plant communities and monospecies. It's dense, rigid form, may appear unnatural in drought tolerant, native, or Mediterranean themed landscape plantings.

The Mexican Fan Palm (*Washingtonia robusta*) is native to Mexico and has naturalized throughout Southern California. The palm may grow to 85 feet, has a vigorous growth rate and few pests or diseases. The palm grows a single trunk that is larger at the base then narrows to 10-12" wide approaching the crown. Very heat and somewhat salt tolerant, the palm is cold tolerant to approximately 18 degrees F.

Large, dark green palmate leaves that droop at the leaflet tips form a symmetrical rounded crown. The palm fronds may grow up to five feet long and four feet wide on three-foot long orange colored stems that are lined with saw-toothed spines. In the summer, the palm produces light beige colored *inflorescences* that extend beyond the palm fronds reaching 10' long that yield small white flowers that mature into black seeds or berries that easily germinate.

As palm fronds die, they droop against the trunk of the palm tree forming a dense matting of dead fronds that may contain rats and other climbing rodents. Heavy accumulation of dead fronds and inflorescences increase tree hazard and risk, especially during weather events. Annual palm pruning should be performed to minimize risk by removing dead fronds and inflorescences.

Due to the fast growth rate, salt tolerance and unique architectural form, the Mexican Fan Palm is used in street tree groupings, mass and linear plantings and large groves.

The inventory inspection and assessment examined and determined:

- Tree species
- Tree trunk diameter at breast height
- Palm tree brown trunk height
- Tree health rating
- Tree conditions
- Tree location relative to curbs, sidewalks and planter obstructions
- Presence of turf
- Maintenance needs

### *Subject Pests:*

The scope of the assignment did not include tree health inspection for disease and pest identification, prevention and eradication. During the course of the inspection, ants and snails were the dominant pest noted on many of the tree species. A small percentage of *Pyrus* trees exhibited varying degree of fireblight infestation.

### *Information from Other Sources:*

KHA provided RDCS the following exhibits for this report:

1. Typical Sections, Heritage to Olympic, see Appendix F
2. Option 4, Typical Sections, Oleander Ave. to Heritage Road, see Appendix D.
3. Option 4A, Typical Sections, Oleander Ave. to Heritage Road, see Appendix E.
4. City of Chula Vista Recommended Plant Palette, see Appendix C.

## **Testing and Analysis**

The onsite assessment occurred during the months of August and September of 2012.

Tree labeling began in August of 2012. The labeling noted:

1. Tree ID # M, SP or NP consecutively numbered from Oleander to Olympic
2. Tree Code: KP, PC, WR, etc.
3. Date: Various dates in August

The labels were stapled to tree trunks greater than 3" in diameter, tied around a tree branch for trunks under 3" in diameter. To reduce vandalism, the labels were placed away from pedestrian sidewalks and at the bottom of the palm tree trunks.

Following tree labeling, the tree assessment and inventory began.

### *Tree Inventory Spreadsheet:*

The full tree inventory is located in Appendix G.

The tree inventory spreadsheet contains six categories, with specific category information contained in separate columns

1. Tree Information: Contains pertinent tree identification and size data.
  - a. Photo #: The individual digital photograph number of the tree. The photograph numbers are NOT in a numeric sequence.
  - b. Tree ID #: The trees are identified as M representing the median tree, SP representing the south parkway trees, and NP representing the north parkway trees.
  - c. Tree Code: The tree code is an abbreviation for the tree genus and species.
  - d. DBH: DBH stands for diameter at breast height. This is a measure of the tree trunk diameter at approximately 4.5' above finish grade.
  - e. BTH: BTH stands for brown trunk height and is a standard for measuring the trunk height of palm trees from finish grade to the bottom of the crown.

2. Tree Condition: The tree condition rates the overall health condition of the tree:
  - a. The letter G: Represents a tree in good condition, vigorous growth, good color, few or minor defects not affecting tree health.
  - b. The letter F: Represents a tree in fair condition, crown, trunk, root injuries, disease or maintenance practices reducing tree vigor and health.
  - c. The letter P: Represents a tree in poor condition, crown dieback, disease, root and trunk injuries have affected the tree to the point of removal.
  - d. The letter D: Represents a dead tree that should be removed.
3. Planting Location: This code assesses the tree location relative to hardscape improvements or in a sidewalk cutout planter:
  - a. Swik: Tree is located in a sidewalk planter cutout.
  - b. <3': The tree is located less than three feet from hardscape obstruction possibly limiting root growth.
  - c. >3': The tree is located greater than 3' from a hardscape obstruction and has greater area for root growth.
  - d. Lwn: The tree is surrounded by turf. Turf irrigation may cause overwatering, turf maintenance may cause root and trunk injury.
4. Conditions: This category describes individual tree factors affecting tree health:
  - a. Weak fork: Poorly formed branch or crotch angles that present areas of mechanical weakness through *co-dominant* branches and *included bark*.
  - b. Root damage: This notes any physical root damage visible at the soil surface and root crown.
  - c. Trunk damage: This notes injuries to the trunk and main *scaffold branches*.
  - d. Crown decline: This notes any decline in crown appearance including off color foliage, thinning foliage, foliage, twig and stem dieback and foliage disease.

- e. **Rot / Cav:** This stands for rot, decay or cavity and assesses whether the tree has a systemic rot within the trunk and or existing cavities caused by injury, rot or other factors.
5. **Maintenance Needs:** This describes whether the tree requires remedial forms of pruning for tree health and or safety reasons:
- a. **Clean:** A form of pruning that only removes dead twigs, stems and branches typically under 2-3” in diameter.
  - b. **Raise:** A pruning technique used to gain vertical clearance from finish grade to the lowest permanent tree branch. It is used to gain pedestrian and vehicular clearance under tree limbs.
  - c. **Red:** Represents reduction, a pruning technique used to lower the height and or spread of a tree by removing live branches up to six inches in diameter.
  - d. **Rem:** This represents remove the tree from the landscape.
6. **Comments:** This category contains site related observations that may be affecting tree health or a sign of impending tree issue:
- a. **Overwatered:** This was a common condition observed for trees planted within turf grass areas.
  - b. **Trk girdled:** The tree trunk is girdled, a term used when the cambium and tree bark is damaged 360 degrees around the trunk.
  - c. **Ants and snails were noted for trees with major infestations.**
  - d. **Miscellaneous comments concern whether the tree has a significant lean, the presence of a *conk* at the *root crown*, fireblight foliage disease or other tree risk factors.**

*Tree Inventory Data:*

The tree inventory data summarizing the tree name, tree code and total quantity is summarized in Table 1.

<b>Scientific Name</b>	<b>Code</b>	<b>Quantity</b>
*Eucalyptus ficifolia	EF	29
Koelreutaria bipinnata	KB	133
Pyrus calleryana	PC	918

Pyrus kawakamii	PK	5
Podocarpus gracilior	PG	8
Pinus halepensis	PH	2
Rhus lancea	RL	2
Rhus integrifolia	RI	3
Washingtonia robusta	WR	453
<b>Total:</b>		1553

Table 1: Tree Inventory Data Summary

\*Previously known as Eucalyptus ficifolia, now classified as Corymbia ficifolia.

The tree condition for all the project trees is summarized in Table 2.

Tree Condition	Actual #	% of Population
Good	1370	88%
Fair	142	9%
Poor	27	2%
Dead	14	1%

Table 2: Project Tree Condition

Specific health conditions assess injuries or structural deficiencies that affect trees, the conditions are summarized in Table 3.

Health Conditions	Actual #	% of Population
Weak Fork	7	0%
Root Injury / damage	119	8%
Trunk Injury / damage	305	20%
Crown decline	54	3%
Rot / Cavity	15	1%

Table 3: Health Conditions

The planting location describes how close the tree is growing to a sidewalk, curb or other hardscape element that impedes root growth. Trees planted in turf grass are noted because of the possible negative effects of turf irrigation and maintenance practices. The planting location is summarized in Table 4.

Planting Location	Actual #	% of Population
Sidewalk (in cut out)	0	0%
<3' (less than 3' from edge of hardscape)	456	29%
>3' (greater than 3' from edge of hardscape)	1096	71%
Planted in Turf-grass	1130	73%

Table 4: Planting Location

East Palomar Street receives regular maintenance service. Most of the woody trees have been pruned within the last one to two years. Majority of the palms require frond cleaning. Maintenance needs are summarized in Table 5.

<b>Maintenance Needs</b>	<b>Actual #</b>	<b>% of Population</b>
Safety / clean	458	29%
Crown raise	7	0%
Crown reduction	0	0%
Removal	30	2%
Overwatered	34	2%
Fully Girdled trunk	22	1%

Table 5: Maintenance Needs

### *South Bay BRT Typical Section Design Options:*

The future BRT bus guideway is being designed to fit within the existing medians of East Palomar Street. East Palomar Street from Oleander Avenue to Heritage Road did not account for a BRT bus guideway when designed and built decades ago. Plans call for the demolition of medians and right of ways, inclusive of all trees except Mexican Fan Palms (which may be relocated within the study area if feasible). The north right of way requires a low retaining wall built along property line to accommodate the street improvements.

From Heritage Road to Olympic Parkway, the existing median in East Palomar Street was designed and constructed anticipating the future BRT bus guideway within the existing median. Therefore, the existing median width and much of the tree planting conforms to the new BRT bus guideway alignment and relocation of certain Mexican Fan palms rather than complete demolition is anticipated.



## **Discussion**

### *General Health Conditions:*

From Oleander Avenue east to Olympic Parkway, the project has 1,553 trees yet with a very few minor exceptions, only the Mexican Fan palms require frond cleaning. The landscape medians and parkways of East Palomar Street are well maintained, with 1,370 trees, or 88% of the project tree population rated in good condition.

The Bradford Pear tree comprises two thirds of the tree population, visual inspection confirmed the trees have been regularly pruned and structured for several years. The Bradford Pear grows dense, heavy, poorly angled branch crotches that overtime tend to bread apart during weather events or with age. Regular pruning is required to keep this tree properly raised above pedestrian and vehicular traffic and thinned of co-dominant branches and included bark. There are a handful of pear trees that have severe fireblight symptoms as well as occasional dead branches on trees scattered throughout the population.

The Mexican Fan Palms, which comprises almost a third of the trees, are in good condition. Only frond and *inflorescences* required removal at the time of inspection.

Trees planted in turf areas exhibited a much higher degree of root and trunk injury than the same trees in shrub planters. Typical lower trunk damage included bark injury consistent with string trimmer maintenance. Root injuries were consistent with mechanical injury from a lawnmower or string trimmer.

Generally, the higher volume turf irrigation in certain areas resulted in standing water in tree wells in turf areas resulting in smaller trees in poorer health condition. Similar trees located in shrub planters were typically larger and more vigorous.

Trees that were greater than 3' from hardscape generally grew larger than trees located less than 3' from hardscape although the Mexican Fan palms appeared relatively unaffected if located within 3' of sidewalk.

### *1. Tree Selection:*

#### *1.1. Preliminary Street Sections:*

KHA provided RDCS preliminary street sections (Option 4 and Option 4A) for Oleander Avenue to Heritage Road and a preliminary BRT bus guideway section for Heritage Road to Olympic Parkway (see Appendices D, E and F). The primary features Options 4 and 4A are summarized in Table 6.

<b>Planter Widths</b>	<b>Option 4</b>	<b>Option 4A</b>
6' width median planters, no trees	X	
12' width ROW planters w/trees	X	
7' width ROW planters @ lft turn w/trees	X	
11' width median planters, no trees		X
7' width ROW planters w/trees		X
7' width ROW planters @ lft turn w/trees		X

Table 6: Preliminary Street Sections Planter Dimensions

### 1.2. *Bus Lane Options and Construction Impacts:*

From Oleander Avenue to Heritage Road, the preliminary street sections present varying planter widths for trees located within each right of way of 12' and 7' respectively.

A tree centered in a 7' wide planter would have a 3.5' for horizontal branch growth before it trespassed into a sidewalk or street. With the exception of the Mexican Fan palms, almost all of the existing woody trees on East Palomar Street have growth characteristics that would be unsuitable to locate within a 7' planter width.

Since the new preliminary street sections require reconstruction of the median and both parkways of East Palomar Street from Oleander Avenue to Heritage Road, all of the trees within the street right of ways will be removed. KHA informed RDCS the City of Chula Vista does not anticipate re-use of the Pyrus or other woody trees with the exception of the Mexican Fan Palm.

Options 4 and 4A both include a retaining wall constructed on the north right of way property line. Construction impacts to existing trees located within a few feet of the right of way property line may be expected. Prior to construction, trees located in this "edge" condition should be identified and best management practices should be employed to protect the tree in place. If the tree cannot be adequately protected, relocation or replanting a new tree in a different location should be considered.

### 1.3 *Tree Selection: Option Preference*

RDCS was tasked to make street tree recommendations that would work within the parameters of the preliminary street sections using the City of Chula Vista Recommended Plant Palette list (see Appendix C). Appropriate tree selection considered street tree theme, plant size at maturity, growth characteristics, cultural requirements, aesthetics and maintenance.

The preliminary street sections contain either a 12' or 7' planter width that effectively reduces tree selection to conical shaped woody trees or palm trees. Over time, trees centered in 7' width parkways will encounter some degree of root restriction; however the continuous planter length would benefit root growth.

The 12' wide planter affords a greater choice of trees to select and sufficient area for small to medium sized woody trees and palms to establish and flourish. As trees mature, they can be raised for horizontal and vertical clearance as needed without sacrificing or destroying the natural form of the tree.

#### *1.4 Tree Selection: Theme and Aesthetics*

The current theme from Oleander Avenue to Heritage Road on East Palomar Street uses deciduous flowering trees such as the Pyrus and Koelreutaria planted in turf grass. Throughout the winter, the trees are bare, leaving a stark appearance for a very busy street. The trees are planted on center with a strong linear emphasis creating a formal theme. This theme may be outdated and no longer applicable based on new water conservation regulations.

East Palomar Street is located in inland Chula Vista, where summer temperatures approach triple digits. Existing native terrain consisted of California Coastal Scrub on the rolling interior hillsides of Chula Vista. Development has replaced drought tolerant California native plants with heavily irrigated turf grass and non-native ornamental trees and shrubs. The results provide street after street with similar formal, repetitious tree plantings surrounded by high water consuming turf grass.

RDCS LLC believes a drought tolerant, Mediterranean themed tree planting is consistent with water regulation guidelines and well suited for the environmental, climatic and geographic location of East Palomar Street. The theme incorporates existing Mexican Fan Palms on East Palomar Street augmented with additional palm species and small to medium sized flowering evergreen trees. The evergreen trees are drought tolerant, possess slow to moderate growth rates, and will fit within a 12' width planter (with appropriate pruning), and will provide annual color or distinguishing characteristics.

This is an appropriate, attractive theme for East Palomar Street. It re-uses a third of the existing trees (Mexican Fan Palm) currently existing on East Palomar Street and reinforces a Chula Vista iconic tree. The Mediterranean theme is drought tolerant and will have much lower water use and maintenance costs.

#### *1.5 Tree Selection: Growth Characteristics and Cultural Requirements*

The preliminary street sections place horizontal growth restrictions on trees grown within a 7' or 12' wide planter. The 7' width planter combined with vehicular and pedestrian traffic requires trees conically shaped, with a very narrow growth form or a palm tree form plant. The 12' wide planter increases the potential tree palette as small to medium size trees may be fit within this width planter. Avoid broad headed canopies and encourage smaller pyramidal, conical, elliptical shaped tree crown that will conform to the planter width.

Tree height at maturity should vary from the tallest Mexican Fan Palm to the lowest clumping palm type. Slower to medium size growth rate is preferred for reduced maintenance, sustainability and longevity. The trees should require full sun exposure, tolerate heat and light frosts, and have drought tolerant characteristics. Well drained soils with drip or low volume irrigation system provide optimum conditions for drought tolerant trees to flourish. Turf grass should be avoided as a ground cover with drought tolerant trees.

#### 1.6 *Legal and Maintenance Considerations:*

Owner liability for a tree related accident that might cause injury to the public or property damage should be considered during the selection process. Trees requiring directional or one-sided pruning, constantly cleared or raised for horizontal or vertical clearance should be avoided as this practice destroys the natural form and possibly the structural integrity of the tree. Increased pruning wounds are entry points for insects and pathogens that cause decay and rot, creating cavities and structural weakness and increased risk of a whole tree or tree part failure. Tree hazards increase over time, thereby increasing the risk of injury to people and property. Maintenance costs increase with increased pruning, disposal and repairs.

#### 1.7 *Tree Selection: Conceptual Tree Choices:*

Woody trees that fit within a 7' planter width include the Italian Cypress (*Cupressus sempervirens*). The Canary Island Pine, (*Pinus canariensis*) and the New Zealand Christmas tree, (*Metrosiders excelsa*) may be considered, however both trees would require increased maintenance inspections and pruning events to ensure they remain within the 7' planter confines and not create vehicular and pedestrian obstructions.

Palm trees are the most appropriate fit for a 7' wide planter. Although the crown of many palms will exceed 7' in width, the canopy should be sufficient height to not pose an obstruction to vehicles or pedestrians. There are many existing Mexican Fan Palms within the medians and parkways of East Palomar Street, many in confined spaced that have adapted and grown well. Other palm trees that would perform well included the Guadalupe palm (*Brahea edulis*) the Windmill palm, (*Trachycarpus fortunei*) and others.

Trees selected that fit based on size at maturity are summarized in Table 7.

Scientific Name	Common Name	7' width	12' width
Brachychiton populneus	Bottle Tree		X
Brahea armata	Mexican Blue Palm	X	X
Brahea edulis	Guadalupe Palm	X	X
Butia capitata	Pindo Pam	X	X
Cassia leptophylla	Gold Medallion tree		X
Chamaerops humilis	Mediterranean Fan palm		X
Cupressus sempervirens	Italian Cypress	X	
Metrosideros excelsa	New Zealand Xmas tree	X	X
Pinus canariensis	Canary Island Pine tree	X	
Podocarpus gracilior	Yew Pine		X
*Podocarpus henkelii	Long Leafed Yew		X
*Rhus lancea	African Sumac		X
Trachycarpus fortunei	Windmill Palm	X	X
Tristania conferta	Brisbane Box		X
Washingtonia robusta	Mexican Fan Palm	X	X

Table 7: Tree Choices Based on Planter Width

\*Tree not on the City of Chula Vista Recommended Tree List

Using the Mediterranean tree theme combined with trees that fit in the 7' and 12' planter width, **Table 8 summarizes a Mediterranean themed landscape and is the recommended street tree palette.**

Scientific Name	Common Name	7' width	12' width
Brachychiton populneus	Bottle tree		X
Brahea armata	Mexican Blue Palm	X	X
Brahea edulis	Guadalupe Palm	X	X
Butia capitata	Pindo Pam	X	X
Cassia leptophylla	Gold Medallion tree		X
Chamaerops humilis	Mediterranean Fan palm	X	X
Chamaerops humilus 'cerifera'	Blue Mediterranean Fan palm	X	X
Metrosideros excelsa	New Zealand Xmas tree	X	X
*Podocarpus henkelii	Long Leafed Yew		X
*Rhus lancea	African Sumac		X
Trachycarpus fortunei	Windmill Palm	X	X
Washingtonia robusta	Mexican Fan Palm	X	X

Table 8: Recommended Street Tree Palette

The new palm tree types, frond, form, color and height at maturity are summarized in Table 9.

Tree:	Single Trunk	Fan	Feature	Clumping	Green	Gray/Blue	Ht.'
Brahea armata	X	X		X		X	30-40
Brahea edulis	X	X			X		20-30
Butia capitata	X		X		X		15-20
Chamaerops humilis		X		X	X		10-20
Chamaerops humilis "cerifera"		X		X		X	10-20
Trachycarpus fortunei	X	X			X		25-35
Washingtonia robusta	X	X			X		50-80

Table 9: Palm Trees Categorized by Trunk, Frond, Form, Color and Size

The flowering evergreen trees contain growth characteristics and features summarized in Table 10.

Tree:	Ht' x W'	Flowers	Distinguishing characteristic	Clearance pruning needed
Brachychiton populneus	45' x 25'	White Inconspicuous	Trunk	Yes
Cassia leptophylla	25' x 15'	Showy yellow in summer	Flowers	minor
Metrosideros excels	30' x 20'	Showy red spring-summer	Flowers, foliage	minor
Podocarpus henkelli	40' x 15'	Inconspicuous	Foliage	minor
Rhus lancea	25' x 18'	Inconspicuous	Trunk, foliage	minor

Table 10: Characteristics of Flowering Evergreen Trees

## Conclusions

Selecting a Mediterranean, drought-tolerant tree palette will increase the number and diversity of the palm trees to bolster the theme, while introducing small to medium sized flowering evergreen trees to create diversity and interest, while conforming to the planter width size restricted conditions.

The palette seeks to emphasize the palm theme by introducing several types of single trunk trees and clumping palms forms. Used in combination, the unique forms, texture and colors will create a striking street tree theme. Interspersing planting zones with drought tolerant flowering evergreen trees adds the cooling effect of shade, flower color, and distinctive trunk and foliage characteristics.

This palette will perform well in a 12' wide planter area. Where the 12' width planter reduces to 7' width, palm trees should be used. The recommended tree palette uses City of Chula Vista recommended trees, reuses existing Mexican Fan Palms, creates a drought tolerant, colorful, sustainable informal street tree planting that is environment and climate appropriate with fewer maintenance issues and lower maintenance costs than the existing turf and street tree theme.

The existing Mexican Fan Palms may require one of three forms of action depending on their existing location relative to the bus lane improvements.

1. Protect in place.
2. Provide minor horizontal relocation within four feet of existing location.
3. Box, or ball and burlap, possible offsite storage for re-installation at a new location.

Once the preliminary street section is finalized and the planter configurations are determined, best management practices (BMP's) for tree protection, moving, and relocation shall be designed and specified.

The shrub palette selections should supplement and augment the Mediterranean street tree theme. Shrubs with dramatic architectural form such as Flax, Agave and other forms will enhance the street tree theme, reduce water consumption and have lower maintenance requirements. Using colored, stabilized decomposed granite, rounded pea sized gravel, and shredded bark are all excellent ground cover choices that do not require irrigation, and are easily maintained and replenished.

## **Recommendations**

1. Remove all of the existing street trees in the median and right of way planters with the exception of the Mexican Fan Palm.
2. Preserve the Mexican Fan Palms for reuse in the landscape.
3. Select an informal drought tolerant Mediterranean theme landscape appropriate for local Chula Vista climate and environment and particularly for the topography and use of East Palomar Street.
4. Reduce or eliminate turf, use only for functional purposes.
5. Avoid planting trees in turf.
6. If turf must be used, install trees in planter areas separate from turf zones.
7. The Mexican Fan Palm may be planted in a formal on center planting or variable.
8. Supplemental palm plantings should be in grouped in drifts and clusters to simulate a natural appearance.
9. Use a drip or low volume irrigation system; avoid overhead spray irrigation except where turf is located.
10. Create improved drainage for all tree plantings through soil amending, grading, and local tree pit drainage devices.
11. Supplement the Mediterranean tree theme with appropriate drought tolerant compatible shrub understory planting.
12. Consider using colored stabilized decomposed granite, small rounded natural colored gravels and shredded bark products for ground cover planting.
13. Avoid selecting trees that have a growth form inconsistent with the restricted planter area widths.
14. Do not overwater drought tolerant trees and shrubs.



## Glossary

<i>Brown trunk Height (BTH)</i>	Term used to measure the height of palm trees from finish grade to the bottom of the canopy.
<i>Cavity:</i>	A hole or hollow formed in a tree trunk caused by an injury resulting in decay. Trees compartmentalize around wounds leaving a cavity.
<i>Clean:</i>	Pruning technique that removes dead and diseased branches to 2" in diameter.
<i>Co-dominant:</i>	A tree trunk with two equal sized trunks, neither trunk is dominant. Co-dominant trunks may have poor crotch angle and included bark.
<i>Conk:</i>	A fruiting body associated with a fungal pathogen. Conks typically signal an infection or decay.
<i>Crotch angle:</i>	Angle created where two trunks or limbs meet.
<i>Crown:</i>	The leaves, twigs, branches, and limbs form the tree crown.
<i>Decay:</i>	The process of wood cellulose tissue dying from disease in a tree usually caused by a pathogen.
<i>Diameter at Breast Height (DBH)</i>	Term used to measure a tree trunk diameter at 4.5' above finish grade.
<i>Included bark:</i>	The bark from two co-dominant trunks is forced inward created a weakened structural crotch angle.
<i>Inflorescence:</i>	The flowering stalk on a Mexican Fan Palm.
<i>Reduction:</i>	A pruning technique that removes live branches up to 6" in diameter, used to lower tree height or spread.
<i>Root Collar:</i>	The portion of a tree where the tree trunk and root system meet at the bottom of the tree.
<i>Scaffold branch:</i>	Main structural limbs attached to the tree trunk.

- Tree Inventory:* A method for collecting, assessing, counting and cataloging tree asset information into a database.
- Turf grass:* Ornamental ground cover known as grass or lawn.
- Visual Observation:* Technique used to observe and inspect trees.

## **Appendix A – Assumptions and Limiting Conditions**

1. Any legal description, easement condition, boundaries lines, property lines, maps, field survey and documents provided to the consultant are assumed to be correct.
2. Good faith efforts and attempts were taken to obtain information and data from reliable sources. However, the consultant can neither guarantee nor be responsible for the accuracy of the information provided by others or lack thereof.
3. Loss or alteration of any part of this report invalidates the entire report.
4. Possession of this report or a copy thereof does not imply the right of publication or use for any purpose outside of this proceeding without expressed written consent of the consultant.
5. No part of the contents of this report or copy shall be conveyed by anyone, including the client, to the public through advertising, public relations, news, sales or other media, without prior expressed written or verbal consent of the consultant particularly as to risk conclusions, identity of the consultant or any reference to any professional society or institute or to any initialed designation conferred upon the consultant as stated in his qualifications.
6. This report and values expressed herein represent the opinion of the consultant, and the consultant's fee is no way contingent upon the reporting of a specific value, stipulated results, and the occurrence of a subsequent event or other preconceived notion, value or figure.
7. Sketches, diagrams, charts and photographs in this report are intended as visual aids and are not drawn to scale and should not be construed as engineering or architectural reports or surveys.
8. Unless expressed otherwise: (1) information contained in this report covers only those items that were examined and reflects the condition of those items at the *time of the inspection*: and (2) the inspection is limited to visual examination of accessible items without dissection, excavation, probing or coring, unless otherwise specified.

9. The tree inventory and recommendations are based on the quantities and condition of the trees inspected in August and September of 2012. There is no warranty or guarantee, expressed or implied that the tree recommendations will survive and flourish without consultant involvement throughout the design, construction and project maintenance.

## **Appendix B – Certificate of Performance**

I, Jeremy Rappoport, certify that:

I have personally inspected the tree(s) and property referred to in this report and have stated my findings accurately, the extent of the inspection services is stated in the attached report and the scope of the assignment.

I have no current or prospective interest in the trees or the property that is the subject of this report and no personal interest or bias with respect to the parties involved.

The analysis, opinions, and conclusions stated herein are my own and based on current scientific procedures, facts and industry accepted inventory techniques.

My analysis, opinions, and conclusions were developed and this report has been prepared according to commonly accepted arboriculture industry practices.

No one provided significant professional assistance to me.

My compensation is not contingent upon the reporting of a predetermined conclusion that favors the cause of the client or any other party nor upon the attainment of stipulated results, or the occurrences of any subsequent events.

I further certify that I am a good standing member of the International Society of Arboriculture (ISA), the Western Chapter of the ISA, the American Society of Consulting Arborists (ASCA), the Professional Tree Care Association of San Diego (PTCA), and the California Landscape Contractors Association (CLCA).

I have been involved in the field of Arboriculture, Horticulture and Landscape contracting and construction for over three decades.

---

Jeremy Rappoport, President

---

Date: November 14, 2012

## Appendix C – City of Chula Vista Recommended Plant List

---

### Appendix "A"

#### Recommended Plant Palette

<u>Botanical Name</u>	<u>Common Name</u>
<b>TREES:</b>	
Acacia baileyana	Bailey's Acacia
Aesculus californica	California Buckeye
Albizia julibrissen	Silk Tree
Alnus rhombifolia	White Alder
Araucaria heterophylla	Norfolk Island Pine
Arbutus unedo	Strawberry Tree
Bauhinia variegata	Purple Orchid Tree
Brachychiton populneus	Bottle Tree
Callistemon viminalis	Weeping Bottlebrush
Calocedrus decurrens	Incense Cedar
Cassia leptophylla	Gold Medallion Tree
Cedrus atlantica 'Glaucua'	Atlas Cedar
Cedrus deodora	Deodar Cedar
Ceratonia siliqua	Carob Tree
Cercidium floridum	Blue Palo Verde
Cercis occidentalis	Western Red Bud
Cinnamomum camphora	Camphor Tree
Cupaniopsis anacardioides	Carrotwood
Cupressus:	
forbesii	Tecate Cypress
sempervirens	Italian Cypress
stephensonii	Cuyamaca Cypress
Erythrina coralloides	Naked Coral Tree
Eucalyptus:	
citriodora	Lemon-Scented Gum
ficifolia	Red-Flowering Gum
lehmannii	Bushy Yate
nicholii	Nicho's Willow-Leafed Peppermint
polyanthemos	Silver Dollar Gum
rudis	Desert Gum
sideroxyton 'Rosea'	Red Ironbark
Feijoa sellowiana	Pineapple Guava
Ficus rubiginosa	Rustyleaf Fig
Fraxinus oxycarpa 'Raywood'	Raywood Ash
Geijera parviflora	Australian Willow
Hymenosporum flavum	Sweetshade
Jacaranda acutifolia	Jacaranda
Juglans californica	California Walnut
Koelreuteria:	
bipinnata	Chinese Flame Tree
paniculata	Goldenrain Tree
Ligustrum lucidum	Glossy Privet
Liquidambar styraciflua	Sweet Gum
Lithocarpus densiflora	Tan-Oak


<u>Botanical Name</u>	<u>Common Name</u>
<b>Lyonothamnus floribundus 'asplenifolius'</b>	<b>Fernleaf Catalina Ironwood</b>
<b>Magnolia grandiflora</b>	<b>Southern Magnolia</b>
<b>Melaleuca:</b>	
<b>linarifolia</b>	<b>Flaxleaf Paperbark</b>
<b>quinquenervia</b>	<b>Cajeput Tree</b>
<b>Metrosideros excelsus</b>	<b>New Zealand Christmas Tree</b>
<b>Olea europaea 'Fruitless'</b>	<b>Olive</b>
<b>Parkinsonia aculeata</b>	<b>Mexican Palo Verde</b>
<b>Pinus:</b>	
<b>canariensis</b>	<b>Canary Island Pine</b>
<b>halepensis</b>	<b>Aleppo Pine</b>
<b>pinea</b>	<b>Italian Stone Pine</b>
<b>torreyana</b>	<b>Torrey Pine</b>
<b>Pittosporum:</b>	
<b>rhombifolium</b>	<b>Queensland Pittosporum</b>
<b>undulatum</b>	<b>Victorian Box</b>
<b>Platanus:</b>	
<b>acerifolia</b>	<b>London Plane Tree</b>
<b>racemosa</b>	<b>California Sycamore</b>
<b>Podocarpus gracilior</b>	<b>Fern Pine</b>
<b>Populus fremontii</b>	<b>Fremont Cottonwood</b>
<b>Prunus:</b>	
<b>cerasifera 'Krauter Vesuvius'</b>	<b>Purple Leaf Plum</b>
<b>lyonii</b>	<b>Catalina Cherry</b>
<b>Psidium littorale</b>	<b>Strawberry Guava</b>
<b>Pyrus:</b>	
<b>calleryana 'Bradford'</b>	<b>Ornamental Pear</b>
<b>kawakamii</b>	<b>Evergreen Pear</b>
<b>Quercus:</b>	
<b>agrifolia</b>	<b>Coast Live Oak</b>
<b>chrysolepis</b>	<b>Canyon Live Oak</b>
<b>engelmannii</b>	<b>Engelman Oak</b>
<b>ilex</b>	<b>Holly Oak</b>
<b>suber</b>	<b>Cork Oak</b>
<b>tomentella</b>	<b>Island Oak</b>
<b>Salix:</b>	
<b>gooddingii</b>	<b>Black Willow</b>
<b>hindsiana</b>	<b>Sandbar Willow</b>
<b>lasiolepis</b>	<b>Arroyo Willow</b>
<b>Sambucus mexicana</b>	<b>Mexican Elderberry</b>
<b>Schinus molle</b>	<b>California Pepper</b>
<b>Sequoia sempervirens</b>	<b>Coast Redwood</b>
<b>Tabebuia chrysotricha</b>	<b>Golden Trumpet Tree</b>
<b>Tipuana tipu</b>	<b>Tipu Tree</b>
<b>Tristania conferta</b>	<b>Brisbane Box</b>
<b>Umbellularia californica</b>	<b>California Laurel</b>

	<u>Botanical Name</u>	<u>Common Name</u>
<b>PALMS:</b>	<b>Archontophoenix cunninghamiana</b>	<b>King Palm</b>
	<b>Arecastrum romanzoffianum</b>	<b>Queen Palm</b>
	<b>Beaucarnea recurvata</b>	<b>Bottle Palm</b>
	<b>Brahea armata</b>	<b>Mexican Blue Palm</b>
	<b>Brahea edulis</b>	<b>Guadalupe Palm</b>
	<b>Butia capitata</b>	<b>Pindo Palm</b>
	<b>Chamaerops humilus</b>	<b>Mediterranean Fan Palm</b>
	<b>Cycas revoluta</b>	<b>Sago Palm</b>
	<b>Dracena draco</b>	<b>Dragon Tree</b>
	<b>Jubaea chilensis</b>	<b>Chilean Wine Palm</b>
	<b>Livistona chinensis</b>	<b>Chinese Fountain Palm</b>
	<b>Phoenix:</b>	
	<b>canariensis</b>	<b>Canary Island Date Palm</b>
	<b>dactylifera</b>	<b>Date Palm</b>
	<b>reclinata</b>	<b>Senegal Date Palm</b>
	<b>roebellenii</b>	<b>Pygmy Date Palm</b>
	<b>Trachycarpus fortuneii</b>	<b>Windmill Fan Palm</b>
	<b>Washingtonia:</b>	
	<b>filifera</b>	<b>California Fan Palm</b>
	<b>robusta</b>	<b>Mexican Fan Palm</b>



**Appendix D – Option 4, Typical Section Oleander to Heritage**

**Option 4 Typical Section**  
Oleander to Heritage







## Appendix G – Palomar Tree Inventory

 1  
 11/13/12

Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information			Tree Condition		Planting Location		Conditions			Maintenance Needs				Comments														
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1	M11	PC	10			X				X																		
2	M2	PC	8			X				X																		
3	M4	PC	7			X				X																		
4	M5	PC	7			X				X																		
5	M6	PC	10			X				X																		
6	M7	PC	8			X				X																		
7	M8	PC	10			X				X																		
8	M9	PC	5			X				X																		
9	M10	PC	1			X				X																		
10	M11	PC	9			X				X																		
11	M12	PC	6			X				X																		
12	M13	PC	5			X				X																		
13	M14	PC	5			X				X																		
14	M15	PC	6			X				X																		
15	M16	PC	6			X				X																		
175	M17	KB	7			X				X																		
176	M18	KB	6			X				X																		
177	M19	KB	7			X				X																		
178	M20	KB	8			X				X																		
179	M21	KB	8			X				X																		
180	M22	KB	9			X				X																		
181	M23	KB	6			X				X																		
182	M24	KB	9			X				X																		
183	M25	KB	8			X				X																		
184	M26	KB	10			X				X																		
185	M27	KB	7			X				X																		
186	M28	KB	6			X				X																		
187	M29	KB	5			X				X																		
188	M30	KB	5			X				X																		
1041	M31	KB	4			X				X																		
1040	M32	KB	5			X				X																		
1039	M33	KB	3			X				X																		
1038	M34	KB	4			X				X																		
1037	M35	KB	5			X				X																		
1036	M36	KB	5			X				X																		
1035	M37	KB	4			X				X																		
1034	M38	KB	4			X				X																		
1033	M39	KB	3			X				X																		
1032	M40	KB	1			X				X																		
1031	M41	KB	3			X				X																		
1030	M42	KB	4			X				X																		
1029	M43	KB	4			X				X																		
1028	M44	KB	4			X				X																		
1027	M45	KB	4			X				X																		
1026	M46	KB	5			X				X																		

2  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition		Planting Location		Conditions				Maintenance Needs				Comments											
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swik	<3'	Lwn	Weak	Root	Trunk	Crown	Rot/	Clean	Raise	Red.	Rem.	Over	Trunk	Ants	Snails	Comments	
													for	Damage	Damage	Decline	Cavity					watered	Girdled				
1025	M47	KB	5			X				X	X	X		X													
1024	M48	KB	1			X				X	X	X			X												
1023	M49	KB	6			X				X	X	X															
1021	M50	KB	4			X				X	X	X															
1020	M51	KB	5			X				X	X	X															
1019	M52	KB	7			X				X	X	X															
1018	M53	EF	7			X				X	X	X															
1017	M54	EF	11			X				X	X	X															
1016	M55	EF	8			X				X	X	X															
1015	M56	EF	7			X				X	X	X															
1014	M57	EF	8			X				X	X	X															
1013	M58	EF	1			X				X	X	X															
1012	M59	EF	8			X				X	X	X															
1011	M60	EF	7			X				X	X	X															
1010	M61	EF	10			X				X	X	X															
1009	M62	EF	1			X				X	X	X															
1008	M63	EF	9			X				X	X	X															
1007	M64	EF	10			X				X	X	X															
1006	M65	EF	4			X				X	X	X															
1005	M66	EF	12			X				X	X	X															
	M67	EF	1			X				X	X	X															
	M68	EF	Not Used			X				X	X	X															
1004	M69	EF	8			X				X	X	X															
1003	M70	EF	10			X				X	X	X															
1002	M71	EF	14			X				X	X	X															
1001	M72	EF	3			X				X	X	X															
1000	M73	EF	10			X				X	X	X															
999	M74	EF	10			X				X	X	X															
991	M75	EF	7			X				X	X	X															
992	M76	EF	4			X				X	X	X															
993	M77	EF	9			X				X	X	X															
994	M78	EF	5			X				X	X	X															
995	M79	EF	3			X				X	X	X															
996	M80	EF	6			X				X	X	X															
997	M81	EF	2			X				X	X	X															
998	M82	EF	9			X				X	X	X															
945	M83	PC	5			X				X	X	X															
944	M84	PC	9			X				X	X	X															
943	M85	PC	5			X				X	X	X															
942	M86	PC	6			X				X	X	X															
941	M87	PC	6			X				X	X	X															
940	M88	PC	7			X				X	X	X															
946	M89	WR	20			X				X	X	X															
947	M90	PC	4			X				X	X	X															
948	M91	WR	22			X				X	X	X															
949	M92	PC	6			X				X	X	X															

3  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Photo #	Tree Information			Tree Condition	Planting Location			Conditions			Maintenance Needs				Comments								
	Tree #	Code	Tree DBH		Palm	BTH	Swlk	<3'	>3'	Lwn	Weak Fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments
950	M193	WR		22	X				X														
951	M194	PC	6	23	X				X													X	
952	M195	WR		23	X				X														
953	M196	PC	3	23	X				X														
954	M197	WR		23	X				X														
955	M198	PC	3	23	X				X														
956	M199	WR		21	X				X														
957	M100	PC	1	22	X				X														
958	M101	WR		22	X				X														
959	M102	PC	8	23	X				X														
960	M103	WR		25	X				X														
961	M104	WR		25	X				X														
962	M105	PC	6	23	X				X														
963	M106	WR		23	X				X														
964	M107	PC	7	22	X				X														
965	M108	WR		22	X				X														
966	M109	PC	8	22	X				X														
967	M110	WR		22	X				X														
968	M111	PC	8	19	X				X														
969	M112	WR		19	X				X														
970	M113	PC	6	13	X				X														
971	M114	WR		13	X				X														
972	M115	PC	7	24	X				X														
973	M116	WR		24	X				X														
974	M117	PC	3	19	X				X														
975	M118	WR		19	X				X														
976	M119	WR		23	X				X														
977	M120	PC	7	19	X				X														
978	M121	WR		19	X				X														
979	M122	PC	6	24	X				X														
980	M123	WR		24	X				X														
981	M124	PC	7	18	X				X														
982	M125	WR		18	X				X														
983	M126	PC	8	19	X				X														
984	M127	WR		19	X				X														
985	M128	PC	6	23	X				X														
986	M129	WR		23	X				X														
987	M130	PC	7	21	X				X														
988	M131	WR		21	X				X														
989	M132	PC	6	24	X				X														
990	M133	WR		23	X				X														
816	M134	WR		23	X				X														
817	M135	PC	7	21	X				X														
818	M136	WR		21	X				X														
819	M137	PC	6	22	X				X														
	M138	WR		22	X				X														

4  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Photo #	Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Antis	Snails	Comments	
820	M1139	PC	5			X				X									X									
821	M140	WR	21			X				X																		
822	M141	PC	7			X				X																		
823	M142	WR	19			X				X																		
824	M143	PC	5			X				X																		
825	M144	WR	21			X				X																		
826	M145	PC	5			X				X																		
827	M146	WR	20			X				X																		
828	M147	PC	5			X				X																		
829	M148	WR	20			X				X																		
830	M149	PC	6			X				X																		
831	M150	WR	20			X				X																		
832	M151	PC	6			X				X																		
833	M152	WR	21			X				X																		
834	M153	PC	5			X				X																		
835	M154	WR	21			X				X																		
836	M155	PC	6			X				X																		
837	M156	WR	21			X				X																		
838	M157	PC	6			X				X																		
839	M158	WR	21			X				X																		
840	M159	PC	4			X				X																		
841	M160	WR	18			X				X																		
842	M161	PC	3			X				X																		
843	M162	WR	20			X				X																		
844	M163	PC	5			X				X																		
845	M164	WR	21			X				X																		
846	M165	PC	6			X				X																		
847	M166	WR	22			X				X																		
848	M167	PC	5			X				X																		
849	M168	WR	24			X				X																		
850	M169	PC	4			X				X																		
851	M170	WR	20			X				X																		
852	M171	PC	7			X				X																		
853	M172	WR	22			X				X																		
854	M173	PC	5			X				X																		
855	M174	PC	6			X				X																		
856	M175	WR	23			X				X																		
857	M176	PC	2			X				X																		
858	M177	WR	18			X				X																		
859	M178	PC	2			X				X																		
860	M179	WR	17			X				X																		
861	M180	PC	6			X				X																		
862	M181	WR	21			X				X																		
863	M182	PC	1			X				X																		
864	M183	WR	20			X				X																		
865	M184	PC	8			X				X																		

5  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Over watered	Girdled	Trunk	Ants	Snails	Comments	
866	M185	WR		18		X				X			X							X								
867	M186	PC	5	21	X	X				X			X							X								
868	M187	WR		21	X	X				X			X							X								
869	M188	PC	5	22	X	X				X			X							X								
870	M189	WR		22	X	X				X			X							X								
871	M190	PC	5	23	X	X				X			X							X								
872	M191	WR		23	X	X				X			X							X								
873	M192	PC	6	23	X	X				X			X							X								
874	M193	WR		23	X	X				X			X							X								
875	M194	PC	6	24	X	X				X			X							X								
876	M195	WR		24	X	X				X			X							X								
877	M196	PC	5	21	X	X				X			X							X								
878	M197	WR		21	X	X				X			X							X								
879	M198	PC	5	23	X	X				X			X							X								
880	M199	WR		23	X	X				X			X							X								
881	M200	PC	5	17	X	X				X			X							X								
882	M201	WR		17	X	X				X			X							X								
883	M202	PC	6	20	X	X				X			X							X								
884	M203	WR		20	X	X				X			X							X								
885	M204	PC	7	24	X	X				X			X							X								
886	M205	WR		24	X	X				X			X							X								
887	M206	PC	7	20	X	X				X			X							X								
888	M207	WR		20	X	X				X			X							X								
889	M208	PC	5	18	X	X				X			X							X								
890	M209	WR		18	X	X				X			X							X								
891	M210	PC	7	21	X	X				X			X							X								
892	M211	WR		21	X	X				X			X							X								
893	M212	PC	6	21	X	X				X			X							X								
894	M213	WR		21	X	X				X			X							X								
895	M214	PC	2	21	X	X				X			X							X								
896	M215	WR		21	X	X				X			X							X								
897	M216	PC	7	17	X	X				X			X							X								
898	M217	WR		17	X	X				X			X							X								
899	M218	PC	5	21	X	X				X			X							X								
900	M219	WR		21	X	X				X			X							X								
901	M220	PC	8	22	X	X				X			X							X								
902	M221	WR		22	X	X				X			X							X								
903	M222	WR		23	X	X				X			X							X								
904	M223	PC	5	22	X	X				X			X							X								
905	M224	WR		22	X	X				X			X							X								
906	M225	PC	5	20	X	X				X			X							X								
907	M226	WR		20	X	X				X			X							X								
908	M227	PC	7	21	X	X				X			X							X								
909	M228	WR		21	X	X				X			X							X								
910	M229	PC	7	21	X	X				X			X							X								
911	M230	WR		20	X	X				X			X							X								



6  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Code	Tree DBH	Palm BTH	G	F	P	D	Swk	<3'	>3'	Lwn	Weak Fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments		
912	M231	PC	6	20	X					X		X							X						X		
913	M232	WR	2	22		X				X		X			X				X							X	
914	M233	PC	3	20						X		X							X							X	
915	M234	WR	9	18						X		X							X							X	
916	M235	PC	8	23						X		X							X							X	
917	M236	WR	2	23						X		X							X							X	
918	M237	WR	9	19						X		X							X							X	
919	M238	PC	7	23						X		X							X							X	
920	M239	WR	2	23						X		X							X							X	
921	M240	PC	9	26						X		X							X							X	
922	M241	WR	6	23						X		X							X							X	
923	M242	PC	8	20						X		X							X							X	
924	M243	WR	7	26						X		X							X							X	
925	M244	PC	2	23						X		X							X							X	
926	M245	WR	9	20						X		X							X							X	
927	M246	PC	6	26						X		X							X							X	
928	M247	WR	2	23						X		X							X							X	
929	M248	PC	9	20						X		X							X							X	
930	M249	WR	7	26						X		X							X							X	
931	M250	PC	2	23						X		X							X							X	
932	M251	WR	6	20						X		X							X							X	
933	M252	WR	9	26						X		X							X							X	
934	M253	PC	7	23						X		X							X							X	
935	M254	WR	2	23						X		X							X							X	
936	M255	PC	3	25						X		X							X							X	
937	M256	WR	7	20						X		X							X							X	
938	M257	PC	4	21						X		X							X							X	
939	M258	WR	7	20						X		X							X							X	
1042	M259	WR	4	21						X		X							X							X	
1043	M260	PC	1	23						X		X							X							X	
1044	M261	WR	6	19						X		X							X							X	
1045	M262	PC	5	23						X		X							X							X	
1046	M263	WR	8	22						X		X							X							X	
1047	M264	PC	2	22						X		X							X							X	
1048	M265	WR	7	20						X		X							X							X	
1049	M266	PC	6	22						X		X							X							X	
1050	M267	WR	5	23						X		X							X							X	
1051	M268	PC	8	22						X		X							X							X	
1052	M269	WR	6	22						X		X							X							X	
1053	M270	PC	2	22						X		X							X							X	
1054	M271	WR	7	20						X		X							X							X	
1055	M272	PC	9	22						X		X							X							X	
1056	M273	WR	2	20						X		X							X							X	
1057	M274	PC	7	20						X		X							X							X	
1058	M275	WR	6	20						X		X							X							X	
1059	M276	PC	7	20						X		X							X							X	

7  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1060	M277	WR		20	X					X			X							X								
1061	M278	PC	8			X				X			X							X								
1062	M279	WR		24	X					X			X							X								
1063	M280	PC	5			X				X			X							X								
1064	M281	WR		17	X					X			X							X								
1065	M282	PC	5			X				X			X							X								
1066	M283	PC	5			X				X			X							X								
1067	M284	PC	5			X				X			X							X								
1068	M285	WR		25	X					X			X							X								
1069	M285A	WR		23	X					X			X							X								
1070	M286	PC	10			X				X			X							X								
1071	M287	WR		23	X					X			X							X								
1072	M288	PC	6			X				X			X							X								
1073	M289	WR		21	X					X			X							X								
1074	M290	PC	6			X				X			X							X								
1075	M291	WR		24	X					X			X							X								
1076	M292	PC	7			X				X			X							X								
1077	M293	WR		18	X					X			X							X								
1078	M294	PC	8			X				X			X							X								
1079	M295	WR		21	X					X			X							X								
1080	M296	PC	7			X				X			X							X								
1081	M297	WR		23	X					X			X							X								
1082	M298	WR		26	X					X			X							X								
1083	M299	PC	7			X				X			X							X								
1084	M300	WR		25	X					X			X							X								
1085	M301	PC	5			X				X			X							X								
1086	M302	WR		24	X					X			X							X								
1087	M303	PC	5			X				X			X							X								
1088	M304	WR		23	X					X			X							X								
1089	M305	PC	2			X				X			X							X								
1090	M306	WR		23	X					X			X							X								
1091	M307	WR		26	X					X			X							X								
1092	M308	PC	6			X				X			X							X								
1093	M309	WR		26	X					X			X							X								
1094	M310	PC	7			X				X			X							X								
1095	M311	WR		25	X					X			X							X								
1096	M312	PC	7			X				X			X							X								
1097	M313	WR		24	X					X			X							X								
1098	M314	PC	7			X				X			X							X								
1099	M315	WR		20	X					X			X							X								
1100	M316	PC	8			X				X			X							X								
1101	M317	WR		19	X					X			X							X								
1102	M318	PC	2			X				X			X							X								
1103	M319	WR		23	X					X			X							X								
1104	M320	PC	7			X				X			X							X								
1105	M321	WR		22	X					X			X							X								

8  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Ro/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1106	M322	PC	3			X			X			X							X								
1107	M323	WR		22	X				X			X							X								
1108	M324	PC	6		X				X			X							X								
1109	M325	WR		25	X				X			X							X								
1110	M326	PC	8		X				X			X							X								
1111	M327	WR		23	X				X			X							X								
1112	M328	PC	4		X				X			X							X								Lean
1113	M329	WR		17	X				X			X							X								
1114	M330	PC	6		X				X			X							X								
1115	M331	PC	7		X				X			X							X								
1116	M332	PC	6		X				X			X							X								
1117	M333	WR		26	X				X			X							X								
1118	M334	WR		26	X				X			X							X								
1119	M335	PC	6		X				X			X							X								
1120	M336	WR		23	X				X			X							X								
1121	M337	PC	4		X				X			X							X								
1122	M338	WR		21	X				X			X							X								
1123	M339	PC	8		X				X			X							X								
1124	M340	WR		18	X				X			X							X								
1125	M341	PC	7		X				X			X							X								
1126	M342	WR		21	X				X			X							X								
1127	M343	PC	6		X				X			X							X								
1128	M344	WR		23	X				X			X							X								Conk at base
1129	M345	WR		21	X				X			X							X								
1130	M346	WR		21	X				X			X							X								
1131	M347	PC	7		X				X			X							X								
1132	M348	WR		18	X				X			X							X								
1133	M349	WR		26	X				X			X							X								
1134	M350	PC	5		X				X			X							X								
1135	M351	WR		24	X				X			X							X								
1136	M352	PC	7		X				X			X							X								
1137	M353	WR		21	X				X			X							X								
1138	M354	PC	7		X				X			X							X								
1139	M355	WR		21	X				X			X							X								
1175	M356	WR		18	X				X			X							X								
1176	M357	PC	6		X				X			X							X								
1177	M358	WR		16	X				X			X							X								
1178	M359	PC	2		X				X			X							X								
1179	M360	WR		18	X				X			X							X								
1180	M361	PC	7		X				X			X							X								
1181	M362	WR		18	X				X			X							X								
1182	M363	PC	8		X				X			X							X								
1183	M364	WR		20	X				X			X							X								
1184	M365	PC	6		X				X			X							X								
1185	M366	WR		17	X				X			X							X								
1186	M367	PC	7		X				X			X							X								

9  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments											
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments		
1187	M368	WR				20	X						X																
1188	M369	WR				17	X						X																
1189	M370	PC	7			19	X						X																
1191	M372	PC	3			21	X						X																
1192	M373	WR	5			21	X						X																
1193	M374	PC				21	X						X																
1194	M375	WR	1			19	X						X																
1195	M376	PC				19	X						X																
1196	M377	WR	7			18	X						X																
1197	M378	PC				22	X						X																
1198	M379	WR	8			19	X						X																
1199	M380	PC				22	X						X																
1200	M381	WR	6			19	X						X																
1201	M382	PC				24	X						X																
1202	M383	WR	6			24	X						X																
1203	M384	WR				24	X						X																
1204	M385	PC				24	X						X																
1205	M386	WR	5			24	X						X																
1206	M387	PC				24	X						X																
1207	M388	WR	4			23	X						X																
1208	M389	PC				20	X						X																
1209	M390	WR	7			18	X						X																
1140	M391	WR				17	X						X																
1141	M392	PC				19	X						X																
1142	M393	WR	7			20	X						X																
1143	M394	PC				17	X						X																
1144	M395	WR	6			19	X						X																
1145	M396	PC				20	X						X																
1146	M397	WR	8			20	X						X																
1147	M398	PC				19	X						X																
1148	M399	WR	7			19	X						X																
1149	M400	PC				20	X						X																
1150	M401	WR	5			20	X						X																
1151	M402	PC				20	X						X																
1152	M403	WR	6			17	X						X																
1153	M404	PC				20	X						X																
1154	M405	WR	3			21	X						X																
1155	M406	WR	8			16	X						X																
1156	M407	PC				17	X						X																
1157	M408	WR	4			17	X						X																
1158	M409	PC				16	X						X																
1159	M410	WR	6			17	X						X																
1160	M411	PC				17	X						X																
1161	M412	WR				17	X						X																
1162	M413	PC	4			17	X						X																

10  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Ro/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1163	M414	WR		19	X								X							X								
1164	M415	PC	5			X				X		X	X							X								
1165	M416	WR		19	X					X		X	X							X								
1166	M417	PC	5			X				X		X	X							X								
1167	M418	WR		22	X					X		X	X							X								
1168	M419	PC	8			X						X	X							X								
1169	M420	WR		23	X					X		X	X							X								
1170	M421	WR		24	X					X		X	X							X								
1171	M422	PC	9			X				X		X	X							X								
1172	M423	WR		17	X					X		X	X							X								
1173	M424	PC	6			X				X		X	X							X								
1174	M425	WR		19	X					X		X	X							X								
1290	M426	WR		20	X					X		X	X							X								
1291	M427	PC	6			X				X		X	X							X								
1292	M428	WR		17	X					X		X	X							X								
1293	M429	PC	6			X				X		X	X							X								
1294	M430	WR		17	X					X		X	X							X								
1295	M431	PC	7			X				X		X	X							X								
1296	M432	WR		22	X					X		X	X							X								
1297	M433	PC	5			X				X		X	X							X								
1298	M434	WR		23	X					X		X	X							X								
1299	M435	PC	6			X				X		X	X							X								
1300	M436	WR		22	X					X		X	X							X								
1301	M437	PC	6			X				X		X	X							X								
1302	M438	WR		24	X					X		X	X							X								
1303	M439	PC	7			X				X		X	X							X								
1304	M440	WR		21	X					X		X	X							X								
1305	M441	WR		25	X					X		X	X							X								
1306	M442	PC	6			X				X		X	X							X								
1307	M443	WR		19	X					X		X	X							X								
1308	M444	PC	6			X				X		X	X							X								
1309	M445	WR		21	X					X		X	X							X								
1310	M446	PC	7			X				X		X	X							X								
1311	M447	WR		20	X					X		X	X							X								
1312	M448	PC	6			X				X		X	X							X								
1313	M449	WR		23	X					X		X	X							X								
1314	M450	PC	7			X				X		X	X							X								
1315	M451	WR		23	X					X		X	X							X								
1316	M452	PC	7			X				X		X	X							X								
1317	M453	WR		23	X					X		X	X							X								
1318	M454	PC	5			X				X		X	X							X								
1319	M455	WR		22	X					X		X	X							X								
1320	M456	WR		22	X					X		X	X							X								
1321	M457	PC	6			X				X		X	X							X								
1322	M458	WR		19	X					X		X	X							X								
1323	M459	PC	5			X				X		X	X							X								

11  
 11/14/12

## Tree Inventory East Palomar Street

## Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1324	M1460	WR				23	X						X							X								
1325	M1461	PC		5			X						X			X												
1326	M1462	WR		5			X						X			X												
1327	M1463	PC		5			X						X			X												
1328	M1464	WR		9			X						X			X												
1329	M1465	PC		9			X						X			X												
1330	M1466	WR		20			X						X			X												
1331	M1467	PC		5			X						X			X												
1332	M1468	WR		24			X						X			X												
1333	M1469	PC		7			X						X			X												
1334	M1470	WR		20			X						X			X												
1335	M1471	WR		26			X						X			X												
1336	M1472	PC		7			X						X			X												
1337	M1473	WR		7			X						X			X												
1338	M1474	PC		8			X						X			X												
1339	M1475	WR		23			X						X			X												
1340	M1476	PC		6			X						X			X												
1341	M1477	WR		20			X						X			X												
1342	M1478	PC		4			X						X			X												
1343	M1479	WR		23			X						X			X												
1344	M1480	PC		7			X						X			X												
1345	M1481	WR		21			X						X			X												
1346	M1482	PC		8			X						X			X												
1347	M1483	WR		20			X						X			X												
1348	M1484	PC		7			X						X			X												
1349	M1485	WR		26			X						X			X												
1350	M1486	WR		25			X						X			X												
1351	M1487	PC		5			X						X			X												
1352	M1488	WR		23			X						X			X												
1353	M1489	PC		4			X						X			X												
1354	M1490	WR		21			X						X			X												
1355	M1491	PC		4			X						X			X												
1356	M1492	WR		24			X						X			X												
1357	M1493	PC		5			X						X			X												
1358	M1494	WR		21			X						X			X												
1359	M1495	PC		5			X						X			X												
1360	M1496	WR		23			X						X			X												
1361	M1497	PC		6			X						X			X												
1362	M1498	WR		22			X						X			X												
1363	M1499	PC		5			X						X			X												
1364	M1500	WR		23			X						X			X												
1365	M1501	WR		22			X						X			X												
1366	M1502	PC		7			X						X			X												
1367	M1503	WR		19			X						X			X												
1368	M1504	PC		5			X						X			X												
1369	M1505	WR		23			X						X			X												

12  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Photo #	Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1210	M506	WR		21		X							X						X									
1211	M507	PC	7	21		X				X	X	X							X									
1212	M508	WR		21		X				X	X	X							X									
1213	M509	PC	7	23		X				X	X	X							X									
1214	M510	WR		23		X				X	X	X							X									
1215	M511	PC	6	22		X				X	X	X							X									
1216	M512	WR		22		X				X	X	X							X									
1217	M513	PC	6	23		X				X	X	X							X									
1218	M514	WR		23		X				X	X	X							X									
1219	M515	PC	5	21		X				X	X	X							X									
1220	M516	WR		21		X				X	X	X							X									
1221	M517	PC	5	23		X				X	X	X							X									
1222	M518	WR		23		X				X	X	X							X									
1223	M519	WR		19		X				X	X	X							X									
1224	M520	PC	6	19		X				X	X	X							X									
1225	M521	WR		19		X				X	X	X							X									
1226	M522	PC	5	19		X				X	X	X							X									
1227	M523	WR		19		X				X	X	X							X									
1228	M524	PC	6	20		X				X	X	X							X									
1229	M525	WR		20		X				X	X	X							X									
1230	M526	PC	7	21		X				X	X	X							X									
1231	M527	WR		21		X				X	X	X							X									
1232	M528	PC	6	22		X				X	X	X							X									
1233	M529	WR		22		X				X	X	X							X									
1234	M530	PC	6	20		X				X	X	X							X									
1235	M531	WR		20		X				X	X	X							X									
1236	M532	PC	6	22		X				X	X	X							X									
1237	M533	WR		22		X				X	X	X							X									
1238	M534	WR		23		X				X	X	X							X									
1239	M535	PC	7	22		X				X	X	X							X									
1240	M536	WR		22		X				X	X	X							X									
1241	M537	PC	4	22		X				X	X	X							X									
1242	M538	WR		23		X				X	X	X							X									
1243	M539	PC	9	19		X				X	X	X							X									
1244	M540	WR		19		X				X	X	X							X									
1245	M541	PC	6	22		X				X	X	X							X									
1246	M542	WR		22		X				X	X	X							X									
1247	M543	PC	6	21		X				X	X	X							X									
1248	M544	WR		21		X				X	X	X							X									
1249	M545	PC	5	21		X				X	X	X							X									
1250	M546	WR		21		X				X	X	X							X									
1251	M547	PC	5	22		X				X	X	X							X									
1252	M548	WR		23		X				X	X	X							X									
1253	M549	WR		23		X				X	X	X							X									
1254	M550	PC	8	21		X				X	X	X							X									
1255	M551	WR		21		X				X	X	X							X									

13  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Code	Tree DBH	Palm BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1256	M552	PC	6		X	X	X	X	X	X	X	X			X				X								
1257	M553	WR		21	X	X	X	X	X	X	X	X															
1258	M554	PC	6		X	X	X	X	X	X	X	X															
1259	M555	WR		21	X	X	X	X	X	X	X	X															
1260	M556	PC	5		X	X	X	X	X	X	X	X			X												
1261	M557	WR		22	X	X	X	X	X	X	X	X															
1262	M558	PC	5		X	X	X	X	X	X	X	X															
1263	M559	WR		20	X	X	X	X	X	X	X	X															
1264	M560	PC	6		X	X	X	X	X	X	X	X															
1265	M561	WR		23	X	X	X	X	X	X	X	X															
1266	M562	PC	6		X	X	X	X	X	X	X	X			X												
1267	M563	WR		22	X	X	X	X	X	X	X	X															
1268	M564	WR		22	X	X	X	X	X	X	X	X															
1269	M565	PC	6		X	X	X	X	X	X	X	X															
1270	M566	WR		20	X	X	X	X	X	X	X	X															
1271	M567	PC	5		X	X	X	X	X	X	X	X															
1272	M568	WR		20	X	X	X	X	X	X	X	X			X												
1273	M569	PC	5		X	X	X	X	X	X	X	X															
1274	M570	WR		20	X	X	X	X	X	X	X	X			X												
1275	M571	PC	6		X	X	X	X	X	X	X	X			X												
1276	M572	WR		19	X	X	X	X	X	X	X	X															
1277	M573	PC	6		X	X	X	X	X	X	X	X			X												
1278	M574	WR		22	X	X	X	X	X	X	X	X															
1279	M575	PC	8		X	X	X	X	X	X	X	X															
1280	M576	WR		23	X	X	X	X	X	X	X	X															
1281	M577	PC	7		X	X	X	X	X	X	X	X			X												
1282	M578	WR		23	X	X	X	X	X	X	X	X															
1283	M579	WR		24	X	X	X	X	X	X	X	X															
1284	M580	PC	7		X	X	X	X	X	X	X	X															
1285	M581	WR		21	X	X	X	X	X	X	X	X															
1286	M582	PC	8		X	X	X	X	X	X	X	X															
1287	M583	WR		19	X	X	X	X	X	X	X	X															
1288	M584	PC	1		X	X	X	X	X	X	X	X			X												
1289	M585	WR		21	X	X	X	X	X	X	X	X															
1290	M586	WR		22	X	X	X	X	X	X	X	X															
1371	M587	PC	9		X	X	X	X	X	X	X	X															
1372	M588	WR		21	X	X	X	X	X	X	X	X															
1373	M589	PC	7		X	X	X	X	X	X	X	X															
1374	M590	WR		24	X	X	X	X	X	X	X	X															
1375	M591	PC	6		X	X	X	X	X	X	X	X															
1376	M592	WR		24	X	X	X	X	X	X	X	X															
1377	M593	PC	6		X	X	X	X	X	X	X	X			X												
1378	M594	WR		23	X	X	X	X	X	X	X	X															
1379	M595	PC	8		X	X	X	X	X	X	X	X			X												
1380	M596	WR		22	X	X	X	X	X	X	X	X															
1381	M597	PC	7		X	X	X	X	X	X	X	X			X												



14  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments													
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swik	<3'	>3'	L	W	N	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments		
1382	M 598	WR	25			X						X										X									
1383	M 599	PC	5			X						X																			
1384	M 600	WR	24			X						X																			
1385	M 601	PC	6			X						X																			
1386	M 602	WR	25			X						X																			
1387	M 603	WR	25			X						X																			
1388	M 604	PC	7			X						X																			
1389	M 605	WR	25			X						X																			
1390	M 606	PC	6			X						X																			
1391	M 607	WR	23			X						X																			
1392	M 608	PC	6			X						X																			
1393	M 609	WR	22			X						X																			
1394	M 610	PC	5			X						X																			
1395	M 611	WR	22			X						X																			
1396	M 612	PC	5			X						X																			
1397	M 613	WR	24			X						X																			
1398	M 614	PC	4			X						X																			
1399	M 615	WR	25			X						X																			
1400	M 616	WR	24			X						X																			
1401	M 617	PC	3			X						X																			
1402	M 618	WR	23			X						X																			
1403	M 619	PC	7			X						X																			
1404	M 620	WR	21			X						X																			
1405	M 621	PC	6			X						X																			
1406	M 622	WR	26			X						X																			
1407	M 623	WR	26			X						X																			
1408	M 624	PC	8			X						X																			
1409	M 625	WR	23			X						X																			
1410	M 626	PC	7			X						X																			
1411	M 627	WR	19			X						X																			
1412	M 628	PC	4			X						X																			
1413	M 629	PC	8			X						X																			
1414	M 630	WR	24			X						X																			
1415	M 631	PC	5			X						X																			
1416	M 632	WR	24			X						X																			
1417	M 633	PC	7			X						X																			
1418	M 634	WR	25			X						X																			
1419	M 635	PC	3			X						X																			
1420	M 636	WR	24			X						X																			
1421	M 637	PC	8			X						X																			
1422	M 638	WR	25			X						X																			
1423	M 639	PC	6			X						X																			
1424	M 640	WR	26			X						X																			
1425	M 641	WR	26			X						X																			
1426	M 642	PC	9			X						X																			
1427	M 643	WR	24			X						X																			

Trk damage at base

X

15  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planning Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1428	M1644	PC	7			X							X							X								
1429	M1645	WR	24	X		X							X															
1430	M1646	PC	5	X		X							X				X											
1431	M1647	PC	4	X		X							X				X											
1432	M1648	WR	25	X		X							X				X											
1433	M1649	PC	6	X		X							X				X											
1434	M1650	WR	24	X		X							X				X											
1435	M1651	PC	7	X		X							X				X											
1436	M1652	WR	23	X		X							X				X											
1437	M1653	PC	1	X		X							X				X											
1438	M1654	WR	18	X		X							X				X											
1439	M1655	PC	4	X		X							X				X											
1440	M1656	WR	25	X		X							X				X											
1441	M1657	PC	4	X		X							X				X											
1442	M1658	WR	24	X		X							X				X											
1443	M1659	PC	8	X		X							X				X											
1444	M1660	WR	25	X		X							X				X											
1445	M1661	PC	10	X		X							X				X											
1446	M1662	WR	24	X		X							X				X											
1447	M1663	PC	10	X		X							X				X											
1448	M1664	WR	27	X		X							X				X											
1449	M1665	PC	7	X		X							X				X											
1450	M1666	PC	8	X		X							X				X											
1451	M1667	WR	23	X		X							X				X											
1452	M1668	PC	1	X		X							X				X											
1453	M1669	WR	21	X		X							X				X											
1454	M1670	PC	7	X		X							X				X											
1455	M1671	WR	23	X		X							X				X											
1456	M1672	PC	9	X		X							X				X											
1457	M1673	WR	21	X		X							X				X											
1458	M1674	PC	8	X		X							X				X											
1459	M1675	WR	26	X		X							X				X											
1460	M1676	PC	6	X		X							X				X											
1461	M1677	WR	25	X		X							X				X											
1462	M1678	PC	8	X		X							X				X											
1463	M1679	WR	23	X		X							X				X											
1464	M1680	PC	8	X		X							X				X											
1465	M1681	WR	23	X		X							X				X											
1466	M1682	PC	7	X		X							X				X											
1467	M1683	WR	26	X		X							X				X											
1468	M1684	PC	6	X		X							X				X											
1469	M1685	WR	21	X		X							X				X											
1470	M1686	PC	4	X		X							X				X											
1471	M1687	WR	26	X		X							X				X											
1472	M1688	WR	27	X		X							X				X											
1473	M1689	PC	2	X		X							X				X											

 Conks at base  
 Thin trk, planted high

16  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
1474	M1690	WR											X															
1475	M1691	PC	6	23	X								X															
1476	M1692	WR	6	23	X								X															
1477	M1693	PC	6	24	X								X															
1478	M1694	WR	4	24	X								X															
1479	M1695	PC							X																			
1480	M1696	WR	6	27	X								X															
1481	M1697	PC	8	25	X								X															
1482	M1698	WR											X															
1483	M1699	PC											X															
1484	M1700	WR											X															
1485	M1701	WR	6	18	X								X															
1486	M1702	PC	6	23	X								X															
1487	M1703	WR	6	20	X								X															
1488	M1704	PC							X																			
1489	M1705	WR	6	22	X								X															
1490	M1706	PC											X															
1491	M1707	WR	6	26	X								X															
1492	M1708	PC											X															
1493	M1709	WR											X															
1494	M1710	WR											X															
1495	M1711	WR											X															
1496	M1712	WR											X															
1497	M1713	WR											X															
1498	M1714	WR											X															
1499	M1715	WR											X															
1500	M1716	WR											X															
1501	M1717	WR											X															
1502	M1718	WR											X															
1503	M1719	WR											X															
1504	M1720	WR											X															
1505	M1721	WR											X															
1506	M1722	WR											X															
1507	M1723	WR											X															
1508	M1724	WR											X															
1509	M1725	WR											X															
1510	M1726	WR											X															
1511	M1727	WR											X															
1512	M1728	WR											X															
1513	M1729	WR											X															
1514	M1730	WR											X															
1515	M1731	WR											X															
1516	M1732	WR											X															
1517	M1733	WR											X															
1518	M1734	WR											X															
1519	M1735	WR											X															

17  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments												
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swk	<-3'	>-3'	Lwn	Weak Fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Girdled	Ants	Snails	Comments			
1820	M736	WR		25	X																									
1821	M737	WR		29	X																									
1822	M738	WR		25	X																									
1823	M739	WR		21	X																									
1824	M740	WR		22	X																									
1825	M741	WR		23	X																									
1826	M742	WR		25	X																									
1827	M743	WR		19	X																									
1828	M744	WR		21	X																									
1829	M745	WR		26	X																									
1830	M746	WR		27	X																									
1831	M747	WR		27	X																									
1832	M748	WR		28	X																									
1833	M749	WR		23	X																									
1834	M750	WR		22	X																									
1835	M751	WR		21	X																									
1836	M752	WR		25	X																									
1837	M753	WR		21	X																									
1838	M754	WR		21	X																									
1839	M755	WR		21	X																									
1840	M756	WR		22	X																									
1841	M757	WR		21	X																									
1842	M758	WR		21	X																									
1843	M759	WR		20	X																									
1844	M760	WR		21	X																									
1845	M761	WR		20	X																									
1846	M762	WR		23	X																									
1847	M763	WR		23	X																									
1848	M764	WR		24	X																									
1849	M765	WR		27	X																									
1850	M766	WR		21	X																									
1851	M767	WR		23	X																									
1852	M768	WR		26	X																									
1853	M769	WR		26	X																									
1854	M770	WR		25	X																									
56	SP 1	KB																												
55	SP 2	KB		8																										
54	SP 3	KB		7																										
53	SP 4	KB		5																										
52	SP 5	KB		5																										
51	SP 6	KB		6																										
50	SP 7	KB		7																										
49	SP 8	KB		3																										
48	SP 9	KB		8																										
47	SP 10	KB		7																										

18  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition		Planting Location			Conditions				Maintenance Needs				Comments											
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
46	SP 11	KB	7			X					X	X	X															
45	SP 12	KB	11			X					X	X	X															
44	SP 13	KB	10			X					X	X	X															
43	SP 14	KB	10			X					X	X	X															
42	SP 15	KB	12			X					X	X	X															
41	SP 16	KB	10			X					X	X	X															
40	SP 17	KB	11			X					X	X	X															
39	SP 18	KB	6			X					X	X	X															
38	SP 19	KB	4			X					X	X	X															
37	SP 20	KB	6			X					X	X	X															
36	SP 21	KB	5			X					X	X	X															
35	SP 22	KB	12			X					X	X	X															
34	SP 23	KB	9			X					X	X	X															
33	SP 24	KB	11			X					X	X	X															
32	SP 25	KB	8			X					X	X	X															
31	SP 26	KB	8			X					X	X	X															
30	SP 27	KB	11			X					X	X	X															
29	SP 28	KB	4			X					X	X	X															
28	SP 29	KB	1			X					X	X	X															
27	SP 30	KB	5			X					X	X	X															
26	SP 31	KB	1			X					X	X	X															
25	SP 32	KB	1			X					X	X	X															
24	SP 33	KB	2			X					X	X	X															
23	SP 34	KB	6			X					X	X	X															
22	SP 35	KB	1			X					X	X	X															
21	SP 36	KB	9			X					X	X	X															
20	SP 37	KB	11			X					X	X	X															
19	SP 38	KB	8			X					X	X	X															
18	SP 39	KB	10			X					X	X	X															
17	SP 40	KB	9			X					X	X	X															
16	SP 41	KB	11			X					X	X	X															
122	SP 42	KB	10			X					X	X	X															
123	SP 43	KB	4			X					X	X	X															
124	SP 44	KB	8			X					X	X	X															
125	SP 45	KB	1			X					X	X	X															
126	SP 46	KB	8			X					X	X	X															
127	SP 47	KB	8			X					X	X	X															
128	SP 48	KB	12			X					X	X	X															
129	SP 49	KB	8			X					X	X	X															
130	SP 50	KB	12			X					X	X	X															
131	SP 51	PC	7			X					X	X	X															
132	SP 52	PC	8			X					X	X	X															
133	SP 53	PC	8			X					X	X	X															
134	SP 54	PC	7			X					X	X	X															
135	SP 55	PC	4			X					X	X	X															
136	SP 56	PC	6			X					X	X	X															

19  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments								
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	S	W	L	S	W	R	C	R	R	R	Over watered	Trunk Girdled	Ants	Snails	Comments	
						<3'	>3'	L	W		Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.						
137	SP157	PC	2			X				X											X				
138	SP158	WR	25			X				X															Tree lean not correcting
139	SP159	PC	5			X				X															
140	SP160	PC	7			X				X															
141	SP161	PC	4			X				X															
142	SP162	WR	23			X				X															
143	SP163	PC	5			X				X															
144	SP164	PC	6			X				X															
145	SP165	PC	3			X				X															
146	SP166	PC	5			X				X															
147	SP167	WR	23			X				X															
148	SP168	PC	7			X				X															
149	SP169	PC	8			X				X															
150	SP170	PC	2			X				X															
151	SP171	WR	23			X				X															
152	SP172	PC	6			X				X															
153	SP173	PC	5			X				X															
154	SP174	PC	7			X				X															
155	SP175	WR	22			X				X															
156	SP176	PC	7			X				X															
157	SP177	PC	6			X				X															
158	SP178	PC	3			X				X															
159	SP179	WR	24			X				X															
160	SP180	PC	7			X				X															
161	SP181	PC	7			X				X															
229	SP182	PC	3			X				X															
230	SP183	PC	8			X				X															
231	SP184	WR	23			X				X															
232	SP185	PC	8			X				X															
233	SP186	PC	8			X				X															
234	SP187	WR	22			X				X															
235	SP188	PC	8			X				X															
236	SP189	PC	9			X				X															
237	SP190	PC	6			X				X															
238	SP191	WR	23			X				X															
239	SP192	PC	5			X				X															
240	SP193	PC	8			X				X															
241	SP194	PC	8			X				X															
242	SP195	WR	22			X				X															
243	SP196	PC	7			X				X															
244	SP197	PC	7			X				X															
245	SP198	PC	8			X				X															
246	SP199	WR	25			X				X															
247	SP100	PC	6			X				X															
248	SP101	PC	8			X				X															
249	SP102	PC	8			X				X															

20  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBRT

Tree Information			Tree Condition		Planting Location			Conditions				Maintenance Needs				Comments													
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak Fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Overwatered	Trunk Girdled	Ants	Snails	Comments		
250	SP103	WR				24	X						X							X									
251	SP104	PC	7				X						X																Conk at base
252	SP105	PC	10				X						X																
253	SP106	PC	9				X						X																
254	SP107	WR				23	X						X								X								
255	SP108	PC	9				X						X																
256	SP109	PC	7				X						X																
257	SP110	PC	8				X						X																
258	SP111	PC	8				X						X																
259	SP112	PC	8				X						X																
260	SP113	PC	7				X						X																
261	SP114	WR				22	X						X								X								
262	SP115	PC	7				X						X																
263	SP116	PC	7				X						X																
264	SP117	PC	5				X						X																
265	SP118	PC	1				X						X																
266	SP119	WR				24	X						X								X								
267	SP120	WR				26	X						X																
269	SP121	PC	4				X						X																
270	SP122	PC	1				X						X																
271	SP123	WR				25	X						X																
272	SP124	PC	6				X						X																
273	SP125	PC	3				X						X																
274	SP126	PC	4				X						X																
275	SP127	WR				24	X						X																
276	SP128	PC	3				X						X																
277	SP129	PC	4				X						X																
278	SP130	PC	2				X						X																
279	SP131	WR				24	X						X																
280	SP132	PC	3				X						X																
281	SP133	PC	3				X						X																
282	SP134	PC	3				X						X																
283	SP135	WR				25	X						X																
284	SP136	PC	2				X						X																
285	SP137	PC	2				X						X																
286	SP138	PC	3				X						X																
287	SP139	WR				22	X						X																
288	SP140	PC	6				X						X																
289	SP141	PC	4				X						X																
290	SP142	PC	2				X						X																
291	SP143	WR				23	X						X																
292	SP144	PC	5				X						X																
293	SP145	PC	6				X						X																
294	SP146	PC	5				X						X																
295	SP147	WR				23	X						X																
296	SP148	PC	5				X						X																

21  
 11/14/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments											
Photo #	Tree #	Code	Tree DBH	Tree	Palm	BTH	G	F	P	D	Swlk <3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Overwatered	Trunk Gridled	Ants	Snails	Comments		
297	SP149	PC	1				X				X	X				X							X						
418	SP147B	PG	8				X				X	X																	
419	SP148B	PG	10				X				X	X																	
420	SP150A	PC	4				X				X	X																	
421	SP150	PC	7				X				X	X																	
422	SP151	PC	7				X				X	X																	
423	SP152	WR	17				X				X	X																	
424	SP153	PC	4				X				X	X																	
425	SP154A	PC	5				X				X	X																	
426	SP154	PC	6				X				X	X																	
427	SP155	WR	17				X				X	X																	
428	SP156	PC	5				X				X	X																	
429	SP157	PC	2				X				X	X																	
430	SP158	PC	3				X				X	X																	
431	SP159	WR	15				X				X	X																	
432	SP160	PC	1				X				X	X																	
433	SP161	PC	1				X				X	X																	
434	SP162	PC	1				X				X	X																	
435	SP163	WR	18				X				X	X																	
436	SP164	PC	5				X				X	X																	
437	SP165	PC	5				X				X	X																	
438	SP166	PC	5				X				X	X																	
439	SP167	WR	24				X				X	X																	
440	SP168	PC	7				X				X	X																	
441	SP169	PC	3				X				X	X																	
442	SP170	PC	4				X				X	X																	
443	SP171	WR	20				X				X	X																	
444	SP172	PC	1				X				X	X																	
445	SP173	PC	1				X				X	X																	
446	SP174	PC	1				X				X	X																	
447	SP175	WR	21				X				X	X																	
448	SP176	PC	6				X				X	X																	
449	SP177	PC	4				X				X	X																	
450	SP178	PC	3				X				X	X																	
451	SP179	WR	21				X				X	X																	
452	SP180	PC	6				X				X	X																	
453	SP181	PC	6				X				X	X																	
454	SP182	PC	7				X				X	X																	
455	SP183	WR	23				X				X	X																	
456	SP184	PC	3				X				X	X																	
457	SP185	PC	3				X				X	X																	
458	SP186	PC	6				X				X	X																	
459	SP187	PC	6				X				X	X																	
460	SP188	PC	2				X				X	X																	
461	SP189	PC	1				X				X	X																	
SP190																													Not used



22  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments											
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swlk <=3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments		
SP 191			Not used																									
SP 192			Not used																									
SP 193			Not used																									
SP 194			Not used																									
SP 195			Not used																									
SP 196			Not used																									
SP 197			Not used																									
SP 200		PC	5			X				X	X																	
SP 201		PC	6			X				X	X																	
SP 202		PC	3			X				X	X																	
SP 203		PC	4			X				X	X																	
SP 204		PC	5			X				X	X																	
SP 205		PC	2			X				X	X																	
SP 206		PC	5			X				X	X																	
SP 207		PC	6			X				X	X																	
SP 208		PC	1			X				X	X																	
SP 209		PC	4			X				X	X																	
SP 210		PC	4			X				X	X																	
SP 211		PC	6			X				X	X																	
SP 212		PC	4			X				X	X																	
SP 213		PC	4			X				X	X																	
SP 214		PC	6			X				X	X																	
SP 215		PC	6			X				X	X																	
SP 216		PC	3			X				X	X																	
SP 217		PC	3			X				X	X																	
SP 218		PC	5			X				X	X																	
SP 219		PC	6			X				X	X																	
SP 220		PC	3			X				X	X																	
SP 221		PC	3			X				X	X																	
SP 222		PC	5			X				X	X																	
SP 223		PC	7			X				X	X																	
SP 224		PC	1			X				X	X																	
SP 225		PC	5			X				X	X																	
SP 226		PC	5			X				X	X																	
SP 227		PC	5			X				X	X																	
SP 228		PC	4			X				X	X																	
SP 229		PC	1			X				X	X																	
SP 230		PC	5			X				X	X																	
SP 231		PC	7			X				X	X																	
SP 232		PC	3			X				X	X																	
SP 233		PC	2			X				X	X																	
SP 234		PC	5			X				X	X																	
SP 235		PC	3			X				X	X																	
SP 236		PC	6			X				X	X																	
SP 237		PC	5			X				X	X																	
SP 238		PC	1			X				X	X																	

23  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Ro/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
501	SP1239	PC	2			X							X															
502	SP1240	PC	1			X							X															
503	SP1241	PC	6			X							X															
504	SP1242	PC	5			X							X															
505	SP1243	PC	2			X							X															
506	SP1244	PC	2			X							X															
507	SP1245	PC	5			X							X															
508	SP1246	PC	4			X							X															
509	SP1247	PC	3			X							X															
510	SP1248	PC	1			X							X															
511	SP1249	PC	7			X							X															
512	SP1250	PC	1			X							X															
598	SP1251	PC	7			X							X															
599	SP1252	PC	1			X							X															
600	SP1253	PC	5			X							X															
601	SP1254	PC	1			X							X															
602	SP1255	PC	6			X							X															
603	SP1256	PC	5			X							X															
604	SP1257	PC	5			X							X															
605	SP1258	PC	5			X							X															
606	SP1259	PC	6			X							X															
607	SP1260	PC	6			X							X															
608	SP1261	PC	7			X							X															
609	SP1262	PC	1			X							X															
610	SP1263	PC	1			X							X															
611	SP1264	PC	6			X							X															
612	SP1265	PC	6			X							X															
613	SP1266	PC	1			X							X															
614	SP1267	PC	4			X							X															
615	SP1268	PC	6			X							X															
616	SP1269	PC	6			X							X															
617	SP1270	PC	5			X							X															
618	SP1271	PC	1			X							X															
619	SP1272	PC	5			X							X															
620	SP1273	PC	5			X							X															
621	SP1274	PC	1			X							X															
622	SP1275	PC	5			X							X															
623	SP1276	PC	5			X							X															
624	SP1277	PC	4			X							X															
625	SP1278	PC	1			X							X															
626	SP1279	PC	6			X							X															
627	SP1280	PC	5			X							X															
628	SP1281	PC	4			X							X															
629	SP1282	PC	4			X							X															
630	SP1283	PC	4			X							X															
631	SP1284	PC	5			X							X															

24  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments						
Photo #	Tree #	Code	Tree DBH	Palm	BTH	G	F	P	D	S	W	L	W	W	W	C	R	R	R	Over watered	Trunk Girdled	Ants	Snails	Comments
632	SP 285	PC	3			X	X	X	X	X	X	X	X	X	X							X		
633	SP 286	PC	3			X	X	X	X	X	X	X	X	X	X							X		
634	SP 287	PC	5			X	X	X	X	X	X	X	X	X	X							X		
635	SP 288	PC	5			X	X	X	X	X	X	X	X	X	X							X		
636	SP 289	PC	7			X	X	X	X	X	X	X	X	X	X							X		
637	SP 290	PC	6			X	X	X	X	X	X	X	X	X	X							X		
638	SP 291	PC	1			X	X	X	X	X	X	X	X	X	X							X		
639	SP 292	PC	1			X	X	X	X	X	X	X	X	X	X							X		
640	SP 293	PC	7			X	X	X	X	X	X	X	X	X	X							X		
641	SP 294	PC	7			X	X	X	X	X	X	X	X	X	X							X		
642	SP 295	PC	2			X	X	X	X	X	X	X	X	X	X							X		
643	SP 296	PC	4			X	X	X	X	X	X	X	X	X	X							X		
644	SP 297	PC	4			X	X	X	X	X	X	X	X	X	X							X		
645	SP 298	PC	5			X	X	X	X	X	X	X	X	X	X							X		
646	SP 299	PC	8			X	X	X	X	X	X	X	X	X	X							X		
647	SP 300	PC	4			X	X	X	X	X	X	X	X	X	X							X		
648	SP 301	PC	6			X	X	X	X	X	X	X	X	X	X							X		
649	SP 302	PC	5			X	X	X	X	X	X	X	X	X	X							X		
650	SP 303	PC	4			X	X	X	X	X	X	X	X	X	X							X		
651	SP 304	PC	5			X	X	X	X	X	X	X	X	X	X							X		
652	SP 305	PC	5			X	X	X	X	X	X	X	X	X	X							X		
653	SP 306	PC	5			X	X	X	X	X	X	X	X	X	X							X		
654	SP 307	PC	8			X	X	X	X	X	X	X	X	X	X							X		
655	SP 308	PC	7			X	X	X	X	X	X	X	X	X	X							X		
656	SP 309	PC	5			X	X	X	X	X	X	X	X	X	X							X		
657	SP 310	PC	5			X	X	X	X	X	X	X	X	X	X							X		
658	SP 311	PC	8			X	X	X	X	X	X	X	X	X	X							X		
659	SP 312	PC	6			X	X	X	X	X	X	X	X	X	X							X		
660	SP 313	PC	1			X	X	X	X	X	X	X	X	X	X							X		
661	SP 314	PC	Removed			X	X	X	X	X	X	X	X	X	X							X		
662	SP 315	PC	1			X	X	X	X	X	X	X	X	X	X							X		
663	SP 316	PC	7			X	X	X	X	X	X	X	X	X	X							X		
664	SP 317	PC	5			X	X	X	X	X	X	X	X	X	X							X		
665	SP 318	PC	5			X	X	X	X	X	X	X	X	X	X							X		
666	SP 319	PC	5			X	X	X	X	X	X	X	X	X	X							X		
667	SP 320	PC	1			X	X	X	X	X	X	X	X	X	X							X		
668	SP 321	PC	5			X	X	X	X	X	X	X	X	X	X							X		
669	SP 322	PC	5			X	X	X	X	X	X	X	X	X	X							X		
670	SP 323	PC	5			X	X	X	X	X	X	X	X	X	X							X		
671	SP 324	PC	5			X	X	X	X	X	X	X	X	X	X							X		
672	SP 325	PC	6			X	X	X	X	X	X	X	X	X	X							X		
673	SP 326	PC	1			X	X	X	X	X	X	X	X	X	X							X		
674	SP 327	PC	4			X	X	X	X	X	X	X	X	X	X							X		
675	SP 328	PC	6			X	X	X	X	X	X	X	X	X	X							X		
676	SP 329	PC	5			X	X	X	X	X	X	X	X	X	X							X		
677	SP 330	PC	5			X	X	X	X	X	X	X	X	X	X							X		Fireblight



26  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments											
Photo #	Tree #	Code	Tree DBH	Tree Palm	BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
723	SP 377	PC	3			X						X	X			X												Lean
724	SP 378	PC	5			X						X	X			X								X				Standing water
725	SP 379	PC	5			X						X	X			X												Standing water
726	SP 380	PC	3			X						X	X			X												
727	SP 381	PC	2			X						X	X			X												
728	SP 382	PC	6			X						X	X			X												
729	SP 383	PC	4			X						X	X			X												
730	SP 384	PC	8			X						X	X			X												
731	SP 385	PC	6			X						X	X			X												
732	SP 386	PC	6			X						X	X			X												
733	SP 387	PC	7			X						X	X			X												
734	SP 388	PC	7			X						X	X			X												
735	SP 389	PC	6			X						X	X			X												
736	SP 390	PC	5			X						X	X			X												
737	SP 391	PC	10			X						X	X			X												
738	SP 392	PC	6			X						X	X			X												
739	SP 393	PC	1			X						X	X			X												
740	SP 394	PC	5			X						X	X			X												
741	SP 395	PC	6			X						X	X			X												
742	SP 396	PC	2			X						X	X			X												
743	SP 397	PC	6			X						X	X			X												
744	SP 398	PC	5			X						X	X			X												
745	SP 399	PC	5			X						X	X			X												
746	SP 400	PC	5			X						X	X			X												
747	SP 401	PC	1			X						X	X			X												
748	SP 402	PC	6			X						X	X			X												
749	SP 403	PC	5			X						X	X			X												
750	SP 404	PC	5			X						X	X			X												
751	SP 405	PC	5			X						X	X			X												
752	SP 406	PC	1			X						X	X			X												
753	SP 407	PC	5			X						X	X			X												
754	SP 408	PC	5			X						X	X			X												
755	SP 409	PC	5			X						X	X			X												
756	SP 410	PC	1			X						X	X			X												
58	NP 1	KB	5			X						X	X			X												
59	NP 2	KB	6			X						X	X			X												
60	NP 3	KB	3			X						X	X			X												
61	NP 4	KB	2			X						X	X			X												
62	NP 5	KB	3			X						X	X			X												
63	NP 6	KB	3			X						X	X			X												
64	NP 7	KB	4			X						X	X			X												
65	NP 8	KB	3			X						X	X			X												
66	NP 9	KB	1			X						X	X			X												
67	NP 10	KB	4			X						X	X			X												

27  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBRT

Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Code	Tree DBH	Palm BTH	G	F	I	P	D	Swlk <=3'	>3' Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Ro/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
68 NP	11	KB	2								X										X					Subordinate to adjacent trees
69 NP	12	KB	3		X						X															Subordinate to adjacent oak trees
70 NP	13	KB	2								X										X					
71 NP	14	KB	1		X						X										X					
72 NP	15	KB	2		X						X										X					
73 NP	16	KB	2		X						X										X					
74 NP	17	KB	4		X						X										X					
75 NP	18	KB	5		X						X										X					
76 NP	19	KB	2		X						X										X					
77 NP	20	KB	4		X						X										X					
78 NP	21	KB	3		X						X										X					
79 NP	22	KB	7		X						X										X					
80 NP	23	KB	4		X						X										X					
81 NP	24	KB	7		X						X										X					
82 NP	25	KB	8		X						X										X					
83 NP	26	KB	9		X						X										X					
84 NP	27	KB	6		X						X										X					
85 NP	28	KB	7		X						X										X					
86 NP	29	KB	10		X						X										X					
87 NP	30	KB	5		X						X										X					
88 NP	31	KB	7		X						X										X					
89 NP	32	KB	8		X						X										X					
90 NP	33	KB	7		X						X										X					
91 NP	34	KB	9		X						X										X					
92 NP	35	KB	5		X						X										X					
93 NP	36	KB	4		X						X										X					
94 NP	37	KB	4		X						X										X					
95 NP	38	KB	5		X						X										X					
96 NP	39	KB	7		X						X										X					
97 NP	40	KB	7		X						X										X					
98 NP	41	KB	5		X						X										X					
99 NP	42	KB	6		X						X										X					
100 NP	43	KB	6		X						X										X					
101 NP	44	KB	10		X						X										X					
102 NP	45	KB	7		X						X										X					
103 NP	46	KB	1		X						X										X					
104 NP	47	KB	3		X						X										X					
121 NP	48	PC	5		X						X										X					
120 NP	49	PC	5		X						X										X					
119 NP	50	WR	7		X						X										X					
118 NP	51	PC	7		X						X										X					
117 NP	52	PC	6		X						X										X					
116 NP	53	PC	5		X						X										X					
115 NP	54	WR	5		X						X										X					Pale color, stem dieback

28  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Tree Code DBH	Palm	BTH	G	F	P	D	Swik	<3'	>3'	Lwn	Weak Fork	Root Damage	Trunk Damage	Crown Decline	RoV/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
114	NP 55	PC			X					X	X	X			X	X						X				Pale color, stem dieback	
113	NP 56	PC			X					X	X	X											X				
112	NP 57	PC			X					X	X	X											X				
111	NP 58	WR		22	X					X	X	X											X				
110	NP 59	PC			X					X	X	X											X				
109	NP 60	PC			X					X	X	X											X				
108	NP 61	PC			X					X	X	X											X				
107	NP 62	PC			X					X	X	X											X				
106	NP 63	WR		22	X					X	X	X											X				
105	NP 64	PC			X					X	X	X											X				
162	NP 65	PC			X					X	X	X											X				
163	NP 66	WR		20	X					X	X	X											X				
164	NP 67	PC			X					X	X	X											X				
165	NP 68	WR		20	X					X	X	X											X				
166	NP 69	PK		6	X					X	X	X											X				
167	NP 70	WR		20	X					X	X	X											X				
168	NP 71	PK		5	X					X	X	X											X				
169	NP 72	WR		23	X					X	X	X											X				
170	NP 73	PK		4	X					X	X	X											X				
171	NP 74	WR		23	X					X	X	X											X				
172	NP 75	PK		4	X					X	X	X											X				
173	NP 76	WR		23	X					X	X	X											X				
174	NP 77	PK		5	X					X	X	X											X				
189	NP 78	PC		4	X					X	X	X											X				
190	NP 79	RL		6	X					X	X	X											X				
191	NP 80	PC		4	X					X	X	X											X				
192	NP 81	PC		5	X					X	X	X											X				
193	NP 82	WR		24	X					X	X	X											X				
194	NP 83	PC		5	X					X	X	X											X				
195	NP 84	PC		4	X					X	X	X											X				
196	NP 85	RL		2	X					X	X	X											X				
197	NP 86	PC		5	X					X	X	X											X				
199	NP 87	PC		4	X					X	X	X											X				
200	NP 88	WR		5	X					X	X	X											X				
201	NP 89	PC		5	X					X	X	X											X				
202	NP 90	PC		4	X					X	X	X											X				
203	NP 91	PC		3	X					X	X	X											X				
204	NP 92	PC		4	X					X	X	X											X				
205	NP 93	WR		21	X					X	X	X											X				
206	NP 94	PC		4	X					X	X	X											X				
207	NP 95	PC		4	X					X	X	X											X				
208	NP 96	WR		4	X					X	X	X											X				
209	NP 97	PC		4	X					X	X	X											X				
210	NP 98	PC		5	X					X	X	X											X				
211	NP 99	PC		5	X					X	X	X											X				
212	NP 100	PC		5	X					X	X	X											X				

29  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments								
Photo #	Tree #	Code	Tree DBH	Palm BTH	G	F	P	D	Swlk <=3'	Swlk >3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
213	NP 101	WR																								
214	NP 102	PC	5	22	X	X			X	X	X		X	X				X								
215	NP 103	PC	4						X	X	X															
216	NP 104	PH	7						X	X	X															
217	NP 105	WR		21																						
218	NP 106	PC	5						X	X	X		X	X												
219	NP 107	PC	5						X	X	X		X	X												
220	NP 108	PH	5						X	X	X		X	X												
221	NP 109	PC	5						X	X	X		X	X												
222	NP 110	PC	5						X	X	X		X	X												
223	NP 111	PC	5						X	X	X		X	X												
224	NP 112	RI	3						X	X	X		X	X												
225	NP 113	RI	3						X	X	X		X	X												
226	NP 114	PC	5						X	X	X		X	X												
227	NP 115	PC	5						X	X	X		X	X												
228	NP 116	RI	3						X	X	X		X	X												
298	NP 117	PG	8						X	X	X		X	X												
299	NP 118	PG	8						X	X	X		X	X												
300	NP 119	PC	5						X	X	X		X	X												
301	NP 120	WR	26						X	X	X		X	X												
302	NP 121	PC	6						X	X	X		X	X												
303	NP 122	PC	6						X	X	X		X	X												
304	NP 123	PC	5						X	X	X		X	X												
305	NP 124	WR		30					X	X	X		X	X												
306	NP 125	PC	6						X	X	X		X	X												
307	NP 126	PC	6						X	X	X		X	X												
308	NP 127	PC	8						X	X	X		X	X												
309	NP 128	WR		27					X	X	X		X	X												
310	NP 129	WR		22					X	X	X		X	X												
311	NP 130	PC	7						X	X	X		X	X												
312	NP 131	PC	6						X	X	X		X	X												
313	NP 132	PC	6						X	X	X		X	X												
314	NP 133	WR		30					X	X	X		X	X												
315	NP 134	PC	6						X	X	X		X	X												
316	NP 135	PC	5						X	X	X		X	X												
317	NP 136	WR		27					X	X	X		X	X												
318	NP 137	PC	5						X	X	X		X	X												
319	NP 138	PC	5						X	X	X		X	X												
320	NP 139	PC	1						X	X	X		X	X												
321	NP 140	WR		26					X	X	X		X	X												
322	NP 141	PG	12						X	X	X		X	X												
323	NP 142	PG	6						X	X	X		X	X												
375	NP 143	PC	6						X	X	X		X	X												
376	NP 144	PC	3						X	X	X		X	X												
377	NP 145	PC	1						X	X	X		X	X												
378	NP 146	WR		21					X	X	X		X	X												



30  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Code	Tree DBH	Tree Palm	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Ro/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
379	NP 147	PC	5		X							X															
380	NP 148	PC	7		X							X															
381	NP 149	PC	5		X							X															
382	NP 150	WR	21		X							X															
383	NP 151	PC	4		X							X															
384	NP 152	PC	6		X							X															
385	NP 153	PC	6		X							X															
386	NP 154	WR	20		X							X															
387	NP 155	PC	5		X							X															
388	NP 156	PC	5		X							X															
389	NP 157	WR	17		X							X															
390	NP 158	PC	5		X							X															
391	NP 159	PC	5		X							X															
392	NP 160	PC	7		X							X															
393	NP 161	WR	21		X							X															
394	NP 162	PC	6		X							X															
395	NP 163	PC	5		X							X															
396	NP 164	WR	20		X							X															
397	NP 165	PC	7		X							X															
398	NP 166	PC	5		X							X															
399	NP 167	PC	1		X							X															
400	NP 168	WR	22		X							X															
401	NP 169	PC	6		X							X															
402	NP 170	PC	6		X							X															
403	NP 171	PC	7		X							X															
404	NP 172	WR	16		X							X															
405	NP 173	PC	5		X							X															
406	NP 174	PC	4		X							X															
407	NP 175	PC	6		X							X															
408	NP 176	WR	18		X							X															
409	NP 177	PC	5		X							X															
410	NP 178	PC	4		X							X															
411	NP 179	PC	6		X							X															
412	NP 180	WR	18		X							X															
413	NP 181	PC	3		X							X															
414	NP 182	PC	6		X							X															
415	NP 183	PC	5		X							X															
416	NP 184	PG	7		X							X															
417	NP 185	PG	8		X							X															
324	NP 186	PC	1		X							X															
325	NP 187	PC	1		X							X															
326	NP 188	PC	5		X							X															
327	NP 189	PC	2		X							X															
328	NP 190	PC	1		X							X															
329	NP 191	PC	1		X							X															
330	NP 192	PC	3		X							X															

31  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Tree Palm	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Ro/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments		
331	NP 193	PC	7		X							X																
332	NP 194	PC	7		X							X																
333	NP 195	PC	6		X							X																
334	NP 196	PC	4		X							X																
335	NP 197	PC	5		X							X																
336	NP 198	PC	1		X							X																
337	NP 199	PC	1				X					X																
338	NP 200	PC	5		X							X																
339	NP 201	PC	5		X							X																
340	NP 202	PC	7		X							X																
341	NP 203	PC	7		X							X																
342	NP 204	PC	4		X							X																
343	NP 205	PC	4		X							X																
344	NP 206	PC	6		X							X																
345	NP 207	PC	6		X							X																
346	NP 208	PC	5		X							X																
347	NP 209	PC	5		X							X																
348	NP 210	PC	7		X							X																
349	NP 211	PC	5		X							X																
350	NP 212	PC	4		X							X																
351	NP 213	PC	4		X							X																
352	NP 214	PC	7		X							X																
353	NP 215	PC	8		X							X																
354	NP 216	PC	1		X							X																
355	NP 217	PC	1		X							X																
356	NP 218	PC	6		X							X																
357	NP 219	PC	5		X							X																
358	NP 220	PC	4		X							X																
359	NP 221	PC	5		X							X																
360	NP 222	PC	7		X							X																
361	NP 223	PC	5		X							X																
362	NP 224	PC	4		X							X																
363	NP 225	PC	5		X							X																
364	NP 226	PC	7		X							X																
365	NP 227	PC	6		X							X																
366	NP 228	PC	5		X							X																
367	NP 229	PC	5		X							X																
368	NP 230	PC	6		X							X																
369	NP 231	PC	3									X																
370	NP 232	PC	5		X							X																
371	NP 233	PC	5		X							X																
372	NP 234	PC	5		X							X																
373	NP 235	PC	4		X							X																
374	NP 236	PC	4		X							X																
513	NP 237	PC	5		X							X																
514	NP 238	PC	7		X							X																

32  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Code	Tree DBH	Tree Palm	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
515	NP 239	PC	4		X																						
516	NP 240	PC	7		X																						X
517	NP 241	PC	6		X																						X
518	NP 242	PC	3		X																						X
519	NP 243	PC	6		X																						X
520	NP 244	PC	3		X																						X
521	NP 245	PC	7		X																						X
522	NP 246	PC	4		X																						X
523	NP 247	PC	3		X																						X
524	NP 248	PC	6		X																						X
525	NP 249	PC	6		X																						X
526	NP 250	PC	Removed					X																			X
527	NP 251	PC	7		X																						X
528	NP 252	PC	2		X																						X
529	NP 253	PC	1		X																						X
530	NP 254	PC	6		X																						X
531	NP 255	PC	7		X																						X
532	NP 256	PC	1		X																						X
533	NP 257	PC	1		X																						X
534	NP 258	PC	6		X																						X
535	NP 259	PC	7		X																						X
536	NP 260	PC	4		X																						X
537	NP 261	PC	3		X																						X
538	NP 262	PC	7		X																						X
539	NP 263	PC	5		X																						X
540	NP 264	PC	1		X																						X
541	NP 265	PC	6		X																						X
542	NP 266	PC	6		X																						X
543	NP 267	PC	1		X																						X
544	NP 268	PC	3		X																						X
545	NP 269	PC	5		X																						X
546	NP 270	PC	6		X																						X
547	NP 271	PC	7		X																						X
548	NP 272	PC	2		X																						X
549	NP 273	PC	1		X																						X
550	NP 274	PC	8		X																						X
551	NP 275	PC	6		X																						X
552	NP 276	PC	4		X																						X
553	NP 277	PC	2		X																						X
554	NP 278	PC	5		X																						X
555	NP 279	PC	6		X																						X
556	NP 280	PC	3		X																						X
557	NP 281	PC	4		X																						X
558	NP 282	PC	8		X																						X
559	NP 283	PC	8		X																						X
559	NP 284	PC	5		X																						X

33  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Code	Tree DBH	Tree Palm	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
560	NP 285	PC	5		X						X														X		
561	NP 286	PC	8		X				X		X														X		
562	NP 287	PC	5		X				X		X														X		
563	NP 288	PC	4		X				X		X														X		
564	NP 289	PC	5		X				X		X														X		
565	NP 290	PC	8		X				X		X														X		
566	NP 291	PC	4		X				X		X														X		
567	NP 292	PC	5		X				X		X														X		
568	NP 293	PC	8		X				X		X														X		
569	NP 294	PC	7		X				X		X														X		
570	NP 295	PC	1		X				X		X														X		
571	NP 296	PC	4		X				X		X														X		
572	NP 297	PC	6		X				X		X														X		
573	NP 298	PC	6		X				X		X				X	X									X		
574	NP 299	PC	4		X				X		X				X	X									X		
575	NP 300	PC	4		X				X		X				X	X									X		
576	NP 301	PC	7		X				X		X			X											X		
577	NP 302	PC	3		X				X		X														X		
578	NP 303	PC	3		X				X		X														X		
NP 304				Not used																							
579	NP 305	PC	7		X				X		X														X		
580	NP 306	PC	4		X				X		X														X		
581	NP 307	PC	4		X				X		X														X		
582	NP 308	PC	6		X				X		X														X		
583	NP 309	PC	7		X				X		X														X		
584	NP 310	PC	4		X				X		X														X		
585	NP 311	PC	4		X				X		X														X		
586	NP 312	PC	6		X				X		X														X		
587	NP 313	PC	7		X				X		X														X		
588	NP 314	PC	4		X				X		X														X		
589	NP 315	PC	5		X				X		X														X		
590	NP 316	PC	7		X				X		X														X		
591	NP 317	PC	7		X				X		X														X		
592	NP 318	PC	4		X				X		X														X		
593	NP 319	PC	5		X				X		X														X		
594	NP 320	PC	5		X				X		X														X		
595	NP 321	PC	3		X				X		X														X		
596	NP 322	PC	1		X				X		X														X		
597	NP 323	PC	1		X				X		X														X		
757	NP 324	PC	4		X				X		X														X		
758	NP 325	PC	5		X				X		X														X		
759	NP 326	PC	5		X				X		X														X		
760	NP 327	PC	3		X				X		X														X		
761	NP 328	PC	3		X				X		X														X		
762	NP 329	PC	6		X				X		X														X		
763	NP 330	PC	3		X				X		X														X		

Leaking bubbler

34  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information				Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments										
Photo #	Tree #	Code	Tree DBH	Tree Palm	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Ro/ Cavity	Clean	Raise	Red.	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments		
764	NP 331	PC	1		X							X																
765	NP 332	PC	5		X							X																
766	NP 333	PC	4		X							X																
767	NP 334	PC	3		X							X																
768	NP 335	PC	3		X							X																
769	NP 336	PC	6		X							X																
770	NP 337	PC	6		X							X																
771	NP 338	PC	3		X							X																
772	NP 339	PC	3		X							X																
773	NP 340	PC	5		X							X																
774	NP 341	PC	1		X							X																
775	NP 342	PC	3		X							X																
776	NP 343	PC	5		X							X																
777	NP 344	PC	5		X							X																
778	NP 345	PC	3		X							X																
779	NP 346	PC	6		X							X																
780	NP 347	PC	8		X							X																
781	NP 348	PC	2		X							X																
782	NP 349	PC	3		X							X																
783	NP 350	PC	7		X							X																
784	NP 351	PC	6		X							X																
785	NP 352	PC	5		X							X																
786	NP 353	PC	7		X							X																
787	NP 354	PC	1		X							X																
788	NP 355	PC	5		X							X																
789	NP 356	PC	5		X							X																
790	NP 357	PC	5		X							X																
791	NP 358	PC	4		X							X																
792	NP 359	PC	5		X							X																
793	NP 360	PC	6		X							X																
794	NP 361	PC	2		X							X																
795	NP 362	PC	7		X							X																
796	NP 363	PC	8		X							X																
797	NP 364	PC	3		X							X																
798	NP 365	PC	6		X							X																
799	NP 366	PC	8		X							X																
800	NP 367	PC	4		X							X																
801	NP 368	PC	6		X							X																
802	NP 369	PC	10		X							X																
803	NP 370	PC	5		X							X																
804	NP 371	PC	6		X							X																
805	NP 372	PC	9		X							X																
806	NP 373	PC	5		X							X																
807	NP 374	PC	8		X							X																
808	NP 375	PC	7		X							X																
809	NP 376	PC	7		X							X																

35  
 11/12/12

## Tree Inventory East Palomar Street

Project: SANDAG SBBRT

Tree Information			Tree Condition			Planting Location			Conditions				Maintenance Needs				Comments									
Photo #	Tree #	Tree Code	Tree DBH	Palm BTH	G	F	P	D	Swlk	<3'	>3'	Lwn	Weak fork	Root Damage	Trunk Damage	Crown Decline	Rot/Cavity	Clean	Raise	Rem.	Over watered	Trunk Girdled	Ants	Snails	Comments	
810/NP	377	PC	8		X					X																
811/NP	378	PC	7		X					X																X
812/NP	379	PC	7		X					X																X
813/NP	380	PC	4		X					X																X
814/NP	381	PC	6		X					X																X
815/NP	382	PC	6		X					X													X			X

## Appendix H – Data Results

Summary of the Results for the Community of:			East Palomar Street		
				Chula Vista, CA.	
<b>Number of Trees Inventoried:</b>		1553			
<b># of Trees /Mile:</b>		409			
<b>Average DBH:</b>		5.45			
<b>Tree Condition</b>			<b>Planting Location</b>		
	Actual #	% of Pop.		Actual #	% of Pop.
Good	1370	88%	Sidewalk	0	0%
Fair	142	9%	<3'	456	29%
Poor	27	2%	>3'	1096	71%
Dead	14	1%	Lawn	1130	73%
<b>Conditions</b>			<b>Maintenance Needs</b>		
	Actual #	% of Pop.		Actual #	% of Pop.
Weak Fork	7	0%	Safety/clean	458	29%
Root Injury	119	8%	Crown raise	7	0%
Trunk Injury	306	20%	Crown reduction	0	0%
Crown Decline	54	3%	Overwatered	34	2%
Rot / Cavity	15	1%	Removal	30	2%
			Girdled trunk	22	1%

## Appendix I – Data Graph


SANDAG SBBRT

Graphs of Tree Data


### Overall Condition




### Planting Location



### Conditions



### Maintenance Needs





## Appendix J – Species List

SANDAG SBBRT


List of Tree Species and Tree Codes

Code	Species	Actual Number of Trees	Percentage of Trees	Genus	Actual Number of Trees	Percentage of Trees
EF	Eucalyptus ficifolia	29	2%	Eucalyptus	29	2%
KB	Koelruetaria bipinnata	133	9%	Pyrus	923	59%
PK	Pyrus kawakami	5	0%	Koelruetaria	133	9%
PC	Pyrus calleryana	918	59%	Pinus	2	0%
PG	Podocarpus gracilior	8	1%	Podocarpus	8	1%
PH	Pinus halepensis	2	0%	Rhus	5	0%
RI	Rhus integrifolia	3	0%	Washingtonia	453	29%
RL	Rhus lancea	2	0%			
WR	Washingtonia robusta	453	29%			


## Appendix K – RDCS Recommended Tree Palette


Scientific Name	Common Name	7' width	12' width
Brachychiton populneus	Bottle tree		X
Brahea armata	Mexican Blue Palm	X	X
Brahea edulis	Guadalupe Palm	X	X
Butia capitata	Pindo Pam	X	X
Cassia leptophylla	Gold Medallion tree		X
Chamaerops humilis	Mediterranean Fan palm	X	X
Chamaerops humilus 'cerifera'	Blue Mediterranean Fan palm	X	X
Metrosideros excelsa	New Zealand Xmas tree	X	X
*Podocarpus henkelii	Long Leafed Yew		X
*Rhus lancea	African Sumac		X
Trachycarpus fortunei	Windmill Palm	X	X
Washingtonia robusta	Mexican Fan Palm	X	X

**Appendix L – Study Area Site Exhibit**




**Appendix M – Median and Parkway Tree Location Exhibit**










## **7.3 Landscape and Irrigation Exhibits**






**Legend**

- BRT Alignment/Transit Lanes
- BRT Station
- BRT Station with Passenger Drop-off
- Ⓟ Transit Park and Ride
- Local Bus Stop
- Landscape Block

OLEANDER AVE. TO MEDICAL CENTER DR.

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Chinese Flame Tree - <i>Koelreutaria Bipinnata</i> Victorian Box - <i>Pittosporum Undulatum</i> Sycamore - <i>Platanus Racemosa</i> Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i>	Aristocrat Pear - <i>Pyrus Calleryana</i>
<b>SHRUBS:</b>	Wax Leaf Privet - <i>Ligustrum Japonicum 'Texum'</i> Dwarf Oleander - <i>Nerium Oleander 'Petite Pink'</i> Indian Hawthorne - <i>Raphiolepis Indica 'Clara'</i> Bird of Paradise - <i>Strelitzia Reginae</i> Viburnum - <i>Viburnum Japonicum</i>		Wax Leaf Privet - <i>Ligustrum Japonicum 'Texum'</i> Dwarf Oleander - <i>Nerium Oleander 'Petite Pink'</i>
<b>GROUNDCOVERS:</b>	Rosea Ice Plant - <i>Drosanthemum Floribundum</i> Trailing Ice Plant - <i>Lampranthus Spectabilis</i>		Rosea Ice Plant - <i>Drosanthemum Floribundum</i>




- Open Space Maintenance Districts**
- D7 Zenith Units 2, 3, 4
  - D97 Otay Ranch Village 1
  - D98 Sunbow 2
  - D97 (2) Otay Ranch McMillin
  - D99 Otay Ranch Village 1 West
  - Millenia (EUC)

- Legend**
- BRT Alignment/Transit Lanes
  - BRT Station
  - BRT Station with Passenger Drop-off
  - Transit Park and Ride
  - Local Bus Stop
  - Landscape Block

MEDICAL CENTER DR. TO MEDICAL CENTER CT.

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i>	Chinese Flame Tree - <i>Koelreutaria Bipinnata</i>
<b>SHRUBS:</b>	Wax Leaf Privet - <i>Ligustrum Japonicum 'Texum'</i> Bird of Paradise - <i>Strelitzia Reginae</i> Viburnum - <i>Viburnum Japonicum</i>		Dwarf Oleander - <i>Nerium Oleander 'Petite Pink'</i>
<b>GROUNDCOVERS:</b>	Rosea Ice Plant - <i>Drosanthemum Floribundum</i> Trailing Ice Plant - <i>Lampranthus Spectabilis</i>		Rosea Ice Plant - <i>Drosanthemum Floribundum</i> Trailing Ice Plant - <i>Lampranthus Spectabilis</i>




- Open Space Maintenance Districts**
- D7 Zenith Units 2, 3, 4
  - D97 Otay Ranch Village 1
  - D98 Sunbow 2
  - D97 (2) Otay Ranch McMillin
  - D99 Otay Ranch Village 1 West
  - Millenia (EUC)

- Legend**
- BRT Alignment/Transit Lanes
  - BRT Station
  - BRT Station with Passenger Drop-off
  - Transit Park and Ride
  - Local Bus Stop
  - Landscape Block

**MEDICAL CENTER CT. TO PASEO LADERA**

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Victorian Box - <i>Pittosporum Undulatum</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i>	Chinese Flame Tree - <i>Koelreutaria Bipinnata</i>
<b>SHRUBS:</b>	Wax Leaf Privet - <i>Ligustrum Japonicum 'Texum'</i> Indian Hawthorne - <i>Raphiolepis Indica 'Clara'</i> Bird of Paradise - <i>Strelitzia Reginae</i> Viburnum - <i>Viburnum Japonicum</i>		Indian Hawthorne - <i>Raphiolepis Indica 'Clara'</i> Dwarf Oleander - <i>Nerium Oleander 'Petite Pink'</i>
<b>GROUNDCOVERS:</b>	Rosea Ice Plant - <i>Drosanthemum Floribundum</i> Trailing Ice Plant - <i>Lampranthus Spectabilis</i>		Rosea Ice Plant - <i>Drosanthemum Floribundum</i> Trailing Ice Plant - <i>Lampranthus Spectabilis</i>




PASEO LADERA TO BRASHEAR PL.

**Legend**

- BRT Alignment/Transit Lanes
- BRT Station
- BRT Station with Passenger Drop-off
- Ⓟ Transit Park and Ride
- Local Bus Stop
- ▬ Landscape Block

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i>	Chinese Flame Tree - <i>Koelreutaria Bipinnata</i>
<b>SHRUBS:</b>	Wax Leaf Privet - <i>Ligustrum Japonicum 'Texum'</i> Bird of Paradise - <i>Strelitzia Reginae</i> Viburnum - <i>Viburnum Japonicum</i>		Wax Leaf Privet - <i>Ligustrum Japonicum 'Texum'</i> Dwarf Oleander - <i>Nerium Oleander 'Petite Pink'</i>
<b>GROUNDCOVERS:</b>	Rosea Ice Plant - <i>Drosanthemum Floribundum</i> Trailing Ice Plant - <i>Lampranthus Spectabilis</i>		Rosea Ice Plant - <i>Drosanthemum Floribundum</i> Trailing Ice Plant - <i>Lampranthus Spectabilis</i>



**Open Space Maintenance Districts**


- D7 Zenith Units 2, 3, 4
- D97 Otay Ranch Village 1
- D98 Sunbow 2
- D97 (2) Otay Ranch McMillin
- D99 Otay Ranch Village 1 West
- Millenia (EUC)

**Legend**

- BRT Alignment/Transit Lanes
- BRT Station
- BRT Station with Passenger Drop-off
- Transit Park and Ride
- Local Bus Stop
- Landscape Block

BRASHEAR PL. TO HERITAGE RD.

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Crape Myrtle - <i>Lagerstroemia Indica</i> Brisbane Box - <i>Tristania Conferta</i> Aristocrat Pear - <i>Pyrus Calleryana</i>	Aristocrat Pear - <i>Pyrus Calleryana</i>	Chinese Flame Tree - <i>Koelreutaria Bipinnata</i> Red Flowering Gum - <i>Eucalyptus Ficifolia</i>
<b>SHRUBS:</b>	Myoporum - <i>myoporum Pacificum</i> 'South Coast' Society Garlic - <i>Tulbaghia Violacea</i> Viburnum - <i>Viburnum Japonicum</i>		Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara' Daylily - <i>Hemerocallis Hybrids</i> 'Yellow'
<b>GROUNDCOVERS:</b>	Rosea Ice Plant - <i>Drosanthemum Floribundum</i>		Rosea Ice Plant - <i>Drosanthemum Floribundum</i>




HERITAGE RD. TO SANTA ANDREA ST.

**Legend**

- BRT Alignment/Transit Lanes
- BRT Station
- BRT Station with Passenger Drop-off
- Ⓟ Transit Park and Ride
- Local Bus Stop
- Landscape Block

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i> Canary Date Palm - <i>Phoenix Canariensis</i>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>
<b>SHRUBS:</b>	Myoporum - <i>Myoporum Pacificum</i> 'South Coast'	Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara' Star Jasmine - <i>Trachelospermum Jasminoides</i>	Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara' Daylily - <i>Hemerocallis Hybrids</i> 'Yellow'
<b>GROUNDCOVERS:</b>			




SANTA ANDREA ST. TO SANTA FLORA RD. + 800 FT.

**Legend**

- BRT Alignment/Transit Lanes
- BRT Station
- BRT Station with Passenger Drop-off
- Ⓟ Transit Park and Ride
- Local Bus Stop
- Landscape Block

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>
<b>SHRUBS:</b>	Myoporum - <i>Myoporum Pacificum</i> 'South Coast' Indian Hawthorne - <i>Raphiolepis Indica</i> 'Enchantress'	Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara' Star Jasmine - <i>Trachelospermum Jasminoides</i>	Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara' Daylily - <i>Hemerocallis Hybrids</i> 'Yellow'
<b>GROUNDCOVERS:</b>			




SANTA FLORA RD. + 800 FT. TO SANTA ROSA DR.

**Legend**

- BRT Alignment/Transit Lanes
- BRT Station
- BRT Station with Passenger Drop-off
- Ⓟ Transit Park and Ride
- Local Bus Stop
- Landscape Block

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
<b>TREES:</b>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i> Cherry Plum - <i>Prunus Blierea</i>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i>
<b>SHRUBS:</b>	Myoporum - <i>Myoporum Pacificum</i> 'South Coast'	Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara'	Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara' Daylily - <i>Hemerocallis Hybrids</i> 'Yellow'
<b>GROUNDCOVERS:</b>			Rosemary - <i>Rosmarinus Officinalis</i>





**Legend**

- BRT Alignment/Transit Lanes
- BRT Station
- BRT Station with Passenger Drop-off
- Ⓟ Transit Park and Ride
- Local Bus Stop
- ▬ Landscape Block

SANTA ROSA DR. TO OLYMPIC PKWY.

	BEHIND BACK OF WALK	PARKWAY	MEDIAN
TREES:	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i> Flowering Plum - <i>Prunus Blireiana</i>	Aristocrat Pear - <i>Pyrus Calleryana</i> Mexican Fan Palm - <i>Washingtonia Robusta</i> Flowering Plum - <i>Prunus Blireiana</i>	Mexican Fan Palm - <i>Washingtonia Robusta</i>
SHRUBS:	Myoporum - <i>Myoporum Pacificum</i> 'South Coast'		Indian Hawthorne - <i>Raphiolepis Indica</i> 'Clara' Daylily - <i>Hemerocallis Hybrids</i> 'Yellow'
GROUNDCOVERS:			Rosemary - <i>Rosmarinus Officinalis</i>



## Preliminary Landscape Removal by District

### Maintenance District D.98

■ Oleander to Gould

6 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

8 - *Koelreutaria Bipinnata* - Chinese Flame Tree

26,700 SF - Turf Area

20,300 SF - Shrub Area

■ Gould to Medical Center Drive

18 - *Koelreutaria Bipinnata* - Chinese Flame Tree

14,100 SF - Turf Area

■ Medical Center Drive to Davies

44 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

6 - *Pittosporum Undulatum* - Victorian Box

17 - *Washingtonia Robusta* - Mexican Fan Palm

19,100 SF - Turf Area

6,200 SF - Shrub Area

■ Davies to Medical Center Court

55 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

9 - *Pittosporum Undulatum* - Victorian Box

25 - *Washingtonia Robusta* - Mexican Fan Palm

21,900 SF - Turf Area

5,500 SF - Shrub Area

■ Medical Center Court to Paseo Ladera

40 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

9 - *Pittosporum Undulatum* - Victorian Box

17 - *Washingtonia Robusta* - Mexican Fan Palm

4 - *Koelreutaria Bipinnata* - Chinese Flame Tree

20,500 SF - Turf Area

4,200 SF - Shrub Area

■ Paseo Ladera to Hedenkamp Elementary

56 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

6 - *Pittosporum Undulatum* - Victorian Box

27 - *Washingtonia Robusta* - Mexican Fan Palm

17 - *Koelreutaria Bipinnata* - Chinese Flame Tree

29,800 SF - Turf Area

13,200 SF - Shrub Area

■ District Totals

201 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

29 - *Pittosporum Undulatum* - Victorian Box

86 - *Washingtonia Robusta* - Mexican Fan Palm

47 - *Koelreutaria Bipinnata* - Chinese Flame Tree

132,100 SF - Turf Area

49,400 SF - Shrub Area

### Maintenance District D.99

■ Hedenkamp Elementary to Santa Olivia

108 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

4 - *Koelreutaria Bipinnata* - Chinese Flame Tree

10,200 SF - Turf Area

12,400 SF - Shrub Area

■ Santa Olivia to Santa Sierra

190 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

20 - *Eucalyptus Ficalia* - Red Flowering Gum

18,300 SF - Turf Area

25,300 SF - Shrub Area

■ Santa Sierra to Heritage

130 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

10 - *Eucalyptus Ficalia* - Red Flowering Gum

11,800 SF - Turf Area

28,300 SF - Shrub Area

■ District Totals

428 - *Pyrus Calleryana* 'Aristocrat' - Flowering Pear Tree

30 - *Eucalyptus Ficalia* - Red Flowering Gum

4 - *Koelreutaria Bipinnata* - Chinese Flame Tree

40,300 SF - Turf Area

66,000 SF - Shrub Area



## Preliminary Landscape Removal by District

### Maintenance District D.97

#### ■ Heritage to Santa Rita

78 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
26/88(T) - *Washingtonia Robusta* - Mexican Fan Palm  
10,900 SF - Turf Area  
59,500 SF - Shrub Area

#### ■ Santa Rita to Santa Andrea

48 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
10/50(T) - *Washingtonia Robusta* - Mexican Fan Palm  
16,800 SF - Turf Area  
24,400 SF - Shrub Area

#### ■ Santa Andrea to Santa Alicia

32 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
0/38(T) - *Washingtonia Robusta* - Mexican Fan Palm  
12,900 SF - Turf Area  
21,000 SF - Shrub Area

#### ■ Santa Alicia to Santa Flora

74 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
12/86(T) - *Washingtonia Robusta* - Mexican Fan Palm  
11,400 SF - Turf Area  
49,000 SF - Shrub Area

#### ■ Santa Flora to Santa Delphina

41 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
26/46(T) - *Washingtonia Robusta* - Mexican Fan Palm  
6,300 SF - Turf Area  
27,900 SF - Shrub Area

#### ■ District Totals

273 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
74/308(T) - *Washingtonia Robusta* - Mexican Fan Palm  
58,300 SF - Turf Area  
181,800 SF - Shrub Area

### Maintenance District D.97.2

#### ■ Santa Delphina to La Media

19 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
4/18(T) - *Washingtonia Robusta* - Mexican Fan Palm  
2,400 SF - Turf Area  
11,500 SF - Shrub Area

#### ■ La Media to Santa Cora

0/20(T) - *Washingtonia Robusta* - Mexican Fan Palm  
4,600 SF - Turf Area  
26,500 SF - Shrub Area

#### ■ Santa Cora to Vista Sonrisa

0/18(T) - *Washingtonia Robusta* - Mexican Fan Palm  
21,400 SF - Turf Area  
11,600 SF - Shrub Area

#### ■ Vista Sonrisa to Santa Rosa

0/14(T) - *Washingtonia Robusta* - Mexican Fan Palm  
3,800 SF - Turf Area  
24,300 SF - Shrub Area

#### ■ Santa Rosa to Olympic

4/9(T) - *Washingtonia Robusta* - Mexican Fan Palm  
2,900 SF - Turf Area  
10,800 SF - Shrub Area

#### ■ District Totals

19 - *Pyrus Calleryana 'Aristocrat'* - Flowering Pear Tree  
8/79(T) - *Washingtonia Robusta* - Mexican Fan Palm  
35,100 SF - Turf Area  
84,700 SF - Shrub Area



Primary Street Tree Species



**Flowering Pear**  
*Pyrus Calleryana 'Arisocrat'*



**Chinese Flame Tree**  
*Koelreutaria Bipinnata*



**Mexican Fan Palm**  
*Washingtonia Robusta*

Possible Street Tree Species



**Fern Pine**  
*Podocarpus Gracillor*




**New Zealand Christmas Tree**  
*Metrosideros Excelsus*



**Brisbane Box**  
*Tristania Conferta*

## **7.4 Station Communications and Electrical Exhibits**



REFER TO DETAIL A  
SHEET E.06

**LEGEND**


	UNDERGROUND CONDUIT		VENDING MACHINE
	ELECTRICAL PULL BOX		BIKE LOCKER
	COMMUNICATIONS PULL BOX		PAY PHONE
	PLATFORM LIGHT		TYPE 1 SITE IDENTIFICATION SIGN
	SHELTER LIGHT		CCTV CAMERA
	VMS AND CCTV POLE		PUBLIC ADDRESS SYSTEM
	PCID		UTILITIES
	TICKET VENDING MACHINE		

**ELECTRICAL SHEET NOTES**


- ① PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE PLATFORM LIGHT.
- ② PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE BIKE LOCKER.
- ③ PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE VARIABLE MESSAGE SIGN.
- ④ PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE PCID.
- ⑤ PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE PLATFORM SHELTER LIGHTS.
- ⑥ PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE TICKET VENDING MACHINE.
- ⑦ PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE VENDING MACHINE.
- ⑧ PROVIDE (1)2" CONDUIT FOR POWER AND (1)2" CONDUIT FOR COMMUNICATION TO SERVE PAY PHONE.
- ⑨ PROVIDE UTILITY CABINET WITH 200AMP 120/240V, IPH SERVICE, METER, AND PANEL. REFER TO DETAILS FOR ADDITIONAL INFORMATION.
- ⑩ PROVIDE 3-CABINET COMMUNICATION RACK. REFER TO DETAILS FOR ADDITIONAL INFORMATION.
- ⑪ PROVIDE IN GRADE CALTRANS NO. 6 (T) STANDARD PULL BOX. ONE DESIGNATED COMMUNICATION AND ONE DESIGNATED ELECTRICAL.
- ⑫ CCTV CAMERA MOUNTED TO POLE. REFER TO ELEVATIONS FOR MOUNTING HEIGHT AND DIRECTIONS.



**E.5.4.1B**  
**Cal Trans Type III-C (Modified) Service**  
**Equipment Enclosure**




TYPE III-C (MODIFIED) SERVICE EQUIPMENT ENCLOSURE WITH PROVISIONS FOR ONE 200 A METER AND PANEL




TYPE III-C (MODIFIED) SERVICE EQUIPMENT ENCLOSURE WITH PROVISIONS FOR ONE 200 A METER AND MAIN BREAKER AND ONE 100 A METER AND MAIN BREAKER

NOTES: (FOR SERVICE EQUIPMENT ENCLOSURE)

1. VOLTAGE RATINGS OF SERVICE EQUIPMENT SHALL CONFORM TO THE SERVICE VOLTAGES INDICATED ON THE PLANS.
2. UNLESS OTHERWISE INDICATED ON THE PLANS, SERVICE EQUIPMENT ITEMS SHALL BE PROVIDED FOR EACH SERVICE EQUIPMENT ENCLOSURE AS SHOWN.
3. CONNECT TO REMOTE TEST SWITCH MOUNTED ON LIGHTING STANDARDS, SIGN POST OR STRUCTURE WHEN REQUIRED.
4. NOT USED
5. METER SOCKETS SHALL BE 5 CLIP TYPE.
6. THE LANDING LUG SHALL BE SUITABLE FOR MULTIPLE CONDUCTORS.
7. TYPE II PHOTOELECTRIC CONTROL SHALL BE USED UNLESS OTHERWISE INDICATED ON THE PLANS.
8. FOR ADDITIONAL NOTES, SEE REVISED CALTRANS STANDARD PLANS RSP ES-2C. RATINGS SHALL BE AS INDICATED ON THE PLANS AND AS REQUIRED BY SDGE.




FOUNDATION DETAIL




BASE FOR TYPE III-C (MODIFIED) SERVICE EQUIPMENT ENCLOSURE



### E.5.4.1C Service Equipment Enclosure Wiring Diagram



TYPICAL SINGLE METER SERVICE EQUIPMENT ENCLOSURE WIRING DIAGRAM



TYPICAL DUAL METER SERVICE EQUIPMENT ENCLOSURE WIRING DIAGRAM


#### 120/240 V SERVICE WIRING DIAGRAM

##### TYPE III-C SERVICE (120/240 V) EQUIPMENT LEGEND


ITEM No.	COMPONENT	NAMEPLATE DESCRIPTION	ITEM No.	COMPONENT	NAMEPLATE DESCRIPTION
1	NEUTRAL LUG		14	200 A, 240 V, 2P, CB	MAIN BREAKER A
2	LANDING LUG (NOTE 6)		15	100 A, 240 V, 2P, CB	MAIN BREAKER B
3	TEST BYPASS FACILITY				
4	METER SOCKET AND SUPPORT				
5	TERMINAL BLOCKS				
6	NEUTRAL BUS (N)				
7	GROUND BUS (GB)				
8	GROUNDING ELECTRODE SYSTEM				
9	40 A, 2P, NO CONTACTOR	(NOTE 10)			
10	PHOTOELECTRIC UNIT (NOTE 7)				
11	15 A, 1P, TEST SWITCH	ILLUMINATION TEST SWITCH			
12	15 A, 120 V, 1P, CB	ILLUMINATION CONTROL			
13	CIRCUIT BREAKER	(NOTE 9)			

#### NOTES: (FOR SERVICE EQUIPMENT ENCLOSURE)


- VOLTAGE RATINGS OF SERVICE EQUIPMENT SHALL CONFORM TO THE SERVICE VOLTAGES INDICATED ON THE PLANS.
- UNLESS OTHERWISE INDICATED ON THE PLANS, SERVICE EQUIPMENT ITEMS SHALL BE PROVIDED FOR EACH SERVICE EQUIPMENT ENCLOSURE AS SHOWN.
- CONNECT TO REMOTE TEST SWITCH MOUNTED ON LIGHTING STANDARDS, SIGN POST OR STRUCTURE WHEN REQUIRED.
- ITEMS NO. 1 AND 6 SHALL BE ISOLATED FROM THE SERVICE EQUIPMENT ENCLOSURE.
- METER SOCKETS SHALL BE 5 CLIP TYPE.
- THE LANDING LUG SHALL BE SUITABLE FOR MULTIPLE CONDUCTORS.
- TYPE II PHOTOELECTRIC CONTROL SHALL BE USED.
- FOR ADDITIONAL NOTES, SEE REVISED CALTRANS STANDARD PLANS RSP ES-2C. RATINGS SHALL BE AS INDICATED ON THE PLANS AND AS REQUIRED BY SDG&E.
- REFER TO PANEL SCHEDULES FOR CIRCUIT BREAKER SIZES AND DESCRIPTIONS.
- CONTACTOR SHALL BE INSTALLED FOR ALL LIGHTING CIRCUITS.









**A** TYPICAL ON-PLATFORM PULL BOX LAYOUT  
NOT TO SCALE



**B** TYPICAL SHELTER CONDUIT ROUTING  
NOT TO SCALE



**CONDUCTOR CALL-OUT LEGEND**



**ELECTRICAL WIRING DIAGRAM**


**ELECTRICAL WIRING ABBREVIATIONS**

CPS	CAMERA POWER SUPPLY, 24VDC, 2-#10 BLACK AND RED
UPS	UNINTERRUPTED POWER SUPPLY, 240V, 2-#10 BLUE AND WHITE
AMP	AUDIO AMPLIFIER
PA	AUDIO SPEAKER CABLE (20V)




**A CONDUIT DUCT BANK TRENCH DETAIL**  
NOT TO SCALE

- NOTE:  
1. SEPARATION BETWEEN POWER AND COMMUNICATIONS CONDUIT SHALL BE 12" MINIMUM.  
2. A BED OF FINE SOIL OR SAND A MINIMUM OF 2" THICK SHALL BE PLACED IN THE TRENCH BEFORE PLACING THE CONDUIT. A MINIMUM OF 4" OF THE SAME TYPE OF MATERIAL SHALL BE PLACED OVER THE CONDUIT BEFORE ADDITIONAL BACKFILL MATERIAL IS PLACED.




**NOTES ON PULL BOXES:**

- TRAFFIC PULL BOX SHALL BE PROVIDED WITH STEEL COVER AND SPECIAL CONCRETE FOOTING. STEEL COVER SHALL HAVE EMBOSSED NON-SKID PATTERN.
- STEEL REINFORCING SHALL BE AS REGULARLY USED IN THE STANDARD PRODUCTS OF THE RESPECTIVE MANUFACTURER.
- TOP OF PULL BOXES SHALL BE FLUSH WITH SURROUNDING GRADE OR TOP OF ADJACENT CURB, EXCEPT THAT IN UNPAVED AREAS WHERE PULL BOX IS NOT IMMEDIATELY ADJACENT TO AND PROTECTED BY A CONCRETE FOUNDATION, POLE OR OTHER PROTECTIVE CONSTRUCTION, THE BOX SHALL BE PLACED WITH ITS TOP 1/4" ABOVE SURROUNDING GRADE. WHERE PRACTICABLE, PULL BOXES SHOWN IN THE VICINITY OF CURBS SHALL BE PLACED ADJACENT TO THE BACK OF CURB, AND PULL BOXES SHOWN ADJACENT TO STANDARDS SHALL BE PLACED ON SIDE OF FOUNDATION FACING AWAY FROM TRAFFIC, UNLESS OTHERWISE NOTED. WHEN PULL BOX IS INSTALLED IN SIDEWALK AREA, THE DEPTH OF THE PULL BOX SHALL BE ADJUSTED SO THAT THE TOP OF THE PULL BOX IS FLUSH WITH THE SIDEWALK.
- PULL BOX COVERS SHALL BE MARKED "ELECTRICAL" OR "COMMUNICATIONS" AS INDICATED ON PLANS.
- BONDING JUMPER FOR METAL COVERS SHALL BE 3' LONG, MINIMUM.
- THE NOMINAL DIMENSIONS OF THE OPENING IN WHICH THE COVER SETS SHALL BE THE SAME AS THE COVER DIMENSIONS EXCEPT THE LENGTH AND WIDTH DIMENSIONS SHALL BE 1/8" GREATER.
- COVERS AND BOXES SHALL BE INTERSHANGABLE WITH CALIFORNIA STANDARD MALE AND FEMALE GAGES. WHEN INTERCHANGED WITH A STANDARD MALE OR FEMALE GAGE, THE TOP SURFACES SHALL BE FLUSH WITHIN 1/8". TOP OUTSIDE EDGE OF CONCRETE COVERS AND PULL BOXES SHALL HAVE A 1/4" MINIMUM RADIUS.
- PULL BOXES SHALL NOT BE INSTALLED WITHIN THE BOUNDARIES OF NEW OR EXISTING CURB RAMPS.
- PULL BOXES FOR ELECTROLIERS, POST AND SIGNAL STANDARDS SHALL BE LOCATED +/- 5'-0" FROM THE STATION OF THE ADJACENT ELECTROLIER, POST OR SIGNAL STANDARD. PULL BOXES SHALL BE PLACED ADJACENT TO BACK OF CURB OR EDGE OF SHOULDER EXCEPT WHERE THIS IS IMPRACTICAL, A BOX MAY BE PLACED IN ANOTHER SUITABLE PROTECTED AND ACCESSIBLE LOCATION.




**B MODIFIED CALTRANS NO. 6(T) TRAFFIC RATED PULL BOX W/ EXT.**  
NOT TO SCALE


\* NOTE: GROUNDING SYSTEM ONLY REQUIRED IN ELECTRICAL PULL BOXES.




**C TYPICAL WELDING CONNECTIONS**  
NOT TO SCALE




**A** COMMUNICATION CABINET PAD DETAIL  
NOT TO SCALE



COMMUNICATIONS CABINET ELEVATION VIEWS  
NOT TO SCALE



SIDE VIEW




**B** ANCHOR BOLT DETAIL  
NOT TO SCALE

NOTES:


1. CONTRACTOR SHALL MANDREL ALL CONDUITS JUST PRIOR TO CABLE INSTALLATION.
2. CABINET PAD DIMENSIONS SHALL BE DETERMINED ON SITE SPECIFIC LOCATIONS. FINAL PAD DIMENSIONS SHALL BE 6" WIDER ON SIDES AND BACK ALL 4 SIDES OF CABINET AND 36" IN FRONT OF CABINET, IF NOT ON PLATFORM.



TYPICAL RACK MOUNTED EQUIPMENT LAYOUT



TYPICAL BACKBOARD CONFIGURATION



A TYPICAL RACK MOUNTED EQUIPMENT LAYOUT  
NOT TO SCALE



# E.5.4.2C Network Communications Device Connections

**NOTES:**

- (A) CAT6 PATCH CABLE WITH RJ-45 MALE CONNECTORS ON BOTH ENDS.
- (B) SINGLE MODE FIBER OPTIC PATCH CABLE WITH SC DUPLEX CONNECTORS ON BOTH ENDS.
- (C) TERMINATE CABLE TO BACK SIDE.
- (D) OUTDOOR RATED CAT6 (COMSCOPE 6NF4+ OR APPROVED EQUIVALENT) WITH RJ-45 MALE CONNECTORS TO DEVICE AND PUNCHED DOWN TO CAT6 PATCH PANEL.

**GENERAL NOTES:**


1. SEE PATCH CABLE SCHEDULE AND EQUIPMENT PORT DESIGNATION SHEET FOR WIRING CONFIGURATION INFORMATION REQUIRED TO CONNECT FIELD DEVICES TO NETWORK EQUIPMENT. THE TYPICAL ARRANGEMENTS SHOWN BELOW ONLY PROVIDE A CONCEPTUAL REPRESENTATION AND DO NOT REFLECT ACTUAL EQUIPMENT PORTS TO BE USED.
2. ALL EQUIPMENT SHOWN ON THIS SHEET SHALL BE NEW EXCEPT WHERE NOTED OTHERWISE.
3. ALL CABLES AND PATCH CORDS SHALL BE LABELED AT BOTH ENDS WITH FROM AND TO DEVICE DESCRIPTIONS AND TERMINATION PORTS INFORMATION.

**LEGEND:**

- X FUSION SPLICE IN SPLICE TRAY

**TYPICAL DEVICE CONNECTIONS VIA CATEGORY 6 CABLING**


(TOTAL CABLE LENGTH FROM NETWORK SWITCH TO DEVICE SHALL NOT EXCEED 330 FEET)



EXISTING/OWNER FURNISHED PASSENGER CARD INTERFACE DEVICE (PCID), TICKET VENDING MACHINE (TVM), OR VARIABLE MESSAGE SIGN (VMS)

**TYPICAL DEVICE NETWORK CONNECTION VIA SINGLE MODE FIBER OPTIC CABLE AND MEDIA CONVERTERS**


(SINGLE MODE FIBER OPTIC CABLE SHALL BE USED TO CONNECT THE DEVICE TO THE NETWORK WHEN CABLE DISTANCE BETWEEN DEVICE AND THE NETWORK SWITCH EXCEEDS 330 FEET)



**(A) NETWORK COMMUNICATIONS DEVICE CONNECTIONS**  
NOT TO SCALE




**RACK MOUNTED LAN  
ETHERNET SWITCH**




NETWORK SWITCH CARD DESIGNATIONS:  
 VARIABLE MESSAGE SIGNS (VMS) - PORTS 1 THRU 15 ODD  
 PASSENGER CARD INTERFACE DEVICES (PCIDs) - PORTS 17 THRU 31 ODD  
 TICKET VENDING MACHINES (TVMs) - PORTS 33 THRU 47 ODD  
 UNASSIGNED - 2 THRU 48 EVEN

**48 PORT RACK MOUNTED  
CAT 6 PATCH PANEL**




TYPICAL PORT DESIGNATIONS FOR CAT6 PATCH PANELS:  
 VARIABLE MESSAGE SIGNS (VMS) - PORTS 1 THRU 8  
 PASSENGER CARD INTERFACE DEVICES (PCIDs) - PORTS 9 THRU 16  
 TICKET VENDING MACHINES (TVMs) - PORTS 17 THRU 24  
 VIDEO SURVEILLANCE - PORTS 25 THRU 40  
 UNASSIGNED - 41 THRU 48

**16 BAY RACK MOUNTED MEDIA  
CONVERTER SYSTEM**



TYPICAL 16 BAY MEDIA CONVERTER DESIGNATIONS:  
 VARIABLE MESSAGE SIGNS (VMS) - CONVERTERS 1 THRU 4  
 PASSENGER CARD INTERFACE DEVICES (PCIDs) - CONVERTERS 5 THRU 8  
 TICKET VENDING MACHINES (TVMs) - CONVERTERS 9 & 10  
 VIDEO SURVEILLANCE - CONVERTERS 11 THRU 14  
 UNASSIGNED - 15 & 16

**RACK MOUNTED  
PCID, TVM, & VMS  
FIBER DISTRIBUTION UNIT**




TYPICAL PCID, TVM, & VMS FIBER DISTRIBUTION UNIT (FDUI):  
 VARIABLE MESSAGE SIGNS (VMS) - A1 THRU A6 AND B1 THRU B6  
 PASSENGER CARD INTERFACE DEVICES (PCIDs) - C1 THRU C6  
 TICKET VENDING MACHINES (TVMs) - D1 THRU D6  
 VIDEO SURVEILLANCE - E1 THRU E6  
 UNASSIGNED - F1 THRU F6

**A NETWORK EQUIPMENT PORT DESIGNATIONS**  
NOT TO SCALE




**PUBLIC ADDRESS SYSTEM-  
RACK MOUNTED INTERCOM AND PAGING SYSTEM**



NOTES:

- (A) FOUR FEET LONG SHIELDED TWISTED PAIR STRANDED 16 AWG WIRE FROM CONVERTER AUDIO OUTPUT TO RACK MOUNTED AMPLIFIER (GROUND SHIELD TO AMPLIFIER).
- (B) 12AWG STRANDED COPPER OUTDOOR RATED SPEAKER WIRE WITH TINNED OR CRIMPED SLEAVED ENDS.

LEGEND:






(A) PUBLIC ADDRESS SYSTEM CONFIGURATION  
NOT TO SCALE





# E.5.4.2F PLC Wiring Diagram


ITEM	DESCRIPTION
1	PACSYSTEMS RX3i CPU IC695CPE305
2	PACSYSTEMS RX3i IC695PSA140 MULTI-PURPOSE POWER SUPPLY
3	PACSYSTEMS RX3i ETHERNET TCP/IP 10/100MBITS IC695ETM001
4	PACSYSTEMS RX3i IC694MDL930 OUTPUT MODULE, ISOLATED RELAY, 4A, B POINT
5	PACSYSTEMS RX3i IC694MDL634 INPUT MODULE, 24 VDC, B POINT
6	PACSYSTEMS RX3i IC694ALG221 4-20 MA ANALOG INPUT, 4 CHANNEL
7	FILLER MODULE BLANK SLOT IC694ACC310 - QTY 5
8	PACSYSTEMS RX3i 12 SLOT HIGH SPEED CONTROLLER BASEPLATE IC695CHS012
9	RACK MOUNT, IC693ACC308 FRONT MOUNT ADAPTER BRACKET
10	24 VDC POWER SUPPLY, DIN RAIL MOUNT - QTY 2
11	INTERPOSING RELAY 120 VAC COIL
12	ELECTRICAL BOX
13	APC DRY CONTACT I/O ACCESSORY, PART # AP9810 (COM UPS)
14	APC DRY CONTACT I/O ACCESSORY, PART # AP9810 (CCTV UPS)
15	GE SENTROL 25074H ENCLOSURE DOOR SWITCH (ONLY IF A DOOR SWITCH HAS NOT BEEN SUPPLIED)
16	AUTOMATION DIRECT PROSENSE TTD25N 4-20 MA TEMPERATURE TRANSMITTER
17	ENERGY PACK IC695ACC400
18	ENERGY PACK CONNECTOR CABLE IC695CBL001



NOTE:  
ALL CONNECTION WIRE TO BE #14 UNLESS OTHERWISE NOTED.



# E.5.4.2G Communications Wiring Plan




### CABLE CALL-OUT LEGEND



### COMMUNICATIONS WIRING DIAGRAM


### COMMUNICATIONS WIRING ABBREVIATIONS

- SMF 12-STRAND SINGLE MODE FIBER OPTIC CABLE
- C7S TWC LOOP CONNECTOR CABLE (CONDUCTOR TWISTED SHIELDED)
- PHONE TELEPHONE CABLE
- CA1B CATEGORY 6 CABLE




**A** TYPICAL SPARE CONDUIT STUB  
NOT TO SCALE

- NOTES:  
1. SEE CIVIL PLANS FOR STATION SPECIFIC PLATFORM GRADES.  
2. PROVIDE SPARE CONDUIT STUB(S) AT THE LOCATIONS SHOWN IN THE PLANS.



**B** CONDUIT STUB-OUT DETAIL  
NOT TO SCALE

- NOTES:  
1. SEE CIVIL PLANS FOR STATION SPECIFIC PLATFORM GRADES.  
2. DETAIL APPLIES TO TICKET VENDING MACHINES, PCID'S, AND BIKE LOCKERS.



**C** PLATFORM LIGHT DETAIL  
NOT TO SCALE


## **7.5 Station Lighting Exhibits**



LIGHT FIXTURE SCHEDULE				
LABEL	MANUFACTURER	WATT	TYPE	DISTRIBUTION
A	Gardco Lighting EH14-1-3-150PSMH	150W	MH	Type III
B	Gardco Lighting EH14-1-FM-150PSMH	150W	MH	Type IV
C	Lumenpulse	32W	LED	N/A

ISOLINE LEGEND	
ISOLINE	VALUE
	5.0 fc and above
	4.99 fc to 1.01 fc
	1.0 fc and below

Calculation Summary					
Label	Units	Avg	Max	Min	Avg/Min
Guideway	Fc	4.51	10.52	0.16	28.19
N Station	Fc	5.81	9.45	0.55	10.56
S Station	Fc	5.87	9.51	1.09	5.39
Utility Area	Fc	3.32	8.30	0.04	83.00
E Ped Crossing	Fc	6.04	6.91	5.36	1.13
W Ped Crossing	Fc	7.39	7.86	6.74	1.10






Job: \_\_\_\_\_  
Type: \_\_\_\_\_  
Notes: \_\_\_\_\_

Featuring **ComaPods** and **MasterColor Elite Electronic HID Systems** **Form 10 Square**  
EH / H Arm Mount

The Philips Gardco arm mounted Square Form 10 products are cutoff luminaires for high intensity discharge lamps up to 1000 watts. The EH series are manufactured from anodized extruded aluminum and finished in an Architectural Class I anodizing. The H style luminaires are die formed aluminum with a thermoplastic finish. Both products can accept one or seven (7) interchangeable and replaceable precision engineered optical systems.

Fluor glass lens luminaires provide full cutoff performance. Sag Lens luminaires provide cutoff performance.



PREFIX	MOUNTING	DISTRIBUTION	WATTAGE	VOLTAGE	FINISH	OPTIONS
EH14	14" Square Extended Luminaire	1	Single Pole Mount	Horizontal Lamp	Type 1	SELCT Built-In Control Type 1, 2 or 3
EH18	18" Square Extended Luminaire	1	Single Pole Mount	Horizontal Lamp	Type 1	SELCT Built-In Control Type 1, 2 or 3
EH14	14" Square Recessed Luminaire	2	Two Pole Mount at 90°	Vertical Lamp	Type 1	SELCT Built-In Control Type 1, 2 or 3
EH18	18" Square Recessed Luminaire	2	Two Pole Mount at 90°	Vertical Lamp	Type 1	SELCT Built-In Control Type 1, 2 or 3
EH18	18" Square Recessed Luminaire	3	3-way Pole Mount at 90°	Vertical Lamp	Type 1	SELCT Built-In Control Type 1, 2 or 3
EH18	18" Square Recessed Luminaire	3	3-way Pole Mount at 120°	Vertical Lamp	Type 1	SELCT Built-In Control Type 1, 2 or 3

1 Not all models in the Luminaire and Type 1X versions, 400W and below, are supplied with the 3-pin. 2 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 3 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 4 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 5 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 6 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 7 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 8 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 9 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp.

WATTAGE	EH / H 14"	EH / H 18"	H 24"
100W	100W14	100W18	100W24
150W	150W14	150W18	150W24
200W	200W14	200W18	200W24
250W	250W14	250W18	250W24
300W	300W14	300W18	300W24
400W	400W14	400W18	400W24
500W	500W14	500W18	500W24
600W	600W14	600W18	600W24
700W	700W14	700W18	700W24
800W	800W14	800W18	800W24
900W	900W14	900W18	900W24
1000W	1000W14	1000W18	1000W24

1 Not all models in the Luminaire and Type 1X versions, 400W and below, are supplied with the 3-pin. 2 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 3 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 4 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 5 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 6 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 7 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 8 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 9 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp.




Featuring **ComaPods** and **MasterColor Elite Electronic HID Systems** **Form 10 Square**  
EH / H Arm Mount

Page 2 of 3

FINISH	OPTIONS
EH14, EH18 and H24	F1 Finishing in Hood
BRA Bronze Anodized	LF No Luminaires Finishing
BLA Black Anodized	AT Adjustable Knuckle - Square Pole Mount
NA Neutral Anodized	AT1 Adjustable Knuckle - Taper Mount
OC Optional Color Finish	PCB Photocatalytic Resincoated
OC Optional Color Finish	PCF Photocatalytic Resincoated
OC Optional Color Finish	PCF1 Photocatalytic Resincoated
OC Optional Color Finish	PCF2 Photocatalytic Resincoated
OC Optional Color Finish	PCF3 Photocatalytic Resincoated
OC Optional Color Finish	PCF4 Photocatalytic Resincoated
OC Optional Color Finish	PCF5 Photocatalytic Resincoated
OC Optional Color Finish	PCF6 Photocatalytic Resincoated
OC Optional Color Finish	PCF7 Photocatalytic Resincoated
OC Optional Color Finish	PCF8 Photocatalytic Resincoated
OC Optional Color Finish	PCF9 Photocatalytic Resincoated
OC Optional Color Finish	PCF10 Photocatalytic Resincoated
OC Optional Color Finish	PCF11 Photocatalytic Resincoated
OC Optional Color Finish	PCF12 Photocatalytic Resincoated
OC Optional Color Finish	PCF13 Photocatalytic Resincoated
OC Optional Color Finish	PCF14 Photocatalytic Resincoated
OC Optional Color Finish	PCF15 Photocatalytic Resincoated
OC Optional Color Finish	PCF16 Photocatalytic Resincoated
OC Optional Color Finish	PCF17 Photocatalytic Resincoated
OC Optional Color Finish	PCF18 Photocatalytic Resincoated
OC Optional Color Finish	PCF19 Photocatalytic Resincoated
OC Optional Color Finish	PCF20 Photocatalytic Resincoated
OC Optional Color Finish	PCF21 Photocatalytic Resincoated
OC Optional Color Finish	PCF22 Photocatalytic Resincoated
OC Optional Color Finish	PCF23 Photocatalytic Resincoated
OC Optional Color Finish	PCF24 Photocatalytic Resincoated
OC Optional Color Finish	PCF25 Photocatalytic Resincoated
OC Optional Color Finish	PCF26 Photocatalytic Resincoated
OC Optional Color Finish	PCF27 Photocatalytic Resincoated
OC Optional Color Finish	PCF28 Photocatalytic Resincoated
OC Optional Color Finish	PCF29 Photocatalytic Resincoated
OC Optional Color Finish	PCF30 Photocatalytic Resincoated
OC Optional Color Finish	PCF31 Photocatalytic Resincoated
OC Optional Color Finish	PCF32 Photocatalytic Resincoated
OC Optional Color Finish	PCF33 Photocatalytic Resincoated
OC Optional Color Finish	PCF34 Photocatalytic Resincoated
OC Optional Color Finish	PCF35 Photocatalytic Resincoated
OC Optional Color Finish	PCF36 Photocatalytic Resincoated
OC Optional Color Finish	PCF37 Photocatalytic Resincoated
OC Optional Color Finish	PCF38 Photocatalytic Resincoated
OC Optional Color Finish	PCF39 Photocatalytic Resincoated
OC Optional Color Finish	PCF40 Photocatalytic Resincoated
OC Optional Color Finish	PCF41 Photocatalytic Resincoated
OC Optional Color Finish	PCF42 Photocatalytic Resincoated
OC Optional Color Finish	PCF43 Photocatalytic Resincoated
OC Optional Color Finish	PCF44 Photocatalytic Resincoated
OC Optional Color Finish	PCF45 Photocatalytic Resincoated
OC Optional Color Finish	PCF46 Photocatalytic Resincoated
OC Optional Color Finish	PCF47 Photocatalytic Resincoated
OC Optional Color Finish	PCF48 Photocatalytic Resincoated
OC Optional Color Finish	PCF49 Photocatalytic Resincoated
OC Optional Color Finish	PCF50 Photocatalytic Resincoated
OC Optional Color Finish	PCF51 Photocatalytic Resincoated
OC Optional Color Finish	PCF52 Photocatalytic Resincoated
OC Optional Color Finish	PCF53 Photocatalytic Resincoated
OC Optional Color Finish	PCF54 Photocatalytic Resincoated
OC Optional Color Finish	PCF55 Photocatalytic Resincoated
OC Optional Color Finish	PCF56 Photocatalytic Resincoated
OC Optional Color Finish	PCF57 Photocatalytic Resincoated
OC Optional Color Finish	PCF58 Photocatalytic Resincoated
OC Optional Color Finish	PCF59 Photocatalytic Resincoated
OC Optional Color Finish	PCF60 Photocatalytic Resincoated
OC Optional Color Finish	PCF61 Photocatalytic Resincoated
OC Optional Color Finish	PCF62 Photocatalytic Resincoated
OC Optional Color Finish	PCF63 Photocatalytic Resincoated
OC Optional Color Finish	PCF64 Photocatalytic Resincoated
OC Optional Color Finish	PCF65 Photocatalytic Resincoated
OC Optional Color Finish	PCF66 Photocatalytic Resincoated
OC Optional Color Finish	PCF67 Photocatalytic Resincoated
OC Optional Color Finish	PCF68 Photocatalytic Resincoated
OC Optional Color Finish	PCF69 Photocatalytic Resincoated
OC Optional Color Finish	PCF70 Photocatalytic Resincoated
OC Optional Color Finish	PCF71 Photocatalytic Resincoated
OC Optional Color Finish	PCF72 Photocatalytic Resincoated
OC Optional Color Finish	PCF73 Photocatalytic Resincoated
OC Optional Color Finish	PCF74 Photocatalytic Resincoated
OC Optional Color Finish	PCF75 Photocatalytic Resincoated
OC Optional Color Finish	PCF76 Photocatalytic Resincoated
OC Optional Color Finish	PCF77 Photocatalytic Resincoated
OC Optional Color Finish	PCF78 Photocatalytic Resincoated
OC Optional Color Finish	PCF79 Photocatalytic Resincoated
OC Optional Color Finish	PCF80 Photocatalytic Resincoated
OC Optional Color Finish	PCF81 Photocatalytic Resincoated
OC Optional Color Finish	PCF82 Photocatalytic Resincoated
OC Optional Color Finish	PCF83 Photocatalytic Resincoated
OC Optional Color Finish	PCF84 Photocatalytic Resincoated
OC Optional Color Finish	PCF85 Photocatalytic Resincoated
OC Optional Color Finish	PCF86 Photocatalytic Resincoated
OC Optional Color Finish	PCF87 Photocatalytic Resincoated
OC Optional Color Finish	PCF88 Photocatalytic Resincoated
OC Optional Color Finish	PCF89 Photocatalytic Resincoated
OC Optional Color Finish	PCF90 Photocatalytic Resincoated
OC Optional Color Finish	PCF91 Photocatalytic Resincoated
OC Optional Color Finish	PCF92 Photocatalytic Resincoated
OC Optional Color Finish	PCF93 Photocatalytic Resincoated
OC Optional Color Finish	PCF94 Photocatalytic Resincoated
OC Optional Color Finish	PCF95 Photocatalytic Resincoated
OC Optional Color Finish	PCF96 Photocatalytic Resincoated
OC Optional Color Finish	PCF97 Photocatalytic Resincoated
OC Optional Color Finish	PCF98 Photocatalytic Resincoated
OC Optional Color Finish	PCF99 Photocatalytic Resincoated
OC Optional Color Finish	PCF100 Photocatalytic Resincoated

**DIMENSIONS AND EPA**



Size	Widths	B	C	D
BH14	14"	17.75"	13.14"	13.78"
BH18	18"	21.75"	16.14"	16.78"
BH24	24"	27.75"	21.14"	21.78"
H14	14"	17.75"	13.14"	13.78"
H18	18"	21.75"	16.14"	16.78"
H24	24"	27.75"	21.14"	21.78"

1 Not all models in the Luminaire and Type 1X versions, 400W and below, are supplied with the 3-pin. 2 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 3 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 4 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 5 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 6 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 7 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 8 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 9 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp.




**lumenfacade™**  
WIFI & BACnet CODES

Client: \_\_\_\_\_  
Project name: \_\_\_\_\_  
Order # \_\_\_\_\_  
Type: \_\_\_\_\_ City: \_\_\_\_\_

**FEATURES AND BENEFITS**

- Low copper content anodized aluminum housing
- Available in 12, 2, 3 or 4' sections
- Electrically supplied polymer powder coat finish
- Machined aluminum end caps and silicone gaskets
- Stainless steel hardware
- Clear tempered glass
- 10" x 10", 10" x 50", 30" x 50" or 50" x 50" optics
- IP60
- Corrosion-resistant option for marine environments



Wing detail - non-dimming	Wing detail - dimming
1 GREEN CODE / USE	1 GREEN CODE / USE
2 WHITE NEUTRAL	2 WHITE NEUTRAL
3 BLACK DIM 120VTV	3 RED DIM 120VTV
	4 ORANGE DIM 120VTV

1 Not all models in the Luminaire and Type 1X versions, 400W and below, are supplied with the 3-pin. 2 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 3 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 4 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 5 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 6 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 7 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 8 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 9 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp.




**lumenfacade™**  
WIFI & BACnet CODES

Client: \_\_\_\_\_  
Project name: \_\_\_\_\_  
Order # \_\_\_\_\_  
Type: \_\_\_\_\_ City: \_\_\_\_\_

**FEATURES AND BENEFITS**

- Low copper content anodized aluminum housing
- Available in 12, 2, 3 or 4' sections
- Electrically supplied polymer powder coat finish
- Machined aluminum end caps and silicone gaskets
- Stainless steel hardware
- Clear tempered glass
- 10" x 10", 10" x 50", 30" x 50" or 50" x 50" optics
- IP60
- Corrosion-resistant option for marine environments



Wing detail - non-dimming	Wing detail - dimming
1 GREEN CODE / USE	1 GREEN CODE / USE
2 WHITE NEUTRAL	2 WHITE NEUTRAL
3 BLACK DIM 120VTV	3 RED DIM 120VTV
	4 ORANGE DIM 120VTV

1 Not all models in the Luminaire and Type 1X versions, 400W and below, are supplied with the 3-pin. 2 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 3 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 4 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 5 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 6 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 7 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 8 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp. 9 400W/400W Type 1X and 1X versions require the 400W/400W indirect pole lamp.

