
KEY FINDINGS




CORRIDOR-WIDE ISSUES



Stressful Biking Conditions

There are inadequate bike accommodations along Imperial Avenue, which create stressful conditions for biking. Many community members requested protected bikeways.



Poor Lighting

There is not enough lighting, and the lighting that does exist is oriented toward cars. This can make it hard to see at night and causes people to feel unsafe when walking and biking.




Rough Roadway Surface

The roadway surface is rough or cracked in many locations along Imperial Avenue. It is difficult to bike on rough or cracked roadways.




Parking at Intersections

In many places, cars park very close to intersections and driveways. This makes it hard to see at intersections for people walking, biking, and driving.



Cracked/Broken Sidewalks

The sidewalks are in disrepair in many locations. This causes hazards for tripping and generally makes walking uncomfortable.



Lack of Street Trees

There is a desire for more trees and landscaping along Imperial Avenue. This could help to provide shade and creates a more pleasant environment for walking and biking.

LOCATION SPECIFIC ISSUES



Crossings

There is a desire for safer and more comfortable street crossings for people who are walking or biking. In some locations, there are no crossings for several blocks.



Cemetery Access

There is little access to the cemetery and park for people who are walking. The entrances are confusing and there is no designated way to cross the street.



Traffic Calming

Traffic calming is desired.

Cars move too fast,

creating an uncomfortable
environment for walking
and biking.



Missing Sidewalks

There are no sidewalks along most of the north side of the road in this area. There are significant gaps in the sidewalk that does exist.







